Alaska Airport Needs Directory

Department Of Transportation & Public Facilities

As of: February 23, 2021 Region: All



This report provides only a portion of the income and expense data related to rural airport operations for DOT&PF. It does not reflect funds received from FAA capital or maintenance grants, Air Carrier Compliance program, or M&O badge or ramp fees. It does not reflect expenses for FAA and State share for capital and maintenance project grants, managerial expenses by Commissioner, Deputy Commissioner, Statewide Aviation staff, or administrative costs incurred by Division of Administrative Services (Budget, Finance, IT, appeals functions), Statewide Aviation Leasing, ROW, Planning, Design and Engineering Services or Construction. It does not reflect expenses for the rural airport Facilities component building costs such as repairs, electricity and heating fuel, or other utilities for buildings. It does include Maintenance and Operations costs such as personnel, utilities and fuel for equipment, runway lights, and some buildings such as heated storage.

ALL/ALL/0800-1600

In Project

Runways: 05/23 - 7,790 Surface: ASPH-G Lighting: HIGH

Classification: Community Off-Road CY20 Enplanements: 1,256 **Borough:** Aleutians West Census Area

Air Carrier Hub: No **Medical Facility:** FY20 Revenue: \$8,785.65 USPS Hub: No School Facility: K-12 FY20 Ops Cost: \$764,181.92 08/19/2019

Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:**

Hours of Operation: Airfield Manager: Innocent Dushkin, 907-592-8026

Last Major Improvement: Rehabilitate RW 5/23 Various SPM

3-02-0200-125-2019;

Rehabilitate Marking for RW 5/23, Taxiway and

NEEDS:

SREB Repairs

	•	•
Airport Fence	Sweeper	
Coastal Launch Program Site	Taxiway A	X
Construct Passenger Shelter	Upgrade Vehicle Gates with Electronic Swipe Capal	bility

In Project NEEDS:

Construct Tie-Downs **Construct Toilet Facilities** Extend RSA on runway Fence Repairs Х Improve Drainage Χ Installation of FAA Weather Cameras Loader Х Major Pavement Rehabilitation on Main Runway Needed Х Master Plan Update New radios (9) for SRE equipment Pavement markings **Pavement Repairs** Plow with Attachments Purchase Badging Computer, Software Upgrade and Printer Χ Purchase New 1,500 gal. ARFF Truck Removal of Old Lighting on Closed Surfaces Repair Mower Repair or replace equipment Repair RW 36 Water Pump Replace ARFF Bunker Gear **RSA** Drainage improvements Skid Steer with Attachments Χ SRE Building Upgrades & Repairs

Runways: 04/22 - 3,120 Lighting: Surface: GRAVEL-G

Borough: Kodiak Island Borough Classification: Community Off-Road CY20 Enplanements: 253

FY18 Revenue: Air Carrier Hub: No **Medical Facility:** \$0.00 USPS Hub: Yes **School Facility:** FY20 Ops Cost: \$24,008.13 Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 10/10/2016

Hours of Operation: Airfield Manager: Phil Smith, 907-487-4952 **UNATNDD**

Last Major Improvement: Improve SREB 3-02-0002-002-1994

NEEDS: In	n Project	NEEDS:	In Project
Acquire 21 acres of property to control expanded airspace		Replace Cones	
Brush Cutting		Replace existing apron	
Construct 180' Runway Extension		Replace Segmented Circle	
Construct and relocate new apron to provide offsets for		Replace/Relocate new 2-bay SREB	X
non-precision approaches		Runway, taxiway, and apron rehabilitation	X
Construct New Segmented Circle and Wind Cone		SREB Cleanup	

Acquire 21 acres or property to control expanded airspace	Replace Colles
Brush Cutting	Replace existing apron
Construct 180' Runway Extension	Replace Segmented Circle
Construct and relocate new apron to provide offsets for non-precision approaches	Replace/Relocate new 2-bay SREB
Construct New Segmented Circle and Wind Cone	Runway, taxiway, and apron rehabilitation
Constituct New Segmented Circle and Wind Cone	SREB Cleanup
Construct Passenger Shelter	-
Construct supplemental wind cone	_
Construct taxiway B	_
Construct Toilet Facilities	_
Demolish existing SREB	_
Grade Runway 4/22	_
Grade safety Areas	
Improve runway to accommodate additional use	_
Install MIRL Runway Lighting X	
Install Perimeter Fence	
Install taxiway edge lighting X	
Install VGSI (PAPI)	_
Loader	_
Lower access road profile to mitigate airspace obstructions	_
Obliterate part of access road	_
Rehabilitate/Resurface Access Road	_
REIL, and navigation lighting aids	_
Relocate AWSS	-
Relocate part of access road	_
Relocate taxiway and apron	-
Remove OFA/OFZ penetrations	-

Runways: 01/19 - 3,300 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 3,308 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:K-12FY20 Ops Cost:\$24,008.13Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/26/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport 3-02-0461-002-2010

NEEDS:	In Project	NEEDS:	In Project
Airport Master Plan	Х		
Apply dust palliative			
Construct crosswind runway	_		
Construct Passenger Shelter	_		
Construct Tie-Downs			
Construct Toilet Facilities			
Dozer	X		
Dust Control			
Extend 3,300' runway to 6,000'			
Install AWOS (Various)	X		
Install Papi and Reil			
Install VGSI (PAPI)			
Install Weather Cameras			
Rehabilitate Apron			
Rehabilitate Runway			
Rehabilitate Taxiway			
Stockpile for Repairing Gravel Runway			
Stockpile for Repairing Graver Runway			

Runways: 03/21 - 3,200 **Surface:** GRVL-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 668 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:K-12FY20 Ops Cost:\$33,831.75Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/20/2014

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0004-002-2003

Building organization and cleaning
Construct new SREB
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dust Control
Grader
Install ASOS or AWOS
Install VGSI (PAPI)
Loader
MIRL Inoperable
Obstruction Removal
provide a portable emergency eye wash station
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Replace all cones and unlit markers
replace fuel tank signage and install security lighting
Runway, taxiway, and apron pavement rehabilitation
Test Akiak Need for Training
Tree obstruction removal
Update ALP
Vandalism Issues

Runways: 09/27 - 4,500 Surface: ASPH Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 808 Borough: Aleutians East Borough

Air Carrier Hub: No Medical Facility: Yes FY18 Revenue: \$0.00 USPS Hub: Yes School Facility: K-12 FY20 Ops Cost: \$682,820.73

 USPS Hub:
 Yes
 School Facility:
 K-12
 FY20 Ops Cost:
 \$682,820.73

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 09/24/2015

Airfield Manager: Steve Berninger, 907-359-1666 Hours of Operation:

ALL/ALL/0700-1900

Last Major Improvement: Construct New Airport Phase 7 3-02-0005-007-2015

NEEDS:

In Project NEEDS: In Project

Construct Tie-Downs

Construct Toilet Facilities

Install PAPI or VASI

Install VGSI (PAPI)

Runways: 16/34 - 4,000 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 803 Borough: Kusilvak Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: Yes School Facility: PK-12 FY20 Ops Cost: \$100,761.45

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport Phase 4

3-02-0440-004-2011

In Project NEEDS: In Project

Airport Signage

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Install ASOS or AWOS

Install VGSI (PAPI)

Loader

NEEDS:

ALEKNAGIK /NEW (5A8)

NPIAS: 02-0359

Runways: 15/33 - 2,030 **Surface:** GRAVEL-G **Lighting:**

Classification: Community Off-Road No Enplanements: 0 Borough: Dillingham Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: No School Facility: K-8 FY20 Ops Cost: \$4,879.18
Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 10/16/2015

Airfield Manager: Jon Taylor, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: No capital-Rehab RW 15/33 (2010)

3-02-0200-073-2010 [Various Grnt] Rehabilitate

Runway 15/33 Aleknagik Various Surface

Maintenance (RE RW IM)

NEEDS: In Project NEEDS: In Project

Aleknagik Airport Improvements

Brush Cutting

Improve Windsock Visibility

Remove Trees

Replace Primary Wind Cone and Segmented Circle

ALLAKAKET (6A8)

NPIAS: 02-0009

Runways: 05/23 - 4,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 1,543 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,726.84USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$114,558.58Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/24/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Expand Apron 3-02-0009-006-2009

In Project

Apply Dust Palliative Cleanup and Organization of Equipment, Parts, and Supplies Compactor Construct Passenger Shelter Construct Tie-Downs **Construct Toilet Facilities Construct Ultimate Apron** Dozer Erosion Repair on Ramp/Taxiway Throat FAA Survey Clear Obstructions & Mark Property Boundary Fuel Farm Upgrades Grader Install AWOS Install external speaker on equipment Install Lighted Supplemental Wind Cone Install Protective Bollards (SREB) Install RW 5/23 PAPI and REIL Install VGSI (PAPI) Realign Primary Wind Cone Relocate Segmented Circle Repair Threshold Markers Replace Fuel Storage Tank and Enhance Security Measures SRE Building Replacement **SRE Repairs** SREB upgrade or replace WX Reporting Needed

Runways: 01/19 - 4,000

10/28 - 2,400

Surface: GRVL-G

GRVL-G

Lighting: MED MED

Classification: Community Off-Road

CY18 Enplanements: 2,501

Borough:

Northwest Arctic Borough

Air Carrier Hub: No

Medical Facility:

FY20 Revenue:

\$2,163.57

USPS Hub: Yes

School Facility: PK-12

FY20 Ops Cost:

\$130,835.30

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

10/07/2015

Airfield Manager:

Alvin Werneke, 907-442-3147

Hours of Operation: UNATNDD

Last Major Improvement:

RW 9/27 & 18/36 Rehabilitation

3-02-0354-006-2016

Ambler Access Road Improvements	
Ambler Airport Improvements	
Ambler Airport Improvements Stage 2	
Ambler Airport Improvements Stage 3	X
Ambler SRE Building Replacement	
Construct 996' Runway Extension	
Construct apron	
Construct Taxiway	
Construct Tie-Downs	
Construct Toilet Facilities	
Dozer	
Grader	

Runways: NW/SE - 10,000 Surface: WATER Lighting:

Classification: Community Off-Road CY20 Enplanements: 873 Borough: Hoonah-Angoon Census Area

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$625.00

USPS Hub: Yes School Facility: K-12 FY19 Ops Cost: \$2,932.80

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Gray, 907-465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Land for Dev, Access Road

3-02-0018-001-1987

NEEDS: In Project NEEDS: In Project

Construct Land Airport

ANIAK (ANI) NPIAS: 02-0019

HIGH

Lighting:

Runways: 05W/23W - 3,000 Surface: WATER

11/29 - 6,200 ASPH-G

Classification: Regional CY20 Enplanements: 2,112 Borough: Bethel Census Area

Air Carrier Hub:YesMedical Facility:YesFY20 Revenue:\$77,412.87USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$590,555.75

 USPS Hub:
 Yes
 School Facility:
 PK-12
 FY20 Ops Cost:
 \$590,555.75

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 09/13/2017

Airfield Manager: Ricky Ciletti, 907-676-0505

16 APR-30

Last Major Improvement: Construct RW 10/28 & Rehab Apron 1 OCT-15 APR/MON-FRI/0730L-1630L

3-02-0019-011-2018

NEEDS: In	Project	NEEDS:	In Project
Abandoned Drums		Loader	
Airport ramp repairs		Move runway	
Broom Runway Towed		New sand storage building	
Building Timers		Pavement Markings	
Coastal Launch Program Site		Placards- Crowley Fuels	
Conduct erosion and drainage study		Provide erosion protection	
Construct Crosswind runway		Ramp light rehab	
Construct floatplane ramp		Reconfigure and expand apron	and develop new lease lots
Construct full parallel taxiway		Rehab/Overlay and Strengthen	Pavement RW 10/28
Construct helipad		Rehabilitate apron and taxiway	pavement (391,241 sq. ft.)
Construct partial parallel taxiway		Relocate approach lighting syste	em
Correct pavement markings on runway, taxiways, & apron		Relocate service road	
Crack Seal		Remove dike by clinic and realig	gn road
Crack sealing on runway, taxiways, & apron		Remove Junk and Hazardous M	Materials
Culvert replacement		Remove obstacles and penetrat	tions
directional plow		Remove obstructions to Part 77	surfaces, ROFA and RSAs
Erosion Protection		Remove power poles and install	I underground power lines
Extend fencing and repair gates		Remove trooper housing and FA	AA buildings
External Directional speakers for equipment		Replace Sign Panels	
Fix leaking SREB roof		Replace wind cone lights with L	ED
Fuel Tank Bollards		Safety Equipment and Fencing	
Grader		Security Enhancements	
Improve/Extend RSA Runway 10/28		Segmented Circle rehab	
Install Fencing		Snow Blower	
Install navaids (PAPIs, REILs, localizer)		Snow Plow	
Install Perimeter Fence		SREB needs door rehab to wea	therize
Light Obstructions		Stand by generator	

Runways: 17/35 - 4,000 **Surface:** GRAVEL-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 104 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,914.64USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$104,636.12Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: Erik Weingarth, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Extend & Rehab RW 17/35, Improve Access

Road, Expand Apron, Construct RSA

3-02-0021-004-2004

Aeronautical Survey
Apply Dust Palliative
clean culverts
Clear Vegetation Around Windcone
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Install Edge Light Can Markers
Install Runway PAPI and REIL, and Aeronautical Survey
Install ULSD Tank
Loader
Renovate SRE Building
Replace SRE Building
Re-Surface Runway, Apron, and Taxiway, Improve Drainage and Install New Lighting
Tree Removal
U-Blade Loader

Runways: 16/34 - 4,500 **Surface:** ASPH-G **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 285 Borough: Aleutians West Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:K-12FY20 Ops Cost:\$20,101.70Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/20/2016

Airfield Manager: Dale Ruckman, 907-581-1786

Hours of Operation:
UNATNDD

Last Major Improvement: Extend & Rehab RW 15/33, Construct Apron &

SREB 3-02-0394-005-2008

Coastal Launch Program Site
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Install REILs
Install VGSI (PAPI)
Installation of FAA Weather Cameras
Lengthen RW to 5,000'
Maintain crack seal
Maintain pavement markings (M&O SPM)
Repair and Add Pavement Markings on Airport
Sand seal taxiway and apron
Seal coat airport pavement
SREB Maintenance and Timer Installation
Visual Aid Repair

ATMAUTLUAK (4A2)

NPIAS: 02-0379

Runways: 15/33 - 3,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 2,551 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,236.40USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$39,171.17Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/08/2016

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Extend & Rehab RW 15/33, Construct SREB

3-02-0379-002-2002

Airport Lighting Repair	
Apply dust palliative	X
Atmautluak Airport Improvements	X
Construct a 1-bay Heated SREB with Floor	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Install AWOS System	
Install Weather Cameras	
Loader with Attachments	
Minor Gravel Resurfacing	
Widen RSA	

BARANOF WARM SPRINGS FLOAT AND SEAPLANE FLOAT (BNF)

NPIAS: 02-0451

Runways: E/W - 10,000 **Surface:** WATER-E **Lighting:**

Classification: Local NPIAS Lower CY19 Enplanements: 12 Borough: City and Borough of Sitka

Air Carrier Hub: No Medical Facility: No No Revenue: \$0.00
USPS Hub: No School Facility: None No Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: HARBORMASTER, (907) 473-3439

Hours of Operation:
UNATNDD

Last Major Improvement:

NEEDS: In Project NEEDS: In Project

Airport Ownership Change

Runways: 05/23 - 3,934 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 336 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No **Medical Facility:** FY20 Revenue: \$2,632.76

USPS Hub: Yes School Facility: PK-12 FY20 Ops Cost: \$58,204.06

Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:**

Hours of Operation: Airfield Manager: Scott Randby, 907-451-5127 **UNATNDD**

Last Major Improvement: Install RW Lighting

Replace Windsock Pole and Lighting

Snow Blower

block the two roads that cross the runway

Resurface runway, apron and taxiway and create berm to

3-02-0028-001-1988

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Apply Dust Palliative Survey, Clear Obstructions, and Mark Property Boundary Brush Cutter - Fecon Skidsteer Update ALP WX Reporting Needed Brush cutting Construct 66' Runway Extension Construct Passenger Shelter Construct SREB **Construct Tie-Downs** Construct Toilet Facilities Establish contingency shelter (connex shack) Extend runway and RSA Grader Grading and drainage improvements Hazmat removal Install VGSI (PAPI) Lighted Supplemental Wind Cone Loader New fuel storage tank (3000+ gal), construct fence to secure and add lighting Obtain wind data (crosswind runway needed?) **Pull Behind Compactor** Rehabilitate segmented circle Replace beacon access ladder and secure Replace cones/markers and replace nonfrangible bases on threshold panels

 Runways:
 01L/19R - 6,400
 Surface: ASPH-F
 Lighting: HIGH

 01R/19L - 4,000
 ASPH-G
 HIGH

 12/30 - 1,858
 GRVL-G
 HIGH

Classification: Regional CY20 Enplanements: 47,306 Borough: Bethel Census Area

Air Carrier Hub: Yes Medical Facility: Yes FY20 Revenue: \$507,994.97
USPS Hub: Yes School Facility: PK-12 FY20 Ops Cost: \$2,620,347.91

Part 139 Cert: Yes On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Joe Laraux, 907-543-2495

Hours of Operation:

OCT-APR/MON-FRI/0500-2200

Last Major Improvement: Reconstruct Parallel RW 01R/19L to correct OCT-APR/SAT-SUN/0700-2200

settlement due to permafrost
3-02-0029-026-2019

MAY-SEP/MON-FRI/0630-2200
MAY-SEP/SAT-SUN/0700-2200

NPIAS: 02-0029

NEEDS: In Project	NEEDS: In Project
Acquire & construct alternate access to Kasayuli Subdivision	Expand and Strengthen N Air Taxi Apron pavement for heavier aircraft (Dash 8)
Acquire 54 acres	Expand N Air Taxi Apron to the south (to Lot 1B)
acquire 722 acres	Extend RSA runway 12
Acquire land for w/in 2,000' of VORTAC and elsewhere for land use compatibility	Extend Taxiway M to Runway 1L/19R
Additional Landside Security Lighting	Fencing
Airport Gate Card Reader Installation	Grader
Airport Gate Replacement	Install MIRL east of the primary runway 18/36
ARFF SCBA compressor	Install Perimeter Fence
ARFF Truck	Install/replace security fencing around expanded northwest apron
Badging computer, software upgrade and printers	Main RW Reconstruction - Stage 1 X
Bethel Parallel Runway Repairs X	Main RW Reconstruction - Stage 2 X
Build 4000' Crosswind RW with Lighting and NAVAIDs and RSA	Master plan update
Coastal Launch Program Site	Mitigate wildlife problem in pond just south of Runway 1R threshold with suspended cable grid
Commercial apron rehab	New Pull Behind Broom
Construct 4,600' x 140' RSA	Parallel runway and other improvements stg. 6 ROW
Construct cargo apron and widen access road	Pavement Markings
Construct GA Apron and Support Area with Taxiway	Perimeter fencing repairs/replacement
Construct new air cargo apron	Purchase New 3,000 gal. ARFF Truck X
Construct Service Roads	Reconfigure vehicle parking and access road for main
Construct Tie-Downs	terminal and N Air Taxi aprons
Construct Wind Cone on East End of Runway	Relocate security fencing on southern end of RPZ for runway 02
Crack Seal	Remove Part 77 obstructions
Develop new lease lots	Reshape and compact RSA beyond each threshold for 1000'
Dozer	Road Repair
	Runway Prevantative Maintenance

BETHEL (BET) NPIAS: 02-0029

Shou	ılders Rwy 1L/19R
Sinki	ng Areas 1R/19L
Snow	v Blower
Truck	Mounted Deicing System and Storage Tank
Twy	C and Tower Road Pavement Repairs
West	Apron Rehabilitation

Runways: 02/20 - 5,190 Surface: GRVL-G Lighting: MED

Classification: Local NPIAS Lower CY20 Enplanements: 514 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$63,833.73USPS Hub:YesSchool Facility:NoneFY20 Ops Cost:\$97,867.28Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/24/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SPB 3-02-0030-004-2001

S: In Project
D

Apply Dust Palliative	Х
Bettles Lighting & Surface Repair	X
Brush Cutter	
Clear Vegetation Around Airport	
Loader Mounted Snow Blower	
Re-Grade Apron	
Regrade, shape, and compact runway	
Remove and replace threshold signs	
Repair/replace and realign marker cones	_
Replace Overhead Doors (SREB)	
Update ALP	

BIG LAKE (BGQ)

Lighting: **Runways:** 07/25 - 2,450 Surface: GRAVEL-G **MED**

Classification: Local NPIAS High No Enplanements: Borough: Matanuska-Susitna Borough

FY20 Revenue: \$56,700.56 Air Carrier Hub: No **Medical Facility:** No USPS Hub: No School Facility: K-12 FY20 Ops Cost: \$53,267.95 Part 139 Cert: No On/Off Road: On **Last CIMP Inspection Date:** 06/25/2019

Airfield Manager:

Hours of Operation: UNATNDD

NPIAS: 02-0031

Last Major Improvement: None

Harry Hensel, 907-745-2159

NEEDS:	In Project	NEEDS:	In Project
Airfield signs		Regrade Perimeter Access Road	
Approach Clearing		Rehabilitate existing tiedown apron	
Conduct Master Plan		Remove Parking Signs along Runway	
Construct 4 new least lots north of new tiedown apron		Replace Lighting System	
Construct a GA apron with gravel surface adjacent to air	rport	Replace Missing Threshold Marker	
Construct airport perimeter fence		Replace or rebuild electrical enclosure	
Construct Gate/Barricade at Hughes Homestead Road		Reserve area for future helicopter apron and future lea	ase lots
Construct new tiedown area east of existing apron		Resurface and extend lease lot access road	
Construct north-south taxilane for 7 future lease lots (Be 20 year planning horizon)	eyond	Runway and taxiway shift, runway lighting replacement rotating beacon, Electrical Enclosure Building (EEB)	nt,
Construct on-airport floatplane service road		Shift R/W to east and south	
Construct Perimeter Fence		Snow Removal Equipment Building	
Construct Snow Removal Equipment Building (SREB),			

Obstruction Removal

Install weather station

Construct Taxiway E

Construct T-hangars

Extend runway 450'

Eye Wash Station Fire Extinguishers

Grading Project

Loader

Extend lease lot access road

Extend taxiway to the east

Increase number of lease lots

New Design Survey datums

Equipment

Construct taxiways between apron and runway

BIRCH CREEK (Z91)

Runways: 16/34 - 4,000 **Surface:** GRAVEL-G **Lighting:** MED

Classification: Local NPIAS Lower CY18 Enplanements: 239 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$625.00

USPS Hub: No School Facility: None FY20 Ops Cost: \$106,510.30

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Last Major Improvement: Rehabilitate TW & RW 16/34

Replace Windsock Pole and Lighting

Resurface runway, taxiway, apron

3-02-0033-003-2003

Hours of Operation: UNATNDD

NPIAS: 02-0033

NEEDS:	In Project	NEEDS:	In Project
Brush cutter		Survey, Clear Obstructions, and Mark	Property Boundary
Compactor		Update ALP	
Construct SREB		Weather reporting system	
Contingency Shelter			
Dozer			
Dust Pallative			
expand apron			
Fence and secure fuel tank			
Grader			
Install New Lighting			
Installation of FAA Weather Cameras			
Lighted Supplemental Wind Cone			
Loader			
PAPI			
Purchase compactor attachment			
Rehab Access Road			
Rehab Apron			
Rehab Runway			
Rehab Taxiway			
Rehabilitate current SREB			
Remove hazmat and trash			
Remove old threshold panels and approach indicators			
Replace cones and damaged lights			
Replace Fuel Storage Tank and Enhance Security Mea	asures		
Danie a Windon de Ala Dala and Linkfina			

BIRCHWOOD (BCV)

Runways: 02L/20R - 4,010

Airfield Manager:

02R/20L - 1,800

Surface: ASPH-F

ASPH-GRVL-F

Lighting: MED NPIAS: 02-0034

Classification: Local NPIAS High No Enplanements: Borough: Municipality of Anchorage

Air Carrier Hub: No **Medical Facility:** No FY20 Revenue: \$273,832.14 USPS Hub: FY20 Ops Cost: School Facility: None \$147,209.04 Part 139 Cert: No On/Off Road: On **Last CIMP Inspection Date:** 06/15/2015

> **Hours of Operation:** Kayce Eliason, 907-338-1426 **UNATNDD**

Last Major Improvement: Reconstruct TW B, C, D, E, G, & Apron, Rehab

RW 02R/20L 3-02-0034-007-2018

NEEDS:	In Project	NEEDS:	In Project
Acquire property for RPZs and land use compatibility		Purchase Property for Compatable Land Use	
Add electric power to transient areas		Rehabilitate Runway	

Add paved intersection taxiway on South side of airport.

Additional East Side Lease Lot Development

Additional GA local and transient aircraft parking on ramp

Airport Pavement and Lighting Repairs

Airport Perimeter Road Improvements

Apply Dust Palliative

Brush Cutting

Change Main Runway Design Markings

Change TWY A

Coastal Launch Program Site

Construct New Connecting Taxiways (Taxiways F and I)

Construct new gravel runway 02S/20S and new ultralight runway

Crack Seal

Develop additional southeast Apron lease lots

Expand East Apron

Expand NE and SW Aprons

Expand northwest apron, rehabilitate apron and taxiway

Fix hump/bump/ruts in Tundra Tire/Ski strip

Grade and Relevel CAP Leasing Area

Master Plan Update

Minor Gravel Resurfacing

Northeast Apron Pavement Rehabilitation

Obstruction removal

Pavement Markings

Relocate security fencing on southern end of RPZ for runway

Relocate segmented circle and windsock to center of field

Remove and replace secondary wind cone

RPZ Fencing

Runway/Taxiway Pavement Rehab and RSA

Security Fence

Snow Removal Equipment Building

Widen taxiways at runway intersections

BOB BAKER MEMORIAL (IAN)

NPIAS: 02-0146

Runways: 06/24 - 3,400 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,345 Borough: Northwest Arctic Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$3,277.13USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$91,540.30Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/06/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct & Extend RW 6/24, Reconstruct

Lighting, Rehab Apron 3-02-0146-004-2018

Acquire land
Apply Dust Palliative
Brush Cutting
Coastal Launch Program Site
Construct 600' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dozer
Drainage project to prevent uphill water from saturating the runway embankment
Expand apron
Fuel Tank Upgrade
Improve aircraft parking setback
Install RCO
Kiana Airport Improvements-Stage 3 X
Lease lots
Rehabilitate surfaces
remove trees
Replace segmented circle and wind cone tower
Replace SREB
Replace the lighting system
Runway extended 600'
SREB repairs

Runways: 05/23 - 2,325 **Surface:** GRVL-DIRT-G **Lighting:**

Classification: Local NPIAS Lower CY15 Enplanements: 2 Borough: Southeast Fairbanks Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: No School Facility: None FY18 Ops Cost: \$311.17

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date: 10/05/2016

Airfield Manager: Sam Jennings, 907-883-5129

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Land for Dev, Construct TW & Extend RW

5/23

3-02-0036-001-1989

NEEDS: In Project NEEDS: In Project

Apply Dust Palliative

Boundary Airport Improvements

Brush Cutting Around Segmented Circle

Replace airport signage

Resurface runway, apron, and taxiway

BREVIG MISSION (KTS)

Runways: 05/23 - 2,110

12/30 - 2,990

Surface: GRVL-G

Lighting:

MED MED

Classification: Community Off-Road

CY20 Enplanements: 1,174

GRVL-G

Borough: Nome Census Area

\$0.00

Air Carrier Hub: No

Medical Facility:

FY18 Revenue:

USPS Hub: Yes

School Facility: PK-12

FY20 Ops Cost:

\$83,620.79

NPIAS: 02-0294

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

10/14/2020

Airfield Manager:

Darrin Otton, 907-443-2500

Hours of Operation: UNATNDD

Last Major Improvement:

Rehab RW 4/22, Construct TW, Install Lighting

3-02-0294-002-1997

Access Road Rehabilitation	
Apron Resurfacing	
Runway 12-30 & 5-23 Resurfacing	Х
Taxiway Resurfacing	

BUCKLAND (BVK)

NPIAS: 02-0399

Runways: 11/29 - 3,200 **Surface:** GRAVEL-G **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 4,694 Borough: Northwest Arctic Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$123,403.09Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/06/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0399-003-2017

	iii i ioject
Apply Dust Palliative	
Buckland Airport Improvements	X
Buckland SRE Building Replacement	
Construct 800' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Dozer	
Expand the apron	
Extend Runway 11/29 to 3,400'	
Fuel tank safety and signage	
Grader	
install additional fuel tank bollards	
PAPI	
Purchase New Fire Extinguishers and Portable Emerger Eye Wash Station	ncy
Reestablish Runway Crown and Compact Surface	
Repaint SREB exterior	
Replace Primary Wind Cone	
Resurface existing runway and taxiway	
Ultimate RPZ	
Unlighted Wind Cone	
Update ALP	
Upgrade airport lighting	

Runways: 08/26 - 2,782 Surface: GRVL-DIRT-P Lighting: MED

Classification: Community On-Road CY20 Enplanements: 12 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: Yes School Facility: FY20 Ops Cost: \$55,142.21

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Improve Access Road, Construct RW 7/25, Install

Lighting, Acquire Land 3-02-0045-001-1989

Apply Dust Palliative
Central Airport Improvements
Central SRE Building Replacement
Construct 618' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Install VGSI (PAPI)
Resurface runway, apron, and taxiway
Update ALP
Upgrade airport lighting

CHALKYITSIK (CIK)

NPIAS: 02-0046

Runways: 04/22 - 4,000 Surface: GRVL-DIRT-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 209 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$85,024.52Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:06/26/2017

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 3/21, Install Lighting

3-02-0046-003-1993

NLLDO.	in Project
Apply Dust Palliative	
Brush & Tree Clearing	
Brush Cutter	
Chalkyitsik Airport Improvements	X
Chalkyitsik SRE Building Replacement	
Compactor	
Connex Storage Unit - Fire extinguisher	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Correct drainage problems at the end of the runway	
Grader	
Install VGSI (PAPI)	
Loader	
Rehabilitate Airport Lighting System	
Relocate the apron and access road	
Remove or Improve the fuel tanks on the apron	
Replace EEB	
Replace Windsock Pole and Lighting	
Resurface Runway, Apron, & Taxiway	
Survey, Clear Obstructions, and Mark Property Bounda	ıry
Update ALP	
Upgrade / Improve SRE building	
Visual Aid Replacement	
WX Reporting Needed	

CHANDALAR LAKE (WCR)

NPIAS: 02-0047

Runways: 03/21 - 3,000 **Surface:** GRVL-DIRT-G **Lighting:**

Classification: Local NPIAS Lower CY20 Enplanements: 4 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$1,600.00

USPS Hub: No School Facility: None FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Improve Access Road, Extend RW 3/21,

Construct TW & Apron, Acquire Land for

Approaches

3-02-0047-001-1994

NEEDS: In Project NEEDS: In Project

Update ALP

CHANDALAR SHELF (5CD)

Runways: 01/19 - 2,529 **Surface:** GRAVEL-G **Lighting:**

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$826.30

USPS Hub: No School Facility: None FY20 Ops Cost: \$2,715.57

In Project NEEDS:

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0431-001-2004

NPIAS: 02-0431

In Project

ALP Update
Chandalar Camp Runway Rehabilitation
Develop lease lots
Resurface all operational surfaces
Update ALP
Upgrade signage/markings

NEEDS:

Runways: 16/34 - 3,230 **Surface:** GRAVEL-G **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 4,002 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$33,814.89

Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/08/2016

Airfield Manager: Joe Laraux, 907-543-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport

3-02-0442-002-2010

Construct 1,500' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dust Palliative & RSA Grading X
Grader
Install VGSI (PAPI)
Loader
SREB Safety Updates
Wildlife Hazards

CHENEGA BAY (C05)

NPIAS: 02-0419

Runways: 16/34 - 3,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road No Enplanements: 0 Borough: Valdez-Cordova Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:K-12FY20 Ops Cost:\$126,324.83

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 07/01/2020

Airfield Manager: Sean Montgomery, 907-262-1187

Hours of Operation:
UNATNDD

Last Major Improvement: Improve Snow Removal Equipment Building 1 bay

SREB, 3-02-0419-002-1992

Construct SREB, Rehab RW 15/33, Apron, and

Access Road, 3-02-0419-004-2004

1 Bay SREB
Brush Cutting
Building cleanup and fire extinguishers
Cone and marker repair / replacement
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dozer
Expand RSA to 150' x 3,900'
Extend runway to 3,300'
Improve GPS Approach
Install ASOS or AWOS
Install lighted wind cone at rwy 16 end
Install REILS
Install VGSI (PAPI)
Level out the Runway
Lighting Repair
Obstruction Removal
Repair Airport Signs and Replace Secondary Windsock Pole
Well
Wildlife Plan

In Project

Runways: 02/20 - 3,220 Surface: GRVL-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,589 Borough: Kusilvak Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$49,349.12Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/08/2016

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport 3-02-0468-002-2007

NEEDS: In Project NEEDS: Х Apply dust palliative Beacon Conduct Master Plan Construct 780' Runway Extension Construct Passenger Shelter **Construct Tie-Downs Construct Toilet Facilities Dust Control** Erosion study Install Perimeter Fence Install Signage Lease-lot development Х Lighting Repairs Loader Minor Gravel Resurfacing Obstacles/penetrations mitigated Χ Resurface runway, taxiways and apron **ROW Acquisition Snow Blower SREB Safety Repairs** X Update ALP

Runways: 13/31 - 2,500 **Surface:** GRVL-DIRT-G **Lighting:**

Classification: Local NPIAS Lower CY20 Enplanements: 38 Borough: Southeast Fairbanks Census Area

Air Carrier Hub:NoMedical Facility:NoFY19 Revenue:\$500.00USPS Hub:YesSchool Facility:NoneFY20 Ops Cost:\$25,295.25

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date: 10/05/2016

Airfield Manager: Sam Jennings, 907-883-5129

Hours of Operation:
UNATNDD

Last Major Improvement: Improve ARFF, Construct RW 13/31 & Apron,

Acquire Land 3-02-0053-001-1987

NEEDS: In Project NEEDS: In Project

Apply Dust Palliative

Brush Cutting

Chicken Airport Improvements

Fuel Tank Upgrade

Resurface Runway, Apron, and Taxiway

Update ALP

Runways: 02/20 - 2,600 Surface: GRAVEL-G Lighting:

Classification: Community Off-Road CY18 Enplanements: 107 Borough: Lake and Peninsula Borough

Air Carrier Hub:NoMedical Facility:YesFY19 Revenue:\$3,159.60USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$35,459.61Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/25/2019

Airfield Manager: Floyd Wilson, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Rehab TW, Extend RW 2/20

3-02-0330-001-1992

Construct 2-Bay SREB	Х
Construct 700' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Culvert replacement	
Cut brush in the RSA	
Expand SREB to include an additional bay, heat, and insulation	X
Fence Airport	
Grader and Loader	
Gravel resurfacing and dust control	
Install Concrete Pad at SREB entrance	X
Install Runway MIRL Lighting	
Install VGSI (PAPI)	
Rehabilitate existing SREB	
Replace cones and markers	
Resurface runway, taxiway, and apron with 9" of new gravel	X

CHIGNIK LAGOON (KCL)

NPIAS: 02-0056

Runways: 04/22 - 2,200 Surface: GRVL-DIRT-F Lighting:

Classification: Community Off-Road CY20 Enplanements: 20 Borough: Lake and Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$625.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$29,598.93

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 07/25/2019

Airfield Manager: Floyd Wilson, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: None

Snow removal equipment

NEEDS: In Project NEEDS: In Project

Add surface course aggregate to the runway. Currently at 3" Apply Dust Palliative Construct 1,490' Runway Extension Construct 10' of gravel access road Construct Passenger Shelter Construct SREB Construct Tie-Downs **Construct Toilet Facilities** Cut brush in the RSA Determine potential runway realignments Install fence Install MIRL Runway Lighting Install VGSI (PAPI) Mobile Fuel Remove structures in OFZ & RSA Repair and replace windsock poles and markers Replace visual aids Replace windsock, poles and markers Resurface existing gravel runway

CHIGNIK LAKE (A79)

NPIAS: 02-0331

Runways: 08/26 - 2,800 Surface: GRAVEL-P Lighting:

Classification: Community Off-Road CY18 Enplanements: 23 Borough: Lake and Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,250.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$16,203.28Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/25/2019

Airfield Manager: Floyd Wilson, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Rehab & Extend RW 8/26, Rehab TW & Apron

3-02-0331-001-1985

NEEDS:	In Project NEEDS:	In Project
NEEDS:	In Project NEEDS:	In Projec

Construct 500' Runway Extension
Construct a One-Bay Replacement SREB X
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Expand RSAs and expand apron
Grader and SRE
Identify future pad for weather reporting system
Install Fence
Install MIRL Runway Lighting
Install REILs
Install VGSI (PAPI)
Lengthen/widen runway to community class standards
Remove OFA penetrations, brush clearing
Resurface Runway & Add Dust Palliative
Resurface RWY and add Dust Palliative
RPZ land acquisition
Segmented Circle Replacement
Update ALP

Runways: 12/30 - 3,000 **Surface:** TURF-GRVL-P **Lighting:**

Classification: Local NPIAS Lower CY20 Enplanements: 57 Borough: Valdez-Cordova Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: No School Facility: None FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: John Hoffman, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

CNATINED

NEEDS: In Project NEEDS: In Project

Brushing, tree clearing and stockpiling surfacing material for future maintenance.

Chisana Airport Improvements

Improve airport for all-season operations, including runway surface repairs

Tie-down replacement

Update ALP

NPIAS: ---

Lighting: **Runways:** 02/20 - 2,060 Surface: TURF-GRVL-F

No Enplanements: Classification: Community On-Road Borough: Valdez-Cordova Census Area

FY18 Revenue: \$0.00 Air Carrier Hub: No **Medical Facility:** No USPS Hub: No \$0.00

FY18 Ops Cost:

School Facility: PK-12 Part 139 Cert: No On/Off Road: On **Last CIMP Inspection Date:**

Hours of Operation: Airfield Manager: John Hoffman, 907-822-3222 **UNATNDD**

Last Major Improvement: None

Apply Dust Palliative
Chistochina Airport Relocation
Construct a new runway, apron, taxiway, aviation support area
Construct new airport access road
Construct Passenger Shelter
Construct SREB
Construct Tie-Downs
Construct Toilet Facilities
Develop ALP
Extend Runway 1,340'
Install MIRLs
Install PAPI or VASI
MIRL Runway Lighting
PAPI or VASI
Runway Extension
Tie-down replacement

Runways: 13/31 - 2,850 **Surface:** GRVL-DIRT-G **Lighting:**

Classification: Local NPIAS Lower CY18 Enplanements: 2 Borough: Valdez-Cordova Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,855.80USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$40,604.14

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: John Hoffman, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0059-002-1999

NEEDS: In Project NEEDS: In Project

Apply Dust Palliative Chitina Airport Paving **Dust Pallative** Fuel Tank Upgrades Loader Parking lot expansion and Apron expansion Part 77 tree removal and brush cutting Place frangible mounted aircraft movement sign near beginning of Twy Place obstruction light on Maintenance shop buildings Raise 2 panels in segmented circle Rehab Access Road Rehab Apron Rehab Runway Rehab Taxiway Replace faded cones and damaged threshold cone Replace wind sock Resurface runway, taxiway, and apron SRE Building Upgrades Update ALP

CHUATHBALUK (9A3)

Runways: 09/27 - 3,401 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 313 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$52,165.18Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/14/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & New Airport

NEEDS:

3-02-0460-001-2002

In Project NEEDS: In Project

NPIAS: 02-0460

Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Dozer	
Grader	
Gravel Resurfacing	
Install ASOS or AWOS	
Rehabilitate access road	X
Rehabilitate Apron	X
Rehabilitate Runway	X
Rehabilitate Taxiway	X
Replace Runway Lighting	X
Replace Taxiway Lighting	X
Shoulder erosion	
Taxiway Repair	

Runways: 15/33 - 2,979 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community On-Road CY18 Enplanements: 277 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$500.00

USPS Hub: No School Facility: PK-12 FY20 Ops Cost: \$63,275.21

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW 14/32 & Apron, Install RW Lighting,

Improve Access Road 3-02-0407-002-1986

Circle Airport Taxiway and Apron Rehabilitation
Construct 421' Runway Extension
Construct Circle SRE Building
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Grader
Install ASOS or AWOS
Install VGSI (PAPI)
Lighted Supplemental Wind Cone
Loader
SREB Building
Survey, Clear Obstructions, and Mark Property Boundary
Update ALP

CIRCLE HOT SPRINGS (CHP)

Runways: 09/27 - 3,669 **Surface:** GRAVEL-G **Lighting:**

Classification: Local NPIAS Lower CY19 Enplanements: 1 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$1,160.00

USPS Hub: No School Facility: None FY18 Ops Cost: \$2,096.86

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:

UNATNDD

NPIAS: 02-0061

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

SRE Building Replacement

Taxiway and Apron Rehabilitation

Runways: E/W - 10,000 Surface: WATER Lighting:

Classification: Community Off-Road CY20 Enplanements: 70 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$1,569.48

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 11/14/2016

Airfield Manager: Tim Lacour, 907-755-2229

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SPB 3-02-0470-001-2006

CLARKS POINT (CLP)

NPIAS: 02-0438

Runways: 18/36 - 3,200 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 207 Borough: Dillingham Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:K-12FY20 Ops Cost:\$28,454.60Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/15/2015

Airfield Manager: Jon Taylor, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0062-003-2004

Acquire Land
Brush Cutting
Clark's Point Runway Extension
Construct access road
Construct apron and Lease lots
Construct Passenger Shelter
Construct SREB
Construct Tie-Downs
Construct Toilet Facilities
Construt Maintenance Road Access to Segmented Circle
Fueling System upgrades
Install MIRL Runway Lighting
Install VGSI (PAPI)
Minor Gravel Resurfacing
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Rehabilitate taxiway lighting
Remove obstructions
Remove part 77 obstructions
Repair/replace runway lights.
Replace cones and markers
Replace runway lighting
Reshaping embankment
Resurfacing gravel runway
Update ALP
Widen runway by 10'

Runways: 01/19 - 3,997 **Surface:** ASPH-G **Lighting:** MED

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Denali Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,403.67USPS Hub:NoSchool Facility:NoneFY20 Ops Cost:\$8,941.86

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 1/19, Construct Apron, Improve

Access Road, Install RW Lighting, Acquire Land

3-02-0420-001-1993

NEEDS: In Project NEEDS: In Project

Lighted Supplemental Wind Cone

PAPI and WX Reporting Needed

SREB building

Survey, Clear Obstructions, and Mark Property Boundary

Update ALP

COLD BAY (CDB)

NPIAS: 02-0065

Runways: 08/26 - 4,900 Surface: ASPH-G Lighting: HIGH

15/33 - 10,179 ASPH-G HIGH

Classification: Regional CY20 Enplanements: 3,495 Borough: Aleutians East Borough

Air Carrier Hub:YesMedical Facility:NoFY20 Revenue:\$87,134.56USPS Hub:YesSchool Facility:K-12FY20 Ops Cost:\$1,145,699.21Part 139 Cert:YesOn/Off Road:OffLast CIMP Inspection Date:05/29/2019

Airfield Manager: Hap Kremer, 907-532-5000 Hours of Operation:

ALL/MON - SAT/0700 - 1800

Last Major Improvement: Expand ARFF Building 3-02-0065-012-2016

NEEDS:	In Project	NEEDS:	In Project
Access to new Lease Lots		Loader	
Add 40' of crosswind runway pavement, 300' of crossw RSA	rind	Maintain Pavement Markings	
		Minivan	
Airport Fence and Gate Repairs		Minor Runway Pavement Repair	
ARFF Building Expansion		New AEB Apron and Taxiway	
ARFF Building Renovations		Obstruction Lighting	
ARFF bunker gear		Old ARFF Building Removal	
ARFF Vehicle	X	Overlay South Apron and Resurface ARFF Apron	
Badging computer, software upgrade and printer		Paint and Exterior Repairs on ARFF Building	
Brush Cutting		Paint and exterior repairs on sand storage building	
Coastal Launch Program Site			
Construct Full Parallel Taxiway		Pavement repairs	
Construct New Chemical Storage Building	X	Pavement Repairs (Runway, Taxiway, and Ramp)	
Construct Stand-by Generator Building		Provide additional SRE storage as needed	
Construct Tie-Downs		Realign and Pave St. Louis Road	
Construct Toilet Facilities		Re-Grade and Compact Safety Areas	
Crosswind Runway Reconfiguration		Relocate Segmented Circle	
Culvert replacements (roadways)		Repair Safety Area Ditches	
		Replace lighting on runway 15/33 and taxiway C	
Dump Truck		Replace World War II era culverts at Trout Creek	
Eagles Nests		Revenue Generation	
Equipment Needs		Runway 15/33 Culvert Replacement	
Expand Terminal Apron		Runway 15/33 Safety Area Expansion / MALSR Reloc	ation
Extend runway 8/26 and reconfigure CW runway	_	Runway lighting electrical repairs	
Fence Repairs			
Install necessary storm drainage, signage		 Sand seal north and south apron areas to include Runway 15 elephant ear turn around and the Runway 8/26 turn around 	
Install Perimeter Fence			
Install REIL & PAPI on Runway 8/26		Sand Storage Building Repairs	

SEF Building Renovations

Χ

NPIAS: 02-0065

Runways: 02/20 - 4,011 Surface: GRAVEL-G Lighting: MED

Classification: Local NPIAS Lower CY20 Enplanements: 738 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$25,017.26

USPS Hub: No School Facility: FY20 Ops Cost: \$227,783.98

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron, RW 1/19, TW, & RW Lighting

3-02-0425-002-2015

In Project NEEDS: In Project

Coldfoot Airport Improvements	
Coldfoot SRE Building Replacement	
Expand Apron	
Install AWOS (Various)	Х
Install new lighting and erosion protection.	
Install permanent erosion control	
Rehab Runway	
Rehab Taxiway	
Remove obstructions	
Resurface all airport operational surfaces	
Update ALP	

NEEDS:

NPIAS: ---

Runways: 13/31 - 2,200 **Surface:** GRVL-DIRT-F **Lighting:**

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Valdez-Cordova Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: No School Facility: PK-12 FY18 Ops Cost: \$1,312.91

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: John Hoffman, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

CORDOVA MUNI (CKU)

Runways: 06/24 - 1,800

09W/27W - 8,000

Surface: GRAVEL-G

WATER

Lighting:

Classification: Local NPIAS High

cal NPIAS High CY20 Enplanements:

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

No Medical Facility:

FY20 Revenue:

\$14,876.01

NPIAS: 02-0068

USPS Hub: No

redical Facility.

FY20 Ops Cost:

\$15,697.69

Part 139 Cert: No

School Facility: K-12

On/Off Road: Off

Last CIMP Inspection Date:

08/23/2016

Airfield Manager:

Robert Mattson, 907-424-3202

Hours of Operation:

UNATNDD

Last Major Improvement: None

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Blade Belly
Cordova Eyak Lake SRE Building
Develop ALP
Drainage Project
Handicap Pass Loader
Remove Unapproved Parking
Snow Plow
Truck Plow Airport
Utility Wagon

Runways: 10/28 - 3,000 Surface: TURF-F Lighting:

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Nome Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: No School Facility: None FY20 Ops Cost: \$2,455.57
Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 06/17/2015

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: Improve SREB 3-02-0413-002-1998

Apron Expansion
Brush Cutting
Dust Pallative
Grading and grass clearing on runway
Install aircraft tie-downs
Lease Lots
Replace Cones
Replace Panels
Replace Segmented Circle
Shoulder Stabilization
Update ALP
Wind Sock replacement

Runways: N/S - 10,000 Surface: WATER Lighting:

Classification: Community Off-Road CY20 Enplanements: 145 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No Medical Facility: Yes No Revenue: \$0.00
USPS Hub: Yes School Facility: K-12 No Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: JON BOLLING, (907) 263-3275

Hours of Operation:
ALL/ALL/DALGT

Last Major Improvement:

NEEDS: In Project NEEDS: In Project

Acquire additional property at Seaplane Base

Add four pull-out ramps to SP float for transient aircraft

Expand the terminal building

Improve street access and provide additional parking for SPB

Install additional bull rail on the center section of float for tying up skiffs

Install pipe bollards and guardrails to protect NE and SE corners of building and eaves around sewer pump station electrical panel, fire hydrant, and ends of the bull rail at the top of the ramp approach

New roof, gutters, downspouts and soffit screens on the building

Repair erosion damage to the bank and install new armor rock on the N side of the ramp

Repair non-skid surfaces on the float and haul out ramps

Repair or replace worn planking

Repair subgrade and repave parking lot

Replace corroded transition plates between floats

Replace Craig SPB Facilities (building, floats and access)

Replace damaged sidewalks on NW and SW corners of terminal building

Replace parking lot, ramp and float lighting with LEDs

Replace signage

Upgrade/Repair Access Ramp and Abutment

CROOKED CREEK (CJX)

NPIAS: 02-0073

Runways: 13/31 - 2,029 **Surface:** GRVL-DIRT-P **Lighting:**

Classification: Community Off-Road CY18 Enplanements: 354 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$35,437.74Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/14/2017

Airfield Manager: Ricky Ciletti, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct and Extend RW 14/32 and lighting;

Construct SREB and Service Road

3-02-0073-004-2019

NEEDS:	In Project NEEDS:	In Project
Acquire Land	Χ	

Acquire Land	Х
Add >3000 CY of surface course to runway	
Construct 1,271' Runway Extension	X
Construct a new heated 2-bay SREB	
Construct Passenger Shelter	
Construct Tie-Downs	X
Construct Toilet Facilities	
Dust Control	X
Grader	
Install MIRL Runway Lighting	X
Install REIL and AWOS	
Install VGSI (PAPI)	
Master plan update	
Obstruction Removal	X
Rehabilitate Runway	
Reshape runway crown, shoulders, and RSA, and compact	
Segmented Circle Panels	
SREB	
Terrain penetrations removal	

Runways: 08/26 - 4,780 **Surface:** GRAVEL-G **Lighting:**

Classification: Local NPIAS Lower CY20 Enplanements: 7 Borough: Northwest Arctic Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$19,791.72USPS Hub:NoSchool Facility:NoneFY18 Ops Cost:\$116.08Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/07/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 8/26, Construct TW & Apron, Remove

Obstructions

3-02-0075-002-1986

Brush Cutting
Dahl Creek Airport improvements
Dahl Creek Airport Lease Lot Development
Install fencing
Relevel or replace wind cone tower and sock
Replace cones and markers
Replace segmented circle
Survey and develop lease lots
Survey and expand apron
Update ALP

DEADHORSE (SCC)

Runways: 06/24 - 6,500 **Surface:** ASPH-G **Lighting:** HIGH

Classification: Regional CY20 Enplanements: 48,451 Borough: North Slope Borough

Air Carrier Hub:YesMedical Facility:NoFY20 Revenue:\$2,375,796.73USPS Hub:NoSchool Facility:FY20 Ops Cost:\$3,147,898.19Part 139 Cert:YesOn/Off Road:OnLast CIMP Inspection Date:09/02/2016

In Project NEEDS:

Airfield Manager: Tim Parault, 907-659-2553

ALL/ALL/0600-1730

NPIAS: 02-0339

In Project

Last Major Improvement: Security Improvements/ARFF Bay Addition

NEEDS:

3-02-0339-017-2016/3-02-0339-016-2015

	•
Access Road between Block 500 and new aprons to Dalton	Lease Lots South Along Dalton Highway
Hwy	New Heavy Apron
Access Roads for Lots in Blocks 70 and 80	New Itinerant Apron
Airport Master Plan Update	New Localizer
Airport Operations Vehicle	New Taxiways
Approach Lights	PAPI
Apron Expansion	Purchase New 1,500 gal. ARFF Truck X
Blower (7,500 ton per hour)	Renovate " Kiewitt" Building
Cat II Approach	Replace "Butler" Building
Coastal Launch Program Site	Replace "old blue shop"
Deadhorse Airport Apron Expansion X	Replace airport signage
Deadhorse Airport Improvements X	Resurface Apron and Taxiways
Deadhorse Airport Security Upgrades	· · · · · · · · · · · · · · · · · · ·
Deadhorse Apron Expansion X	Road between Blocks 200 and 700
Deadhorse Drive Extension	Road between Blocks 50 and 301
Deadhorse Fence Installation X	Road North of Block 200
Deadhorse SREB/ARFF Building Replacement	Runway 23 ILS
Drainage Improvements X	Runway 23 Localizer
Drainage Improvements - Phase II X	Runway Light Cleaning Plow
Electrical repairs and safety checks	Secure Gravel Source
	Security Upgrades
Expand existing apron to accommodate larger aircraft	SREB / ARFF Building Addition to add two double equipment
Expand Heavy Apron	bays and a sand storage bay
Fence and Gate Security Improvements	SREB/ARFF Building Replacement
Friction Measure Trailer	Towed Broom Runway Plow
Grader	Towed Broom Runway Plow (22' + width)
Handicap Pass Loader	Weather Reporting Equipment Upgrade
Lease Lots East of Dalton Hwy.	West Lake Colleen Road Lease Lots

DEADHORSE (SCC)

Wildlife Control - Phase I

Wildlife Control - Phase II

NPIAS: 02-0339

DEERING (DEE)

Runways: 03/21 - 3,320 Surface: GRVL-DIRT-G

12/30 - 2,660 GRVL-DIRT-G

Classification: Community Off-Road **CY18 Enplanements:** 1,576

Air Carrier Hub: No **Medical Facility:** \$0.00 USPS Hub: Yes School Facility: PK-12 FY20 Ops Cost:

Part 139 Cert: No On/Off Road: Off

Rehabilitate & Extend RW **Last Major Improvement:**

Airfield Manager:

3-02-0400-004-2001

Alvin Werneke, 907-442-3147

FY18 Revenue:

MED

MED

\$127,104.65

Northwest Arctic Borough

NPIAS: 02-0400

In Project

Last CIMP Inspection Date: 10/05/2015

Hours of Operation: UNATNDD

Lighting:

Borough:

NEEDS:	In Project	NEEDS:
Building repairs		
Construct 680' Runway Extension		
Construct Passenger Shelter		
Construct Tie-Downs		
Construct Toilet Facilities		
Deering Airport and Access Road Improvements	Х	
Deering Airport Snow Fence	X	
Deering Snow Fence	X	
Dozer	_	
Dust Palliative		
Expand RSA		
Extend apron		
Extend ROFA	_	
Extend ROFZ		
Extend runway 680'	_	
Grader		
Install Culvert		
Relocate Electrical Equipment Enclosure		
Relocate Lighted Wind Cone and Segmented Circle		
Relocate rotating beacon		
Relocate Terminal Bldg		
Repaint building exterior		
Replace overhead door		
Replace Segmented Circle		
Snow Fence	Х	

DILLINGHAM (DLG)

Runways: 01/19 - 6,400 Surface: ASPH-G Lighting: HIGH

Classification: Regional CY20 Enplanements: 9,430 Borough: Dillingham Census Area

Air Carrier Hub:YesMedical Facility:YesFY20 Revenue:\$172,260.44USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$1,164,061.80Part 139 Cert:YesOn/Off Road:OffLast CIMP Inspection Date:10/29/2020

Hours of Operation:

ALL/ALL/0800-1830

NPIAS: 02-0078

Airfield Manager: Jon Taylor, 907-842-5511

Last Major Improvement: Rehabilitate RW 1/19 3-02-0078-016-2017

3-02-0078-016-2017 Access Control Project 3-02-0078-018-2018

 NEEDS:
 In Project
 NEEDS:
 In Project

 Acquire Land
 Door jamb/roof repairs

Acquire Land	Door jamb/roof repairs
Additional tie-downs	Expand main terminal apron, vehicle parking area, and RSA
Airport fence and gate repairs	Expand Water/Sewer to all Airport Properties
Apron and Taxiway Pavement Rehabilitation	Extend ROFA
ARFF bunker gear	Fence Relocation
ARFF SCBA compressor	Follow up Fuel Inspection
Badging computer, software upgrade and printers	Improve W. Airport Road
Build Heliport	install emergency eye wash station
Close existing access road	Install MALSR
Coastal Launch Program Site	Install runway lighting
Construct 2000' Crosswind Runway and RSA	Install taxiway lighting
Construct an FAA-compliant RSA	Main Apron Redesign for Better Drainage
Construct FSS	Maintain Pavement Markings
Construct Full Parallel Taxiway	Master Plan Update
Construct RSA embankment	Minor Pavement Repairs
Construct runway	Overhead door needs replaced
Construct taxiway	Pave vehicle parking area
Construct Toilet Facilities	Pave/rehabilitate GA apron and taxiway
Crack Seal	Pavement Markings
Deicer Truck	Perimeter fencing repairs/replacement
Deicing Truck	Realign Wood River Road
Dillingham Airport Equipment	Reconstruct and Pave Public Parking Area
Dillingham Airport Improvement Stage 1 - RSA Expansion	Relocate VASI or install PAPI
Dillingham Airport Improvements Stage 2 - FAA Navigation Equipment	Relocate wind cone
Dillingham Airport Improvements Stage 3	Remove buildings
Dillingham SPB Master Plan	Remove Kanakanak and W. Airport Roads
- Imagination b master right	Remove trees

Remove Trees in Approach Surfaces	
Repair/repaint exterior panels	
Replace Airport Lighting System	
Shift runway away from cemetery	
Snow Blower	
South Apron Expansion	
SUV	
Update Airport Master Plan	X
Update DLG Surveys and Light Obstructions	

Vehicle gates with electronic swipe capability

Runways: H1 - 64 Surface: CONC-G Lighting:

Classification: Community Off-Road No Enplanements: 0 Borough: Nome Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: No School Facility: PK-12 FY20 Ops Cost: \$46,273.37

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: Construct Apron, Acquire Land for Development

3-02-0381-001-1993

NEEDS: In Project NEEDS: In Project

Coastal Launch Program Site

Diomede Temporary SRE Building

Diomede Weather Reporting

Dozer

Little Diomede Helipad Improvements

Little Diomede SRE Building Construction

Repair ice scour damage to helipad embankment and replace $\,^{\,\mathrm{X}}\,$ riprap

Replace Diomede lighting and wind cone.

Runways: 07/25 - 3,600 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 228 Borough: Southeast Fairbanks Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$11,212.39USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$56,245.71Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/31/2017

Airfield Manager: Sam Jennings, 907-883-5129

Hours of Operation:
UNATNDD

Last Major Improvement: Construct TW & Apron, Install RW Lighting,

Improve Access Road, Extend RW 6/24

3-02-0083-001-1984

Access road drainage improvements	X
Brush Cutting	
Construct New EEB	X
Construct Passenger Shelter	
Construct Tie-Downs	
Eagle Airport Improvements	X
Improve sub-grade and drainage	
Install New Lighting	X
Rehab Apron	
Rehab Runway	
Rehab Taxiway	
Resurface runway and taxiway	
Update ALP	_

EDWARD G PITKA SR (GAL)

2,863

Runways: 06/24 - 2,600

08/26 - 6,000

Surface: GRAVEL-G

ASPH-CONC-F

Lighting: HIGH

Classification: Regional

CY20 Enplanements:

Yukon-Koyukuk Census Area

Air Carrier Hub: Yes

Medical Facility:

FY20 Revenue:

\$55,530.57

NPIAS: 02-0102

USPS Hub: No

On/Off Road: Off

Borough:

\$689,224.83

Part 139 Cert: No

School Facility: PK - 12

FY20 Ops Cost: **Last CIMP Inspection Date:**

07/23/2014

Airfield Manager:

Scott Randby, 907-451-5127

Hours of Operation:

OCT-APR/MON-FRI/0600-1700

Last Major Improvement:

Rehab Apron, Install NAVAID & Segmented Circle,

Remove Obst. 3-02-0102-007-2017

Airfield lighting and signage repairs
Brush Cutter
Compactor
Construct 7,249' Full Parallel Taxiway
Construct Passenger Shelter
Construct Tie-Downs
Deicer Truck
Fueling equipment repairs
Loader
Paint Truck
Painting
PAPI Needed
Repaving
Replace Segmented Circle and Primary Wind Cone
Runway Undulation Repairs
Sand Storage
security/wildlife fencing
Towed Broom 22' or wider
Undulation Repair

EEK (EEK) NPIAS: 02-0085

Runways: 18/36 - 3,242 Surface: GRVL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,057 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$32,372.04Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/11/2016

Airfield Manager: Joe Laraux, 907-543-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & New Airport

3-02-0085-003-2002

NEEDO.	ii Fiojeci
Apply Dust Palliative	Х
Beacon	X
Brush Cutting Around Segmented Circle	X
Construct 100,000 sq ft Apron and Aviation Support Area	
Construct a 2,150' x 12' airport access road	
Construct a 2,400' x 60' gravel crosswind runway w/ RSA	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Grader	
Grader and loader	
Install MIRL and airport lighting	
Loader	
Primary Windsock & Rotating Beacon Repair	X
Purchase 225 acres of land	
Rehabilitate apron	X
Rehabilitate runway	X
Rehabilitate runway lighting	X
Rehabilitate taxiway	X
Rehabilitate taxiway lighting	X
Repair dips on southern end of runway	X
Resurface airport access road	X
SREB Repairs	
Update airport geometry to ADG II	X
VWOS Site Location	
Wildlife Mitigation	

Runways: NW/SE - 10,000 Surface: WATER-E Lighting:

Classification: Local NPIAS Lower CY20 Enplanements: 175 Borough: Hoonah-Angoon Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub:YesSchool Facility:NoneFY18 Ops Cost:\$0.00Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/01/2016

Airfield Manager: Scott Gray, 907-465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Install Electric Power to Dock

Remove Cleats

Weather Reporting Improvements

ELIM (ELI) NPIAS: 02-0090

Runways: 01/19 - 3,401 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 1,082 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$148,449.42Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 1/19

3-02-0090-005-2008

In Project

20:1 Clearance	
Apply Dust Palliative	
Construct 599' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Dozer	
Dust Palliative	
Embankment stabilization	
Erosion repairs	
Fuel Tank repairs	
Install Runway PAPIs and REILs, and Aeronautical Survey	
Install VGSI (PAPI)	
Loader	
Purchase a Portable Emergency Eye Wash Station	
Realign Access Road	
Rehab SREB	
Relocate beacon off of building	
Repair/Renovate SRE Building	
Replace Segmented Circle	
Replace SRE Building	
Resurface Runway, Apron, and Taxiway, Improve Drainage and Install New Lighting	
Upgrade Existing SREB	X

EMMONAK (ENM)

NPIAS: 02-0397

Runways: 16/34 - 4,601 **Surface:** GRAVEL-G **Lighting:** MED

Classification: Regional CY18 Enplanements: 9,117 Borough: Kusilvak Census Area

Air Carrier Hub:YesMedical Facility:NoFY20 Revenue:\$11,146.63USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$168,889.39Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0397-005-2016

Acquire Land
Aeronautical Survey and Install ILS
Apply Dust Palliative
Brush Cutting
Construct 399' Runway Extension
Construct Full Parallel Taxiway
Construct Passenger Shelter
Construct SREB
Construct Tie-Downs
Construct Toilet Facilities
Culvert Replacement
Dozer
Extend Runway and Improve RSA
Install new lighting
Loader
Relocate Beacon
Repair Segmented Circle
Replace Culvert
Replace Secondary Wind Cone
Runway Rehabilitation, Ultimate
U-Blade Loader
Update ALP

EXCURSION INLET (EXI)

Runways: NW/SE - 1,000 Surface: WATER Lighting:

Classification: Local NPIAS Lower CY20 Enplanements: 65 Borough: Haines Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00 USPS Hub: No School Facility: None FY19 Ops Cost: \$5,858.16 Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 06/06/2017

Airfield Manager: Scott Gray, 907-465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: None

ONATIOD

NPIAS: 02-0095

NEEDS: In Project NEEDS: In Project

Float Maintenance

Replace seaplane float

FALSE PASS (KFP)

NPIAS: 02-0097

Runways: 14/32 - 2,150 **Surface:** GRVL-DIRT-G **Lighting:**

Classification: Community Off-Road CY20 Enplanements: 101 Borough: Aleutians East Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,970.00USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$20,929.46Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:06/16/2016

Airfield Manager: Hap Kremer, 907-532-5000

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, Acquire Land, Improve SREB &

Access Road, Rehabilitate RW 13/31

3-02-0097-001-1988

Clear Vegetation Around Airport	
Construct New SRE Building	X
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Existing SREB Lighting Update	
Install lighted windsock	
Loader	
Paint New Threshold Markers	
Relocate Apron; Construct Lease Lots on Apron; Resurface Runway and Reconstruct Taxiway; Place Riprap Along the Roundtop Creek Bank; Raise Runway Profile	
Repair Current SRE Building	X
Repair Windsock	
Resurface RSA and grade to drain	
Resurface Runway and add dust palliative	

FLAT (FLT) NPIAS: 02-0099

Runways: 08/26 - 4,045 **Surface:** TURF-GRVL-P **Lighting:**

Classification: Local NPIAS Lower CY20 Enplanements: 0 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: No School Facility: None FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 09/20/2017

In Project NEEDS:

Airfield Manager: Steffen Strick, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

In Project

Brush Cutting
grading
Repair Windsock
wind sock /cones and markers

FORT YUKON (FYU)

NPIAS: 02-0100

Runways: 04/22 - 5,000 Surface: GRVL-DIRT-G Lighting: MED

Classification: Regional CY20 Enplanements: 2,068 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$23,650.95USPS Hub:YesSchool Facility:PK-12FY20 Ops Cost:\$96,441.80

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & Rehab Apron

3-02-0100-004--2009

NEEDS: In Project NEEDS: In Project

Airport Operations Vehicle Blower (7,500 ton per hour) Brush cutting Construct 5,000' Full Parallel Taxiway Construct Tie-Downs **Construct Toilet Facilities** Create material stockpile **Dust Pallative Erosion Control** Grader Lighted Supplemental Wind Cone Loader Place signage and/or post/rocks on road that crosses runway Re-plumb fuel tanks Resurface runway, taxiway and apron Runway Light Cleaner Survey, Clear Obstructions, and Mark Property Boundary Towed Broom (22'+ width)

Runways: NE/SW - 10,500 Surface: WATER-E Lighting:

Classification: Local NPIAS Lower CY20 Enplanements: 3 Borough: Hoonah-Angoon Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

 USPS Hub:
 No
 School Facility:
 None
 FY20 Ops Cost:
 \$3,800.00

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 09/01/2016

Airfield Manager: Scott Gray, 907-465-4512

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project In Project In Project In Project In Project Install Wind Cone

Mark Seaplane Threshold and Runway Edges

Replace seaplane float

Maintain Dock

Replace Slip Proof Grates

Runways: 14/32 - 5,182 Surface: GRAVEL-G Lighting: MED

Classification: Local NPIAS Lower CY20 Enplanements: 31 Borough: North Slope Borough

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$5,883.64

USPS Hub: No School Facility: None FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: None

Runways: 16/34 - 4,500 Surface: ASPH-CONC-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,320 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$950.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$130,602.89

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: Reconstruct RW 16/34 Lighting, Rehab RW 16/34,

TW & Apron

3-02-0103-004-2017

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Building Improvements
Coastal Launch Program Site
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dozer
Fix runway cracks
Gambell Airport Pavement Rehab and Lighting
Gambell SREB X
Grader and Loader
Improve GPS Approach
Improve Runway Safety Areas
Pavement Markings
Repave and Expand Apron
Resurface runway and taxiway
Update ALP

GIRDWOOD (AQY)

NPIAS: 02-0104

Runways: 02/20 - 2,095 **Surface:** GRAVEL-G **Lighting:**

Classification: Local NPIAS Lower CY18 Enplanements: 257 Borough: Municipality of Anchorage

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$31,936.83USPS Hub:NoSchool Facility:KG - 8FY20 Ops Cost:\$11,717.68Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:09/22/2020

Airfield Manager: Paul Bertholl, 907-783-2232 Hours of Operation: 907-783-2232

Last Major Improvement: Rehabilitate RW 1/19 & Install Perimeter Fencing

3-02-0104-002-2002

S: In Project
D

Coastal Launch Program Site
Construct apron for transient parking
Construct erosion protection
Construct new airport access road
Construct New Lease Lots and M&O Reserve
Construct SREB
Construct T-hangars
Dust Control
Erosion Protection
Expand Apron
Extend Parallel Taxiway
Extend perimeter fencing
Extend RSA, ROFA, and OFZ
Install runway edge markers
Known wildlife hazards on airport
Lower power/telephone lines
Obstruction Removal
Pave access road
Rehabilitate Access Road
Rehabilitate Runway
Rehabilitate Runway Lighting
Rehabilitate Taxiway
Rehabilitate Taxiway Lighting
Remove Part 77 obstructions (trees)
Repair Threshold Markers
Replace signage, with a frangible base
Update ALP

NPIAS: ---

Runways: 09/27 - 2,558 **Surface:** GRVL-DIRT-F **Lighting:**

Classification: Local Non-NPIAS CY19 Enplanements: 2 Borough: Denali Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: No School Facility: FY18 Ops Cost: \$101.17

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: None

Runways: 03/21 - 4,000 Surface: GRAVEL-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,016 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: Yes **School Facility:** PK - 12 **FY20 Ops Cost:** \$78,892.93

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: Rehabilitate RW 16/34 & Lighting, Construct TW &

Apron

3-02-0106-004-2016

NEEDS: In Project NEEDS: In Project NEEDS:	oject
--	-------

Building Improvements
Construct Cross wind runway
Construct Passenger Shelter
Construct taxiway, apron and access road
Construct Tie-Downs
Construct Toilet Facilities
Expand RPZ
Golovin Airport Runway and Apron Improvements
Grader
Install aircraft tie-downs
Install VGSI (PAPI)
Replace the existing airport lighting
Resurface and rehabilitate the runway
Ultimate Approach to Runway 20
Update ALP

GOODNEWS (GNU)

NPIAS: 02-0107

Runways: 06/24 - 3,300 **Surface:** GRAVEL-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 234 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$21,887.32Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/25/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW

5/23 3-02-0107-002-2009

Apply Dust Palliative	Х
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Determine Need for Wildlife Hazard Program	
Install perimeter fencing	X
Install VGSI (PAPI)	
Land Acquisition	
Misc.	
Rehabilitate apron	X
Rehabilitate runway	X
Rehabilitate runway lighting	X
Rehabilitate taxiway	X
Remove obstructions	X
Replace taxiway lighting	X
Runway Lighting Change	

Runways: 08/26 - 3,000 Surface: GRAVEL-F Lighting:

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Matanuska-Susitna Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: No School Facility: None FY20 Ops Cost: \$9.101.71

USPS Hub:NoSchool Facility:NoneFY20 Ops Cost:\$9,101.71Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:10/28/2020

Airfield Manager: Harry Hensel, 907-745-2159

Hours of Operation:
UNATNDD

Last Major Improvement: Install RW Lighting, Improve SREB & Access

Road 3-02-0409-002-1987

In Project NEEDS: In Project

Rehabilitate runway
Brush Cutting
Construct Perimeter Fence
Equipment
Minor Gravel Resurfacing
Rehab Threshold Markings
Rehabilitate apron
Rehabilitate taxiway
Remove obstructions
SREB Renovation

NEEDS:

GRAYLING (KGX)

NPIAS: 02-0109

Runways: 17/35 - 4,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 142 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$85,027.20

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 09/29/2014

Airfield Manager: Erik Weingarth, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW and Apron

3-02-0109-005-2008

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Apply Dust Palliative
Clear Vegetation Around Airport
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Erosion repairs
Erosion stabilization
Grader and Dozer
Install AWOS
Install Runway PAPI, REIL, Aeronautical Survey
Install VGSI (PAPI)
Rehab Apron
Rehab Runway
Rehab Taxiway
Repair Airfield Lighting and Markers
Repair Runway Threshold Markers
Repair SRE Building
Replace fuel tank
Replace SRE Building
Update ALP

GULKANA (GKN)

Runways: 15L/33R - 5,001

15R/33L - 2,300

Surface: ASPH-G

GRVL-G

Lighting: MED

Classification: Community On-Road

CY20 Enplanements: 104 **Borough:** Valdez-Cordova Census Area

Air Carrier Hub: Yes

Medical Facility:

FY20 Revenue: \$25,068.61

NPIAS: 02-0110

USPS Hub: Yes

School Facility: PK - 12

FY20 Ops Cost: \$132,312.51

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

Airfield Manager:

John Hoffman, 907-822-3222

Hours of Operation:

Last Major Improvement:

Rehabilitate Apron, TW &RW Remarking

3-02-0110-005-2015

JUN-SEP/MON-FRI/0900-1700 OCT-MAY/MON-FRI/1000-1500

NEEDS:	n Project NEEDS:	In Project
Apply Dust Palliative	Repair and rehab apron	
Complete Aeronautical Survey/Remove Part 77 obstruction	nns Replace sign panels	
Construct New Apron	Replace Twy A cones with blue banded cones	
Construct Passenger Shelter	Resurface airport access road and parking area resurfacing	
Construct Runway 33L/15R	Resurface medevac apron and taxiway	
Construct Security Fence for Fuel Tanks	Segmented Circle Rehab	
Construct Tie-Downs	Snow Blower	
Construct Toilet Facilities		

Decrease Vertical Runway Grade Grader

Gulkana Airport Apron and Taxiway Repaving

Increase RSA Runway 33R/15L

Install Airport Markings/Signage

Install floodlighting in ramp area

Loader

Place cones on Twy C

Place gate across road

Preventative Maintenance on 504,500 sq. ft. runway pavement and 168,160 sq. ft. apron/taxiway pavement

Ramp sign removal

Reconstruct apron and taxiway pavement

Reconstruct Runway, Apron & Taxiway Pavement 229,280

sq.ft.

Rehab Runway, Apron and Txy

Rehabilitate SREB building

Relocate FAA facility currently inside OFA

Relocate secondary windsock and/or add an additional

Remove obstacles

GUSTAVUS (GST)

2,214

Runways: 02/20 - 3,010

11/29 - 6,720

Surface: ASPH-G

ASPH-G

Lighting: MED

Classification: Regional

CY20 Enplanements:

Medical Facility:

FY20 Revenue:

Borough:

Hoonah-Angoon Census Area

Air Carrier Hub: Yes

\$72,809.79

NPIAS: 02-0111

USPS Hub: Yes

School Facility: K - 12

FY20 Ops Cost:

\$193,678.85

Part 139 Cert: Yes

On/Off Road: Off

Last CIMP Inspection Date:

11/12/2015

Airfield Manager:

Last Major Improvement:

Jeffrey Jarvis, 907-697-2251

Improve RSA 11/29

3-02-0111-005-2011

Hours of Operation:

1 SEP-1 JUN/ALL/0600-1430 1 JUN-1SEP/FRI-MON/1000-1830

1 JUN-1 SEP/TUE-THU/0600-1830

NEEDS:	In Project NEEDS:	In Project

Construct 6,721' Full Parallel Taxiway	Χ
Construct Future Apron	
Construct New SRE/ARFF Building	X
Construct Sand and Chemical Building	X
Construct Tie-Downs	
Construct Ultimate 50' wide Taxiway	
FY'15 Aeronautical survey in conjunction with pavement project design	
Master Plan Update	X
Mow Grass on Airport	
Obstruction Survey	
Rehab Runway 11/29, Apron and Taxiways	
Remove and Repaint Both Runways	
Replace or service fire extinguishers and eye wash stations	
Replace overhead doors	
Resurface asphalt aprons	
WHA/WHMP Update	

Runways: 08/26 - 4,000 Surface: ASPH-G Lighting: MED

Classification: Community On-Road CY20 Enplanements: 2,965 Borough: Haines Borough

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$30,308.09USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$34,007.50Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:11/23/2020

Airfield Manager: Matt Boron, 907-766-2340

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron, TW & Install Perimeter

Fencing

3-02-0112-006-2017

Airport Fence	
Brush Cutting in Runway 8/26 Safety Area	
Construct Hard Stands	
Construct Sand and Chemical Building	Х
Crack Sealing / Banding	
Drainage	Х
Haines Sand, Chemical & SRE Bld Const	Х
Heli Pad Rehab	
Lighting	Х
Master Plan Update	
New ALP with a Narrative	Х
Repaint Markings	
Runway Rehabilitation	Х
Taxiway Rehabilitation	Х
Update ALP	
WHA/WHMP Update	

HEALY RIVER (HRR)

NPIAS: 02-0414

Runways: 15/33 - 2,910 Surface: ASPH-G Lighting: MED

Classification: Community On-Road CY18 Enplanements: 105 Borough: Denali Borough

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$24,283.06

USPS Hub: No School Facility: PK - 12 FY20 Ops Cost: \$4,592.98

Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:09/15/2016

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 15/33 & TW, Expand Apron

3-02-0414-002-1995

Airport Lighting replacement
Construct 488' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Healy River Airport Land Lease Extension
Healy River Airport Lighting Replacement
Healy River Airport Resurfacing X
Healy River Tree Removal
Install Perimeter Fence
Install VGSI (PAPI)
Replace Wind Cones
Resurface all operational surfaces
Update ALP
VWOS Site Location

HOLY CROSS (HCA)

NPIAS: 02-0120

Runways: 01/19 - 4,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 1,439 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$127,586.77Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/02/2014

Airfield Manager: Erik Weingarth, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0120-003-2001

2 Loaders
Aeronautical Survey
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dust Palliative
Install VGSI (PAPI)
Raise Runway Grade, Clear Obstructions, Resurface All Operational Surfaces and Install New Airport Lighting
Relocated and Replace Segmented Circle and Wind Cone
Repair Runway Visual Aids
Replace SRE Building
Resurface Runway
Update ALP

Lighting:

Runways: 04/22 - 6,701

06W/24W - 2,501

Surface: ASPH-F

WATER

HIGH

Classification: Regional CY20 Enplanements: 7,220 Borough: Kenai Peninsula Borough

Air Carrier Hub:YesMedical Facility:YesFY20 Revenue:\$271,119.20USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$931,036.00Part 139 Cert:YesOn/Off Road:OnLast CIMP Inspection Date:06/25/2015

Airfield Manager: Kevin Jones, 907-235-5217

Last Major Improvement: Improve RSA 4/22, Rehab TW-C

3-02-0122-016-2018

NOV-MAR/ALL/0400-2030 APR-OCT/ALL/0600-2030

NEEDS: In Project	: NEEDS: In P	roject
2 Snow Plows - 1 with attachments	Expand east terminal apron and access road	
Acquire lease lots, SREB lot	Expand RPZ	
Acquire Lot 2, Block 400 lease lot	Expand west terminal apron	
Address Part 139 issues on runway 04/22 by filling, regrading, and leveling the RSA	Extend taxiways, south apron, and GA apron toward Lampert Lake	t
Apply dust palliative on GA and Beacon areas	External Speakers for all equipment	
ARFF bunker gear	Homer Chemical Storage Building	X
Brush Cutting	Homer RSA Regrading	
Brush Cutting Equipment	Install PAPI lighting system	
Build a new multi-bay ARFF building	Install pavement markings	
Chemical and deicing material storage facility	Install Rotating Beacon/Floating Transient Floatplane Dock a	t
Coastal Launch Program Site	Beluga Lake	
Cold Storage Building repairs	Maintain pavement markings (M&O SPM)	
Construct 30-space vehicle parking lot	Master Plan Update	
Construct 5-Bay SREB	New ARFF Vehicle	
Construct 6,701' Full Parallel Taxiway	New taxilane and access road to GA lease lots	
Construct access road to the dock	Obstruction Removal	
Construct Boat House Building	Parallel Taxiways and South Apron Extension	
Construct Chemical and Deicing Material Storage Building	Pavement Markings	
Construct new access road to the GA apron	Pavement Rehab and Resurface - Stage 1	X
Construct New Regulator Building	Pavement Rehab and Resurface - Stage 2	X
Construct Tie-Downs	Perimeter fencing repairs/replacement	
Crack Seal	Rebuild GA Tiedowns	
Deicer Truck	Rehab Approach Lighting and Taxiway Edge Lighting	
Demo existing SREB and construct new 5-bay facility w/ FSS	Rehabilitate Pavement on GA Apron & TW A & B	X
	Rehabilitate runway, taxiway, and apron	X
Develop Heliport off Taxiway E and access road	Remove berm from Elephant Ear to RWY 22 approach.	
Drainage Maintenance & Repair	Remove Elephant Ear apron (M&O SPM)	

HOMER (HOM)

NPIAS: 02-0122

Remove trees between elephant ear and Lampert Lake (M&O OR)

Replace snow removal equipment

Replace taxiway signs

Replace/relocate rotating beacon

Runway, NAVAIDS, Lights, and Fencing relocation to east

Safety Areas and Drainage improvements

Sand Storage Building Lighting timer

Secure and Monitor Vehicle Parking

SUV, grader

Tree removals east of runway

Vehicle gates with electronic swipe capability

X

Visual Aids

HOMER-BELUGA LAKE (5BL)

NPIAS: - - -

Runways: NE/SW - 3,000 Surface: WATER Lighting:

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:YesFY18 Revenue:\$0.00

USPS Hub: No School Facility: PK - 12 FY20 Ops Cost: \$358.32

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Kevin Jones, 907-235-5217

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Construct a rescue boat house and lake side floats

Construct access road

Construct Access Road and Ramp

Construct floating dock

Construct floatplane slips

Construct ramp access and turnaround

Control Waterfowl on Lake

Float Plane Base Improvements

Fueling Facility

Homer Beluga Lake Float Plane Base Planning Study

New rotating beacon

Rescue Boat

Water lane acquisition

Runways: 06/24 - 3,367 Surface: ASPH-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 2,969 Borough: Hoonah-Angoon Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$10,282.57USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$87,250.71

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Ken Meserve, 907-945-3426

Last Major Improvement: Extend RW 6/24 & Expand Apron

3-02-0125-005-2012

Hours of Operation:

UNATNDD

NEEDS: In	n Project NEEDS:	In Project
-----------	------------------	------------

Apron Improvements and Lease Lot Access
Coastal Launch Program Site
Construct Tie-Downs
Construct Toilet Facilities
Crack Seal Runway 6/24
FY'18 Apron/TWY Rehab
FY'19 Obstruction Removal
Improve Airport Utilities
Install Perimeter Fence
Obstruction Survey
Pavement Markings RW 6/24
Property Acquisition
Replace Beacon tower with a tip down style for safer access for maintenance.
Sand and Chemical Storage Shed
Sweeper

Runways: E/W - 9,000 Surface: WATER Lighting:

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Hoonah-Angoon Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

 USPS Hub:
 Yes
 School Facility:
 PK - 12
 FY19 Ops Cost:
 \$6,462.83

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 09/01/2016

Airfield Manager: Ken Meserve, 907-945-3426

Hours of Operation:
UNATNDD

Last Major Improvement: None

Chart and Light Zip Line Obstruction	
Haul Out Ramp	
Maintain Dock	
OOH Hydraulic Engineering	X
Seaplane Base Improvements	
Threshold and RW Edge Marking	
Tiedown Cleats	

HOOPER BAY (HPB)

NPIAS: 02-0126

Runways: 13/31 - 3,300 Surface: GRVL-DIRT-P Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,621 Borough: Kusilvak Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$568.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$61,126.26Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/04/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, Rehab Access Road

3-02-0126-008-2016

Coastal Launch Program Site
Construct 1,200' Runway Expansion
Construct 3-Bay SREB
Construct access road
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Demolish Old SREB
Dozer
Land acquisition
Loader
New lighting
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Relocate apron

Runways: 17/35 - 2,040 Surface: GRAVEL-F Lighting:

Classification: Community On-Road No Enplanements: 0 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$11,153.39USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$1,338.73Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:06/12/2019

Airfield Manager: Jason Lange, 907-288-2428

Hours of Operation:
UNATNDD

Last Major Improvement: None

Airport has no fencing for airport for wildlife mitigation
Apply Dust Palliative
Clear trees
Coastal Launch Program Site
Construct a GA apron and taxiway
Construct access road
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Contains objects other than approved by ALP
Install ASOS or AWOS
Install MIRL Runway Lighting
Install new wind cone A
Install VGSI (PAPI)
Know wildlife hazards, no wildlife hazard program
Landfill is not an adequate distance from teh airfield
New Tie-downs
Reconstruct the runway to A2 standards
Regrade safety areas
Regular patching not done
Repair/Replace Cones and markers
resurface runway
Significant depressions exist
Surface shows no sign of dust pallative

HUGHES (HUS)

NPIAS: 02-0127

Runways: 17/35 - 3,381 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 291 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY19 Revenue:\$250.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$88,880.96Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/23/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Expand Apron, Install RW Lighting & Rehab,

Acquire Land for Development

3-02-0127-001-1990

Apply Dust Palliative	
Brush Cutter	_
Clear Vegetation in Runway Safety Areas	_
Compactor	_
Construct 620' Runway Extension	_
Construct Passenger Shelter	_
Construct Tie-Downs	_
Construct Toilet Facilities	_
Construct Ultimate Apron	_
Grader	_
Hughes Airport Improvements	_
Hughes SRE Building	_
Install ASOS or AWOS	_
Install New Wind Cone	_
Install VGSI (PAPI)	_
Install Weather Reporting Station and GPS Approach	_
Loader	_
Purchase compactor attachment	_
Raise Airport Grade, Relocate Apron, and Apply Dust Palliative on Operational Surfaces	<u> </u>
Re-Grade and Level Runway	_
Replace Runway Lighting System	<u> </u>
Replace SRE Building	<
Resurface Runway	_
Supplemental Wind Cone	_
Survey, Clear Obstructions, and Mark Property Boundary	_
Update ALP	_

Runways: 03/21 - 4,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 3,128 Borough: Yukon-Koyukuk Census Area

 Air Carrier Hub:
 No
 Medical Facility:
 No
 FY20 Revenue:
 \$2,899.69

 USPS Hub:
 Yes
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$79,094.14

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 07/23/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron 3-02-0128-006-2010

NEEDS:	In Project NEEDS:	In Project
HEEDO.	III F I OJECL INLLEDO.	III F I OJECL

NEEDS.	in Project
Apply Dust Palliative	
Brush Cutter	
Clear Obstructions	
Clear Vegetation in Runway Safety Areas	
Compactor	
Construct Passenger Shelter	
Construct Run-Up Pad on Apron	
Construct Tie-Downs	
Construct Toilet Facilities	
Construct Ultimate Apron	
Fuel Tank Upgrade	
Install Wind Cone	
Repair airfield lighting	
Repair Erosion on Shoulders	
Repair SRE building	
Repair/Replace Runway Threshold Lights	
Replace Beacon Light (White Side)	
Replace Runway Edge Cones	
Replace SRE Building	
Runway Grading and Crown Restoration	
SREB Cleanup	
Update ALP	

Runways: E/W - 5,000 Surface: WATER Lighting:

Classification: Community On-Road CY20 Enplanements: 3 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$189.86Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:11/14/2016

Airfield Manager: Tim Lacour, 907-755-2229

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron & Acquire Land

3-02-0129-001-1994

In Project NEEDS: In Project

HYD Rehab	X
replace wind sock	

NEEDS:

Runways: 05/23 - 3,000 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 73 Borough: Lake and Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$4,839.05USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$39,651.11Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:11/13/2017

Airfield Manager: Clint Anelon, 907-571-1261

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Land, Improve SREB & Access Road,

Install RW Lighting, Construct Apron & TW,

Improve RSA

3-02-0131-001-1993

Acquire additional ROW	
Apply Dust Palliative	X
Brush Cutting	'
Conduct ALP Update	
Construct a Heated 1-Bay SREB	
Construct Passenger Shelter	
Evaluate and Expand the Property Boundary at the terminal for land interest	
Expand apron	
Extend runway 05/23 to 3,300'	
Grader, loader, snow removal equipment	
Install apron concrete parking pads (2) and additional tie downs	
Install VGSI (PAPI)	
Miscellaneous SREB Cleanup	
Reinstall tie downs on apron	
Replace and extend existing MIRL	
Replace lighting	X
Resolve Airport Land Use Compliance Issues	
Resurface Runway and Taxiway	X

Runways: 08/26 - 5,086

18/36 - 4,800

E/W - 2,998

Surface: ASPH-G

ASPH-G

WATER-E

Classification: Regional CY20 Enplanements: 1,424

Air Carrier Hub: Yes **Medical Facility:**

USPS Hub: Yes School Facility: PK - 12

Part 139 Cert: No On/Off Road: Off

Airfield Manager: Clint Anelon, 907-571-1261

Last Major Improvement: Construct TW C, Strenthen RW 7/25 & 17/35,

> Improve Access Road, Acquire Security Equipment, Install Generator, Construct Service

Road

3-02-0132-006-2002 **NEEDS:**

Lighting: MED

MED

Borough: Lake and Peninsula Borough

FY20 Revenue: \$75,438.58

FY20 Ops Cost: \$520,242.81

Last CIMP Inspection Date: 11/14/2017

Hours of Operation:

OCT-MAY/M-F/0800-1630 JUN-SEP/M-W/0600-1630 JUNE-SEP/TH/0600-1400

In Project NEEDS: In Project

Acquire Land
Acquire Snow Removal Equipment
Airfield Lighting and Signage
Cold Storage Building Repairs
Construct 4,400' x 200' north/south waterway
Construct 5,086' Full Parallel Taxiway
Culvert replacement
Equipment - Chevy 3500 Needs Replacement
Helipad
Minor SREB Repairs
Misc. Equipment Repairs
Repaint Markings
Seal coat airport pavement
service fire extinguishers

Runways: 11/29 - 4,000 Surface: ASPH-P Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 3,309 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$697.36

USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$68,658.42

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Barry Youngberg, 907-772-4624 Hours of Operation: UNATNDD

Last Major Improvement: Reconstruct RW 11/29 & TW Lighting, Rehab RW

11/29 & Improve RSA 3-02-0398-007-2018

In Project

Acquire Land	
Construct access road	X
Construct apron and leasing area	
Construct Hard Stands	
Construct Tie-Downs	
Construct Toilet Facilities	
Extend OFZ & OFA 1000'	
Extend RSA 1000'	
Extend runway 1000'	
Fence Perimeter Road	X
Fix Part 77 obstructions	
FY'16 Runway Rehab	X
FY'18 SRE Building and Parking Lot	
FY'22 Obstruction Removal and Runway Extension	
FY'23 Apron Expansion	
PAPI	
Parking Lot	
Remove electric power vault	
Remove passenger shelter	
Replace Kake Runway Lighting	X
Replace Kake Taxiway Lighting	X
Runway Rehab	X
Test Taxilane Rehab	
Wildlife Hazard Assessment	

KALSKAG (KLG)

NPIAS: 02-0136

Runways: 06/24 - 3,198 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 674 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$4,245.93USPS Hub:YesSchool Facility:4 - 12FY20 Ops Cost:\$41,170.70Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/18/2017

Airfield Manager: Ricky Ciletti, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: Install Perimeter Fence

3-02-0136-002-2003

In Project NEEDS:	In Project
	In Project NEEDS:

Brush Cutting
Construct 10' of gravel access road
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Demolish or Sell Old SREB
Dust Control
Fencing
Grader
Gravel Resurfacing
Improve runway safety area grade and slopes
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Rehabilitate taxiway lighting
Relocate Access Road
Replace runway lighting
River Erosion a Concern
Security lighting
Threshold Markers
Timers for lighting

Runways: 03/21 - 3,986 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 446 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,886.39USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$97,264.82Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/23/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, Improve RSA, SREB, & Access

Road, Install RW Lighting 3-02-0137-002-1991

3-02-0137-002-1991				
NEEDS:	In Project	NEEDS:	In Project	
Apply Dust Palliative	Х	Replace Segmented Circle	Х	
Brush Cutter		SRE Building Repairs		
Clear Vegetation in Runway Safety Areas	X	Stage 1 - Rehabilitate Runway 3/21	X	
Compactor		Survey, Clear Obstructions, and Mark Property Boundar	-y	
Construct 14' Runway Extension		Update ALP		
Construct Passenger Shelter				
Construct SRE Building	X			
Construct Tie-Downs				
Construct Toilet Facilities				

NEED9:	n Project
Apply Dust Palliative	Х
Brush Cutter	
Clear Vegetation in Runway Safety Areas	X
Compactor	
Construct 14' Runway Extension	
Construct Passenger Shelter	
Construct SRE Building	X
Construct Tie-Downs	
Construct Toilet Facilities	
Construct Ultimate Access Road	X
Construct Ultimate Apron	
Drainage Improvements	X
Install Both PAPIs on Runway 3/21 (replace VASI)	
Install New Light Can	
Install New Wind Cone	X
Install VGSI (PAPI)	
Kaltag Airport Improvements - Stage 1	
Kaltag SREB Replacement	X
Lighted Supplemental Wind Cone	
Regrade Ramp	
Regrade Runway and Safety Areas	
Remove/Relocate Landfill	
Remove/Relocate Wildlife Ponds	
Repair Airport Fuel Tank	
Replace Airport Lighting System	X
Replace Fuel Storage Tank and Enhance Security Measu	ıres

Runways: 10/28 - 1,887 Surface: GRVL-DIRT-G Lighting:

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Denali Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: No School Facility: None FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Update ALP

In Project

Runways: 10/28 - 2,000 Surface: GRAVEL-G Lighting:

Classification: Community Off-Road CY20 Enplanements: 91 Borough: Kodiak Island Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,416.60USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$26,053.91Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/13/2016

In Project NEEDS:

Airfield Manager: Phil Smith, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Airport surface rehabilitation
Apron extension by 200'
Brush cutting (M&O OR)
Clear brush around segmented circle (M&O OR) Replace circle
Construct 1,300' Runway Extension
Construct new maintenance building
Construct Passenger Shelter
Construct Toilet Facilities
Grader
Improve Access Road
Install MIRL Runway Lighting
Install Perimeter Fence
Install VGSI (PAPI) X
Karluk SREB
Leasehold interest extended in 2012
Rehabilitate runway, taxiway and apron; aggregate needed
Rehabilitate West end of Runway
replace cones and or bands and re align cones
SREB and yard cleanup
Stabilize RSA embankment
verify landfill proximity to airport
Village has Native Sovereignty Issues
Wind cone replacement (M&O DM)

Runways: N/S - 2,000 Surface: WATER Lighting:

3-02-0139-001-1989

Classification: Local NPIAS Lower CY20 Enplanements: 2 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$1,615.90

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 11/15/2016

Airfield Manager: Tim Lacour, 907-755-2229

Hours of Operation:

Last Major Improvement: Rehabilitate Apron

Runways: 17/35 - 3,000 Surface: GRVL-DIRT-F Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 4,273 Borough: Bethel Census Area

Air Carrier Hub: No **Medical Facility:** FY18 Revenue: \$0.00 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$37,457.21 Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 03/01/2018

Hours of Operation: Airfield Manager: Joe Laraux, 907-453-2495 **UNATNDD**

Last Major Improvement: Install RW & Apron Lighting, Construct TW,

Acquire Land, Expand Apron, Improve SREB, Install RW VGS, Extend RW 17/35, & Improve

Access Road 3-02-0341-001-1997

NEEDS:	In Project	NEEDS:	In Project
Apply Runway Dust Palliative	Х	Stockpile gravel for surface repairs	
Brush cutting		Visual Aids	X
Construct 1-bay heated SREB		Widen RSA	

Construct 2-bay heated SREB Construct Crosswind Runway Construct Passenger Shelter Construct Security Fence for Fuel Tanks Construct Terminal Building Construct Tie-Downs Construct Toilet Facilities **Grader with Attachments** Improve SREB Install VGSI (PAPI) Kasigluk Airport Improvements Loader Placards, fire extinguishers and signage for fuel tanks Reconstruct runway 17/35 to address settlement and line of sight issues Rehab runway 17/35 Re-level segmented circle Relevel Windsock Tower Repair safety area undulations and soft areas Replace cones and reflective bands Replace Faded Runway Edge Lighting Globes replace threshold panels with current standard markers Safety Area Shift apron

In Project

Runways: 01/19 - 2,400 **Surface:** GRAVEL-G **Lighting:**

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:PK - 6FY20 Ops Cost:\$938.05Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:08/10/2020

In Project NEEDS:

Airfield Manager: Sean Montgomery, 907-262-1187

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Acquire Ownership of RPZ Area
Apron Restore
Brush cut and regrade runway
Brush cutting/Tree removal
Clear surface penetrations
Coastal Launch Program Site
Cone and Marker Repair / Replacement
Install aircraft tie-downs
Install Fence
Level Safety Area
Wildlife Hazard Program

KETCHIKAN INTL (KTN)

NPIAS: 02-0144

HIGH

Runways: 11/29 - 7,500 **Surface:** ASPH-G **Lighting:**

WNW/ESE - 9,500 WATER

Classification: Regional CY20 Enplanements: 46,435 Borough: Ketchikan Gateway Borough

 Air Carrier Hub:
 Yes
 Medical Facility:
 Yes
 FY18 Revenue:
 \$0.00

 USPS Hub:
 No
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$1,321,509.35

Part 139 Cert: Yes On/Off Road: Off Last CIMP Inspection Date: 07/19/2019

Airfield Manager: Mike Carney, 907-225-6800 Hours of Operation:

ALL/ALL/0600-2130

Last Major Improvement: Install perimeter fencing, gates, and gate controls to improve airport access security.

3-02-0144-026-2019

NEEDS:	In Project	NEEDS:	In Project	
Airport parking and circulation improvements		Install a second boarding ramp in terminal		
ARFF Vehicle		Ketchikan Seaplane Ramp and Floats	X	
BROOM RUNWAY SP		KIA fuel storage		
BROOM RUNWAY TOWED		KTN Paving by SREB & ARFF Buildings	X	
Brushing, safety areas and fence line		Loader		
Construct additional vehicle parking at the ferry dock a terminal	nd	Master Plan Update		
Construct executive hangars		Obstruction Survey for runway 11/29		
		PAPI bases need fill around them to eliminate hump		
Construct floatplane terminal		Pavement overlay of GA apron	_	
Construct New Airport Ferry Berth	X	Pavement overlay of lower apron access TXY.		
Construct parking structure		Preventative Maintenance for 1,125,000 sq. ft. runway and	and	
Construct Tie-Downs		587,100 sq. ft. apron/taxiway		
Crack Seal Runway 11/29		Ramp Repair		
Deicer Truck		Reconstruct 127,000 sq. ft. runway/taxiway pavement	t	
Dump Truck		Relevel surface drains and hard stands on ramp		
Exit taxiway		Remove part 77 obstructions		
Expand Access Road		Repaint Runway Markings		
Expand GA and Air Cargo Aprons		Repair Roof on ARFF Building		
Expand M&O/SREB and ARFF		Replace hardstands		
Fencing repairs (Lower apron fence non standard)		Runway pavement seams bleed water in winter		
Fencing repairs to eliminate wildlife hazards		Sander		
FY'14 30' Trap Plow		Search and Rescue Boat		
FY'14 Multi-purpose carrier		Snow Blower		
GA and air cargo expansion		Snow Plow		
Grader		Utility Wagon		
HANDICAP PASS LOADER				
Improve Terminal Building				

KING COVE (KVC)

NPIAS: 02-0147

MED

Surface: GRVL-G Lighting:

Classification: Community Off-Road CY20 Enplanements: 369 Borough: Aleutians East Borough

Air Carrier Hub: No **Medical Facility:** FY20 Revenue: \$5,336.69 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$68,025.66 Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 06/15/2016

Hours of Operation: Airfield Manager: Hap Kremer, 907-532-5000 **UNATNDD**

Last Major Improvement: Acquire Safety/Security Equipment & Install

Runways: 07/25 - 3,500

Perimeter Fencing 3-02-0147-004-2010

Brush cutting	
Construct Heated Passenger Waiting Terminal	
Construct New 3-Bay SRE Building	
Construct Tie-Downs	
Construct Toilet Facilities	
Expand Runway and Runway Safety Area and Widen Taxiway	_
Grader and Loader	_
Grading and digouts for shoulders, RSA and apron areas	X
Rehabilitate and pave the runway, taxiway and apron	X
Renovate Existing SREB	
Repair/Maintain Drainage Systems Along Runway	_
Resurface Runway, Apron, and Taxiway	X
Update ALP	
Vehicle gates with push button electric	
Wildlife and Minor Work	_

KING SALMON (AKN)

Lighting:

HIGH

MED

NPIAS: 02-0148

Runways: 12/30 - 8,901 **Surface:** ASPH-G

18/36 - 4,017 ASPH-F

NW/SE - 4,000 WATER

Classification: Regional CY20 Enplanements: 13,183 Borough: Bristol Bay Borough

Air Carrier Hub:YesMedical Facility:NoFY20 Revenue:\$177,782.86USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$1,149,095.96

Part 139 Cert: Yes On/Off Road: Off Last CIMP Inspection Date: 07/14/2014

Airfield Manager: Floyd Wilson, 907-246-3325 Hours of Operation:

Last Major Improvement: Rehabilitate RW 12/30 & TW A, B & E

3-02-0148-017-2018

Grader

Highspeed blower

Install 5 Auto-Gate Proxy Readers

Install Transit Shelter on Apron

Install REIL and PAPI for Runway 18/36

NEEDS:	In Project	NEEDS:	In Project
8 Yd truck with Sander		Loader	
Apron Markings	X	Master Plan Update	
ARFF bunker gear		Minivan	
ARFF SCBA compressor		Overhead Crane	
ARFF Vehicle		Purchase RPZ	
Badging computer, software upgrade and printers		Purchase Signs	
Brush cutting (M&O OR)		Re-grade and Compact Runway Safety Area	
Chart and remove obstructions		Rehabilitate GA Apron and Taxiway G	X
Compactor		Rehabilitate Runway 18/36 and Runway 18 Overrun	X
Complete RSA		Rehabilitate Taxiways	X
Construct 4-Bay SRE Building	X	Rehabilitate TWY C	X
Construct Full Parallel Taxiway		Remove and Repaint Markings	
Construct GA Sanitation Facility		Remove leadin Twy	X
Construct Parallel Taxiway; Realign and Pave Main Street and Jensen Road; Expand Long Term Vehicle Parking Area; Expand Terminal Apron		Remove Taxiway P	X
		Repair/Replace Segmented Circle Panels	
Construct Sand Storage Facility		Replace edge lighting	X
Construct Tie-Downs		Replace wind cones	
Construct Toilet Facilities		Runway lights	Х
Crack Seal Pavement		Runway turnaround	Х
Dozer		Upgrade Airport Access Controls	X
Fence and Gate Repair			
GA Parking Solution			

Χ

Runways: 17/35 - 3,200 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 6,186 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$716.55USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$62,429.00Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/08/2016

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW 3-02-0150-004-2010

Airfield Vandalism	
Apply Dust Palliative	
Construct 100' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Construct two SREBs	_
Environmental	
Install VGSI (PAPI)	_
Replace edge lighting	X
Resurface Runway	
River Access Rd	
SREB Safety Repairs	

Runways: E/W - 4,000 Surface: WATER Lighting:

Classification: Local NPIAS Lower CY20 Enplanements: 62 Borough: Kodiak Island Borough

Air Carrier Hub:NoMedical Facility:NoNo Revenue:\$0.00USPS Hub:NoSchool Facility:NoneNo Ops Cost:\$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: KODIAK REGIONAL AQUACULTURE ASSOC., (877)

Hours of Operation:
UNATNDD

Last Major Improvement:

Runways: 12/30 - 3,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,460 Borough: Northwest Arctic Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,575.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$60,973.34Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/05/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Acquire Easement for Approaches & Improve

Airport Erosion Control, Construct Erosion

Protection

3-02-0152-005-2018

Apply Dust Palliative
Clear Transitional Surface by Remove Brush
Coastal Launch Program Site
Construct 1,000' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Expand Apron
Expand RSA and ROFA
Grader and Loader
Install VGSI (PAPI)
Kivalina Airport Erosion Control
Kivalina SRE Building Replacement
Loader
loader mounted snow blower
Paint Building Exterior
Reestablish Runway Crown and Compact Surface
Rehabilitate Runway Surface
Relocate Landfill
repair or replace furnaces
Replace wind cone, runway cones and or color bands.
Widen Runway by 15'

KLAWOCK (AKW)

NPIAS: 02-0154

In Project

Runways: 02/20 - 5,000 **Surface:** ASPH-G **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 13,503 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$41,125.18USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$90,633.24

In Project NEEDS:

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Tim Lacour, 907-755-2229

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB

NEEDS:

3-02-0154-0082001

add 7 smaller aircraft tie downs	Electrical conduit exposed		
add NPI markings	Evaluate /Repair Runway Undulations		
Apron Lighting	Expand apron and lease lots		
Apron/Taxiway Preventative Maintenance	expand terminal aircraft parking apron		
BROOM RUNWAY TOWED	extend W&S Utilities		
Brush cut RSA RWY 2/20	Fence Perimeter Road X		
Brush Cutting in Runway Safety 2/20 Area	FY'20 Obstruction Removal		
Conduct Wildlife Hazard Assessment X	Hazmat Barrels Located on Airport		
construct access road and aircraft pullout ramp to provide SP	Improve Access Road		
access to airport apron	improve airfield pavement		
construct access taxiway to GA aviation lease lots X	install approach lighting		
Construct air cargo apron improvements and a cargo terminal	New electric vehicle gate		
Construct Apron Paint 6 biz jet parking spaces			
Construct ARFF building and purchase ARFF vehicle	parking lot 100 sq. ft.? raise approx. 1000 lf. of Access road to apron grade		
construct connector road between apron and access road	Pavement Preservation		
Construct float plane haul out and access road	Reconfigure apron lease lot arrangement		
Construct helipad	Reduce runway grade, extend runway 1000'		
construct lease lots	Rehabilitate Runway 02/20		
Construct Parallel Taxiway	Relocate ASOS Wind Sensor		
Construct ramp parking hard stands	relocate wind sensor		
Construct runway extension	Remove Part 77 obstructions		
Construct SREB X	Remove ROFA and airspace obstructions		
Construct Terminal Building			
Construct Tie-Downs	Repair erosion damage and install permanent beach erosion control		
Construct Toilet Facilities	Replace Segmented Circle and Wind Cone		
Crack Seal Runway 2/20	Revenue Generation		
Dump Truck	Runway markings (NPU) poor		

KLAWOCK (AKW)

NPIAS: 02-0154

Runway signs	
Safety Area Drainage	
Sander	
Transfer PAPI ownership to FAA, restore Runway 20 PAPI's	
Wildlife control	Х

Runways: 09/27 - 4,020 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 753 Borough: Northwest Arctic Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$49,571.78Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/07/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron & RW 9/27 & Extend RW

9/27 3-02-0427-003-2003

ASOS needs to be connected to emergency generator
AWOS
Brush Cutting
Building upgrades
Construct new Taxiway
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dozer
Floodlights
Fuel Tank Upgrade
grade and compact safety areas
Grader
Install ASOS or AWOS
Install VGSI (PAPI)
Rehab Runway
Rehab Taxiway
Rehabilitate Runway Surface
Weather Reporting Equip

Runways: 01/19 - 5,010 **Surface:** ASPH-G **Lighting:** HIGH

08/26 - 7,534 ASPH-G HIGH 11/29 - 5,400 ASPH-G HIGH

Classification: Regional CY20 Enplanements: 24,857 Borough: Kodiak Island Borough

Air Carrier Hub:YesMedical Facility:YesFY20 Revenue:\$222,086.12USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$1,152,316.05Part 139 Cert:YesOn/Off Road:OffLast CIMP Inspection Date:10/10/2016

Airfield Manager: Phil Smith, 907-487-4952

SAME AS ARPT MAINT HRS

In Project

Χ

Last Major Improvement: Improve Airport Drainage 3-02-0158-019-2015

NEEDS:	In Project	NEEDS:	ı
Airport Drainage	Х	Upgrade the ARFF vehicle from 1,500 to 3,000 gallons	
Apron A, B, C Rehab pavement	X	Vehicle gates with electronic swipe capability	-
ARFF bunker gear			-
ARFF Vehicle 3000 gal.			
Badging computer, software upgrade and printers			
Coastal Launch Program Site			
Construct new 3-bay ARFF building			
Construct Tie-Downs	X		
Electrical	X		
Grader			
lighting	X		
Maintain pavement markings and crack seal (M&O SPM))		
Minivan			
New Equipment			
Pave access roads			
Perimeter fencing repairs/replacement	X		
Rehabilitate Runway 11/29 Pavement	X		
Remove Part 77 tree obstructions (M&O OR)			
Replace electric Gate A	X		
Replace fence/gates around perimeter of ramp	X		
Replace fencing around Commercial Apron perimeter	X		
Sand seal aprons A & C (M&O SPM)			
Surface Area and Reconfigure Drainage between RW 7 a	and		
Taxiway F Rehab Pavement	X		
Tree/Brush Cutting around Airport			
Upgrade Airport Access Controls	X		

KOKHANOK (9K2)

NPIAS: 02-0406

Runways: 07/25 - 3,300 Surface: GRVL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 1,095 Borough: Lake and Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$3,227.14USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$31,553.50Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:11/14/2017

Airfield Manager: Clint Anelon, 907-571-1261 Hours of Operation: UNATNDD

Last Major Improvement: Extend RW 6/24, Expand Apron, Construct SREB

3-02-0406-002-2005

NEEDS:	In Project	NEEDS:
Airport Drainage	Х	
Apply Dust Palliative		
Brush Cutting		
Construct Passenger Shelter		
Construct SREB		
Construct Tie-Downs		
Construct Toilet Facilities		
Expand RSAs		
Expand runway to 4,200' x 75'		
Grader & loader with attachments		
Install one or two apron concrete parking pads		
Install PAPIs and REILs		
Kokhanok Resurfacing and Fencing	X	
Miscellaneous SREB Cleanup and Cone Replacement		
Replace Devils Creek culvert		
Resurface gravel runway, taxiway, and apron	X	
Wildlife Hazard on Airport		

KOLIGANEK (JZZ)

NPIAS: 02-0424

Runways: 09/27 - 3,300 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 981 Borough: Dillingham Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,589.74USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$48,528.44Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/02/2020

Airfield Manager: Jon Taylor, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstructed and Extended RW to 3,300' in 2015

Brush removal
Bull dozer
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Emergency eye wash station
Fire extinguishers out of annual maintenance
Grader & Loader with Attachments
Install AWOS
Install REILs
Loader
Rehabilitate access road
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Repair man door
Wildife mitigation

KONGIGANAK (DUY)

Runways: 01/19 - 2,400 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 3,712 Borough: Bethel Census Area

Air Carrier Hub: No **Medical Facility:** FY18 Revenue: \$0.00 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$38,997.13

Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 08/08/2016

Hours of Operation: Airfield Manager: Joe Laraux, 907-453-2495 **UNATNDD**

Last Major Improvement: Extend RW 18/36, Widen RSA

NEEDS:

3-02-0380-003-2010

In Project NEEDS: In Project

NPIAS: 02-0380

Scarify, reshape and recompact surfacing material runway (M&O SPM) Taxiway Lighting Upgrade Windsock with Lighting

Add surface course to runway surface Construct 900' Runway Extension Construct a new apron and segmented circle Construct new SREB Construct Passenger Shelter Construct Snow Removal Equipment Building Construct SREB Construct Tie-Downs **Construct Toilet Facilities** Environmental **Expand Apron** Extend Runway Safety Area Grader and Loader Install ASOS or AWOS Install NAVAIDS Install VGSI (PAPI) Х Kongiganak Airport Rehabilitation Loader Minor Gravel Resurfacing Х Rehab Runway, Taxiway and Apron Rehabilitate Apron Rehabilitate Runway Rehabilitate Taxiway Replace Wind Cone Resurface south half of existing runway Runway Lighting Runway Resurfacing

Runways: 02/20 - 4,400 Surface: GRAVEL-F Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 3,709 Borough: Kusilvak Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$129,751.92Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:
UNATNDD

Last Major Improvement: Expand Service Road to allow SRE to pass

maintenance vehicles; Install Misc NAVAIDS Reconstruct Runway Lighting 02/20; Reconstruct Taxiway Lighting; Rehabilitate RW 2/20, Taxiway

NEEDS: and Apron 3-02-0159-004 Project NEEDS: In Project

20:1 Clearance	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Grader	_
Install AWOS (Various)	X
Install VGSI (PAPI)	
Kotlik Airport Rehab	X
Repair Ramp	
Replace runway markers and cones	
Replace segmented circle and light tower	
Resurface airport and electrical system replacement	

KOYUK ALFRED ADAMS (KKA)

NPIAS: 02-0161

Runways: 01/19 - 3,002 Surface: GRVL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,013 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$72,304.67Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron, Acquire Land for Development,

Improve SREB 3-02-0161-002-1991

Building upgrades
Construct 998' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
New ULSD tank
Repair airfield lighting
resurface runway
Update ALP

Runways: 06/24 - 4,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 332 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: Yes School Facility: PK - 10 FY20 Ops Cost: \$122,265.40

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 03/23/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RSA, Rehab & Extend RW 6/24, Expand

Apron, Construct SREB 3-02-0162-002-2003

Building Maintenance
Compactor
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Grader
Install ASOS or AWOS
Koyukuk SRE Building Replacement
Lighted Supplemental Wind Cone
Loader
PAPI Needed (Runway 24)
Survey, Clear Obstructions, and Mark Property Boundary
Upgrade lighting

Runways: 18/36 - 3,199 Surface: GRVL-DIRT-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 759 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$29,946.09Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/08/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Construct New Airport

3-02-0435-001-2001

1117	lojeci
Access Road	
Acquire Land	
Apply Dust Palliative on Runway	
Beacon	
Brush Cutter	
Brush cutting	
Construct 1-bay SREB with Floor	X
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Dozer	
Dust Control	
Grader	
Loader	
Minor Gravel Resurfacing & Dust Control	
Rehab RW 18/36 gravel surface, safety areas, txys and ramp)
Rehabilitate the runway, taxiway, safety areas, apron, and access road.	X
Relevel and Repair Windsock Tower	
Remove RW 36 approach (hill)	
Repair safety area undulations and soft areas	
Replace cones and reflective bands	
Replace Faded Runway Edge Lighting Globes	
Safety Area	
SREB maintenance	
Stockpile gravel for surface repairs	

KWIGILLINGOK (GGV)

NPIAS: 02-0165

Runways: 15/33 - 1,835 Surface: GRVL-DIRT-F Lighting:

Classification: Community Off-Road CY18 Enplanements: 3,320 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$32,242.41Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/18/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Apron, RW 15/33 & TW

3-02-0165-004-2018

Acquire Native Allotments and Tribal Property	Х
Apply Dust Palliative	
Construct 1,465' Runway Extension	X
Construct 2, 1-bay SREBs	X
Construct New Apron	X
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Grader	
Grader, snow plow and wing attachments, loader	
Gravel Surface Repair	
Install erosion projection for rwy embankment along tidal slough	
Install MIRL Runway Lighting	X
Install Taxiway Lighting	X
Install VGSI (PAPI)	
Loader	
Rehabilitate runway, taxiway, and apron surfaces	X
Replace Wind Cone	
Replace Wind Cone Tower	_
Reshape, recrown and compact runway surface	X
Resolve Trespass Property Issues	
Runway reduced to 1840 x 30 on 6-27-11 in message to FAA from the previous 2,472'.	

Runways: 13/31 - 2,900 Surface: GRAVEL-E Lighting:

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Matanuska-Susitna Borough

Air Carrier Hub:NoMedical Facility:NoFY19 Revenue:\$200.00USPS Hub:NoSchool Facility:K - 12FY18 Ops Cost:\$0.00

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date: 10/24/2015

Airfield Manager: John Hoffman, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 12/30, Access Road, & Apron

3-02-0430-002-20-2010

NEEDS: In Project NEEDS: In Project

Remove obstructions on dock at Seaplane Base

Remove/replace Wind Cone

Safety area/ ramp grading

Secure runway

Runways: 04/22 - 2,690 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 2,450 Borough: Kodiak Island Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$33,485.59Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/13/2015

Airfield Manager: Phil Smith, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB & Access Road, Install RW

Lighting, Construct Apron, Acquire Land 3-02-0166-001-1993

Add a GPS Approach
Airport Lighting Repair
Apply Dust Palliative
Brush Cutting
Construct 1-bay SREB
Construct 600' Runway Extension
Construct Passenger Shelter
Construct Toilet Facilities
Grader
Install VGSI (PAPI)
Level out Runway 4/22
Purchase a Portable Emergency Eye Wash Station
Regrade RSA
Rehabilitate Runway Surface and Edges
Remove old chevron panel signs
Remove Trees on West end of Runway
Repair/replace runway lights.
SREB cleanup
Stream realignment
Wind Sock replacement

NPIAS: ---

In Project

Runways: 15/33 - 2,355 **Surface:** GRVL-G **Lighting:**

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:FY18 Ops Cost:\$5,734.42Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:11/01/2017

In Project NEEDS:

Airfield Manager: Jason Lange, 907-288-2428

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS:

Various - Surface Course and Brush Cutting

Runways: 01/19 - 3,284 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 261 Borough: Lake and Peninsula Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: Yes **School Facility:** PK - 12 **FY20 Ops Cost:** \$43,138.58

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Floyd Wilson, 907-246-3325

Last Major Improvement: Construct SREB

3-02-0167-002-2003

Hours of Operation:
UNATNDD

In Project NEEDS:	In Project
	In Project NEEDS:

Apply Dust Palliative

Brush cutting

Construct Crosswind 07/25 Runway

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Extend RSA to 120' x 3761'

Install ASOS or AWOS

Install VGSI (PAPI)

Place E-1 on apron, shoulders, and RSA and compact (M&O SPM)

Rehabilitate airfield with new aggregate on runway, taxiway, apron, shoulders, and RSA

Replace threshold markers

LIME VILLAGE (2AK)

NPIAS: 02-0360

Runways: 10/28 - 1,500 Surface: GRVL-DIRT-F Lighting:

Classification: Local NPIAS Lower CY18 Enplanements: 25 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,370.00USPS Hub:NoSchool Facility:FY20 Ops Cost:\$33,692.84Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/20/2017

Airfield Manager: Steffen Strick, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: None

windsock

NEEDS: In Project NEEDS: In Project

Airport is subject to river erosion and ice jam flooding. building Bypass trail at the airport for access around the airport Construct a second SREB Construct new community class airport Construct RSA (4800' x 75') Construct runway (4000' x 75'), taxiway, apron (60,000 sqft) Construct SREB with rotating beacon Embankment repair and obstruction removal Embankment/Erosion equipment fuel tank Extend electric power lines to airport and acquire 50 acres of land Grader Grader and loader Grader, snow plow, loader wheel Reestablish airport Right of Way Remove brush and trees from approaches Remove trees from primary surface Remove Windsock from on Top of SREB Resurface eroded material on west end of runway runway Runway cannot be lengthened without expensive relocation **SREB**

LIVENGOOD CAMP (4AK)

NPIAS: ---

In Project

Runways: 15/33 - 3,000 Surface: GRVL-G Lighting:

Classification: Local Non-NPIAS CY18 Enplanements: 5 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$1,127.98
USPS Hub: No School Facility: FY20 Ops Cost: \$4,109.09

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 09/30/2016

In Project NEEDS:

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: None

Minor Drainage Work

NEEDS:

Remove Possible Obstructions

LLOYD R ROUNDTREE SEAPLANE FACILITY (63A)

Runways: NE/SW - 9,000 **Surface:** WATER-E **Lighting:**

Classification: Local NPIAS Lower CY18 Enplanements: 1,376 Borough: Petersburg Borough

Air Carrier Hub:NoMedical Facility:YesFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$3,749.91Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/10/2016

In Project NEEDS:

Airfield Manager: Michael Etcher, 907-772-4624

Hours of Operation:
UNATNDD

Last Major Improvement: Construct Apron & Acquire Land

3-02-0340-001-1994

NPIAS: 02-0340

In Project

Replace Wind Sock

NEEDS:

Veg clearing /wildlife management /mat replacement

MANLEY HOT SPRINGS (MLY)

NPIAS: 02-0170

Runways: 18/36 - 3,400 Surface: GRAVEL-G Lighting: MED

Classification: Community On-Road CY20 Enplanements: 31 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$-100.00USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$128,708.24

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date: 11/30/2017

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0170-003-2015

NEEDS: In Project NEEDS: In Project

Construct Passenger Shelter

Extend and widen runway to 3,400' x 75'

Increase clear area to treeline runway end 18

Install VGSI (PAPI)

Manley Airport Improvements and Apron Construction

X

Wheel Loader

MANOKOTAK (MBA)

NPIAS: 02-0171

Runways: 03/21 - 3,300 Surface: GRAVEL-G Lighting: MED

Borough: Classification: Community Off-Road CY18 Enplanements: Dillingham Census Area

Air Carrier Hub: No **Medical Facility:** FY20 Revenue: \$4,348.02 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$52,573.28 Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 10/28/2020

Hours of Operation: Airfield Manager: Jon Taylor, 907-842-5511 **UNATNDD**

Last Major Improvement: Construct New Airport

Replace runway lighting

3-02-0473-002-2007

NEEDS: In Pro	ect NEEDS:	In Project
Apply Dust Palliative	Replace taxiway lighting	
Brush removal	Snow Blower	
Coastal Launch Program Site	Visual Aid repairs/replacement	
Construct additional lease lots	Wildife Mitigation	

Construct Additional Taxiway Construct Tie-Downs Construct Toilet Facilities Construction SRE/highway M&O building Day tank pump repair Emergency eye wash station **Erosion Protection** Expand RPZ Extend Access Road by Apron Extend Apron Additional 400' x 300' Extend ROFA 700' Extend ROFZ 700' Extend RSA to 4,600' Extend Runway to 4,000' Fire extinguisher service Fuel tank upgrades Install REILs Install VGSI (PAPI) Rehabilitate apron Rehabilitate runway Rehabilitate taxiway Relocate Wind Cone and Segmented Circle

MARSHALL DON HUNTER SR (MDM)

NPIAS: 02-0363

Runways: 07/25 - 3,200 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 2,643 Borough: Kusilvak Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$750.00USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$73,540.86Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: Erik Weingarth, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport & Improve SREB

3-02-0363-003-1999

Construct 800' Runway Extension
Construct Crosswind Runway
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Fuel Tank Upgrade
Install VGSI (PAPI)
Marshall Airport Improvements X
purchase a portable emergency eye wash station
Severe Cracking & Lighting Shifting
Shoulder and slope repair
Threshold Lighting Repair
Update ALP

Runways: 13/31 - 2,700 **Surface:** TURF-GRVL-G **Lighting:**

Classification: Local NPIAS Lower CY20 Enplanements: 15 Borough: Valdez-Cordova Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: No School Facility: None FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: John Hoffman, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Develop ALP

Tie-down replacement

MC GRATH (MCG)

Runways: 05/23 - 2,000

16/34 - 5,936

Surface: GRAVEL-G

ASPH-G

Lighting: MED

MED

Classification: Regional

CY20 Enplanements: 825

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: Yes

Medical Facility:

FY20 Revenue:

\$116,723.42

NPIAS: 02-0176

USPS Hub: No

School Facility: PK - 12

FY20 Ops Cost:

\$437,174.45

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

08/24/2016

In Project

Airfield Manager:

Steffen Strick, 907-524-3241

Last Major Improvement: Construct RW & Apron

3-02-0176-005-2006

Hours of Operation:

MAY-SEPT/MON-WED/0700-1730 OCT-APR/MON-FRI/0800 - 1630 MAY-SEPT/THURS/0700-1500

NEEDS:	In Project	NEEDS:
Construct Access Road	Х	Snow Blo
Construct SREB	X	Snow plov
Construct Tie-Downs		Vehicle ga
Construct Toilet Facilities		
Crack Seal		
Erosion Control	X	
Expand SREB		
Improve Airfield Erosion Control	X	
Install Fencing	X	
Install NAVAIDs	X	
Install Perimeter Fence		
Install wind cone and segmented circle	X	
Obstruction removal		
Pavement Markings	X	
Pavement Rehabilitation	X	
Perimeter fencing repairs/replacement		
Reconstruct Airfield Guidance Signs	X	
Reconstruct Apron	X	
Reconstruct Runway	X	
Reconstruct Runway Lighting	X	
Reconstruct Runway, Taxiway, and Apron Pavement	X	
Reconstruct Taxiway	X	
Reconstruct Taxiway Lighting	X	
Rehabilitate Apron		
Rehabilitate Crosswind Runway		
Rehabilitate Runway 16/34 Lighting	X	
Replace Crosswind Runway Lighting		

Snow Blower
Snow plow, snow blower, dump truck, snow attachments
Vehicle gates with push button electric

Runways: 01/19 - 3,501 **Surface:** GRVL-DIRT-F **Lighting:**

3-02-0334-003-1999

Classification: Local NPIAS Lower CY18 Enplanements: 5 Borough: Valdez-Cordova Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$11,763.06

USPS Hub: No School Facility: FY20 Ops Cost: \$27,374.33

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: John Hoffman, 907-822-3222

Last Major Improvement: Construct RW 1/19

NEEDS: In Project NEEDS: In Project

Update ALP

MEKORYUK (MYU)

NPIAS: 02-0178

Runways: 05/23 - 3,001 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 416 Borough: Bethel Census Area

Air Carrier Hub: No **Medical Facility:** FY18 Revenue: \$0.00 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$83,329.61

Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 08/26/2016

Hours of Operation: Airfield Manager: Joe Laraux, 907-543-2495 **UNATNDD**

Last Major Improvement: Rehabilitate TW, Apron, & RW 5/23, Install RW

Lighting 3-02-0178-001-1984

NEEDS:	In Project	NEEDS:	In Project
Abandon east GA apron and the GA "elephant ear" apro	n	Rehabilitate Taxiway	Х
ASOS and RCO improvements		Replace Electrical Lighting Vault and Transformer	X
Build Crosswind Runway		Replace New Windsock	X
Building cleaning and safety checks		Resurface runway and build crosswind runway	
Coastal Launch Program Site		Runway Extension	
Construct 930' Runway Extension		Segmented Circle	X
Construct new three bay SREB		Update ALP	X
Construct Passenger Shelter		Upgrade or construct heated SREB	
Construct SREB		Visual Aids	X
Construct Tie-Downs			
Construct Toilet Facilities			

Abandon east GA apron and the GA "elephant ear" apron		Rehabilitate Taxiway	Х
ASOS and RCO improvements		Replace Electrical Lighting Vault and Transformer	Х
Build Crosswind Runway		Replace New Windsock	
Building cleaning and safety checks		Resurface runway and build crosswind runway	
Coastal Launch Program Site		Runway Extension	
Construct 930' Runway Extension		Segmented Circle	Х
Construct new three bay SREB		Update ALP	Х
Construct Passenger Shelter		Upgrade or construct heated SREB	
Construct SREB		Visual Aids	Х
Construct Tie-Downs			
Construct Toilet Facilities			
Dozer			
Grader			
Gravel Resurfacing			
Install NAVAIDs	X		
Loader wheel, grader, bulldozer, snow attachments, snow blower			
Mekoryuk Airport Access and Road Rehab	X		
Mekoryuk SRE Building Replacement	X		
Minor Gravel Resurfacing			
Reconstruct Runway Lighting	X		
Reconstruct runway with grade raise	X		
Reconstruct Taxiway Lighting	X		
Rehab Runway & Access Road	X		
Rehabilitate Access Road	X		
Rehabilitate Apron	X		
Rehabilitate Runway	X		

MERLE K (MUDHOLE) SMITH (CDV)

NPIAS: 02-0067

HIGH

Surface: ASPH-G Lighting: **Runways:** 09/27 - 7,500

16/34 - 1,899 **GRVL-F**

CY20 Enplanements: 6,417 Borough: Valdez-Cordova Census Area Classification: Regional

Air Carrier Hub: No **Medical Facility:** FY20 Revenue: \$69,553.52 USPS Hub: School Facility: K-12 FY20 Ops Cost: \$744,006.49

Part 139 Cert: Yes On/Off Road: Off **Last CIMP Inspection Date:** 09/29/2020

Hours of Operation: Airfield Manager: Robert Mattson, 907-424-3202

ALL/MON-FRI/0700-1730 ALL/SAT-SUN/0700-1730 **Last Major Improvement:** Apron, TW, & GA Improvements

3-02-0067-014-2016

Resolve drainage problems Runway 9/27 Tree Removal

NEEDS:	In Project NEEDS:	In Project
AADE/Maintonanaa Chan Danlaaanant	Dunium Linkt Dlaw Olaman	

AARF/Maintenance Shop Replacement Runway Light Plow Cleaner Airport crack sealing Runway Resurfacing Airport Operations Vehicle Sand Storage Repairs Blower (7,500 ton per hour) SREB Replacement Towed Broom 22' or wider Chemical Storage Building Replacement Complete obstruction removal Transient and GA aircraft parking Construct Access Road Tree removal Construct Full Parallel Taxiway Update Airport Master Plan Study Construct partial parallel and connecting taxiways Wildlife Control Measures Construct Tie-Downs Cordova Airport Apron, Taxiway and GA Improvements Stage 2 Χ Cordova Airport ARFF Building Replacement Χ Cordova Airport Perimeter Fence Installation Cordova Airport RSA Improvements (Drainage) Cordova Airport Security Upgrades Cordova SREB/ARFF Building Replacement **Deicer Truck** Expand existing apron area Heliport pad, aviation support areas Install Perimeter Fence Maintenance Equipment Х Purchase New 1,500 gal. ARFF Truck Rehabilitate the runway safety areas, including grading and drainage improvements, clearing and grubbing. Replace Damaged Culverts

Runways: E/W - 5,000

N/S - 5,000

Surface: WATER

WATER

Lighting:

Classification: Community Off-Road

CY20 Enplanements: 178 **Borough:** Prince of Wales-Hyder Census Area

Air Carrier Hub: No

Medical Facility:

FY18 Revenue: \$0.00

USPS Hub: Yes

School Facility: PK - 12

\$2,087.06

FY18 Ops Cost:

Hours of Operation:

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

05/24/2019

Airfield Manager:

Scott Gray, 907-465-4512

UNATNDD

Last Major Improvement: Rehabilitate SPB

3-02-0369-003-2004

NEEDS: In Project NEEDS: In Project

Master Plan Update

Metlakatla Seaplane Base Rehab and Reconfigure

Χ

Runways: NW/SE - 7,000 Surface: WATER Lighting:

Classification: Local NPIAS Lower No Enplanements: 0 Borough: City and Borough of Wrangell

Air Carrier Hub:NoMedical Facility:NoNo Revenue:\$0.00

USPS Hub: No School Facility: No Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: GREG MEISSNER, HARBOR MASTER, (907) 743-3736

Hours of Operation: UNATNDD

Last Major Improvement:

MINCHUMINA (MHM)

NPIAS: 02-0180

Runways: 03/21 - 4,184 Surface: GRAVEL-G Lighting: MED

Classification: Local NPIAS Lower CY20 Enplanements: 0 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,980.38USPS Hub:NoSchool Facility:NoneFY20 Ops Cost:\$73,547.08Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:06/26/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0180-002-1991

NEEDS: In Project NEEDS: In Project

Clean up Shop Area Clean, organize and inventory materials Compactor FY'18 Seaplane Float Rehab/Reconfiguration Grader Leasehold cleanup Lighted Supplemental Wind Cone Lighting Repairs PAPI Needed (Runway 21) Repair Wiring and Conduit Replace eye wash stations Replace Windsock Pole and Lighting Runway resurfacing Survey, Clear Obstructions & Mark Property Boundary taxiway culvert replacement Update ALP Wildlife control Wind Cone Replacement

MINTO AL WRIGHT (51Z)

Runways: 02/20 - 3,400 Surface: GRAVEL-G Lighting: MED

Classification: Community On-Road CY18 Enplanements: 248 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: No **School Facility:** PK - 12 **FY20 Ops Cost:** \$48,402.42

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, RW, & Apron

NEEDS:

3-02-0336-002-2007

In Project NEEDS: In Project

NPIAS: 02-0336

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Update ALP

MOUNTAIN VILLAGE (MOU)

NPIAS: 02-0184

Runways: 02/20 - 3,501 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 919 Borough: Kusilvak Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$673.26USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$111,541.85Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: Erik Weingarth, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 2/20 & Construct RSA

3-02-0184-002-2004

Apply Dust Palliative	
Construct 499' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Dozer	
Fuel Tank Upgrade	
Install PAPI	
Mountain Village SRE Building Replacement	Х
Repair PAPI	
Repair REIL Lighting	
Repair Shoulder/RSA cracking	
Repair/Renovate SRE Building	
Replace Segmented Circle	
Replace supplemental edge markers	
Replace Wind Cone	
Resurface Runway	
Safety Area Repairs	
Update ALP	

Runways: 08/26 - 1,950

Surface: GRAVEL-P 08W/26W - 2,000 WATER 14/32 - 1,836

GRAVEL-P

Classification: Local NPIAS High

CY18 Enplanements: 19 **Borough:** Bristol Bay Borough

Air Carrier Hub: No

Medical Facility:

FY20 Revenue:

USPS Hub: No

School Facility: PK - 12

FY20 Ops Cost: \$20,218.76

Part 139 Cert: No

On/Off Road: On

Last CIMP Inspection Date:

07/25/2019

\$625.00

Airfield Manager:

Floyd Wilson, 907-246-3325

Hours of Operation:

Lighting:

UNATNDD

Last Major Improvement: None

NEEDS:	In Project NEEDS:	In Project
Airport is not federally obligated		
Brush Cutter		
Clear Vegetation in Runway Safety Areas		

Compactor and Grader

Environmental Clean up

Full Survey of Airport Property Boundary

Improve Drainage

Loader and Blower

New ALP for Seaplane Base Study

Re-Grade and Compact North/South Runway

Repair Windsock

Resurface Runways

Snow removal attachments

Update ALP

In Project

Runways: 01/19 - 1,850 Surface: GRAVEL-P Lighting:

Classification: Community Off-Road CY20 Enplanements: 639 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$23,180.93

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/27/2016

In Project NEEDS:

Airfield Manager: Kevin Jones, 907-235-5217

Hours of Operation:
UNATNDD

Last Major Improvement: None

Provide shore protection

Replace all cones and markers

Replace wind sock and pole

Transformer replacement

NEEDS:

Acquire acreage for new airport

Construct 2-mile access road connecting Port Graham & Nanwalek

Construct Storage Shed

Construct Toilet Facilities

Install AWOS or ASOS

Install Secondary Wind Cone

Landfill relocation

Mark Runway Edges

Minor Gravel Resurfacing

NAPAKIAK (WNA)

NPIAS: 02-0188

Runways: 16/34 - 3,248 Surface: GRAVEL-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 273 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

 USPS Hub:
 Yes
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$36,322.08

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 06/18/2014

Airfield Manager: Joe Laraux, 907-453-2495 Hours of Operation:

Last Major Improvement: Construct SREB

3-02-0188-002-2003

NEEDS:	In Project NEEDS:	In Project
20:1 Clearance		

20:1 Clearance
Address Boundary Crossing Issues X
Apply Dust Palliative
Brush Cutting (M&O OR)
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dust Control
fencing
Grader
Grader, loader, snow plow attachments
lighting repairs
Loader
Minor Gravel Resurfacing
Place E-1 on runway crown and compact
Repair Cones
Replace Electrical Lighting Vault and Transformer
SREB Repair
Update ALP
Update Master Plan
wildlife control

NAPASKIAK (PKA)

308

Runways: 02/20 - 3,000

09W/27W - 15,000

Surface: GRVL-G

WATER

Lighting: MED

Classification: Community Off-Road

CY20 Enplanements:

Borough:

Bethel Census Area

Air Carrier Hub: No

Medical Facility:

FY18 Revenue:

\$0.00

NPIAS: 02-0189

USPS Hub: Yes

School Facility: PK - 12

FY20 Ops Cost:

\$31,852.46

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: Hours of Operation:

UNATNDD

06/18/2014

Airfield Manager:

Joe Laraux, 907-453-2495

Last Major Improvement:

Airport relocation study needed

Construct Apron, TW, Rehabilitate RW 1/19, Improve SREB & Access Road, Install RW

Lighting

3-02-0189-002-1991

•
Apply dust palliative
Beacon
Brush Cutting
Construct a 1-bay Heated SREB with Floor
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dust Control
Electrical vault replacement
Grader
Grader, loader, snow plow attachments
Install ASOS or AWOS
Install VGSI (PAPI)
Loader
Minor Gravel Resurfacing
Napaskiak 2 Bay SRE Building X
New Lighted Cones
Place E-1 on runway crown and compact
Repair Rotating Beacon
Replace Electrical Lighting Vault and Transformer
Replace fuel tanks
Replace Primary Wind Cone Tip Down Mechanism
Replace Segmented Circle and Wind Cone Tower
Rwy 20 approach clearance
Snow Removal Equipment Building

NELSON LAGOON (OUL)

NPIAS: 02-0190

Runways: 08/26 - 4,003 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 381 Borough: Aleutians East Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

 USPS Hub:
 Yes
 School Facility:
 FY20 Ops Cost:
 \$20,688.45

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 06/15/2016

Airfield Manager: Hap Kremer, 907-532-5000 Hours of Operation: UNATNDD

Last Major Improvement: Improve SREB & Access Road, Expand Apron,

Rehabilitate RW 8/26 & RW Lighting, Acquire Land

3-02-0190-001-1996

Airport surface repairs
Construct a New 1-bay SREB
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Electrical vault replacement
Grade Taxiway, TSA, and Apron (M&O SPM)
Grader, loader, snow plow, motor grader
Grass Cutting
Install VGSI (PAPI)
Place E-1 on runway crown, shoulders, and RSA, and compact
Replace Airport Lighting
Replace threshold markers
Replacement runway lighting
Transformer replacement
Update ALP

NEW STUYAHOK (KNW)

NPIAS: 02-0193

Runways: 14/32 - 3,281 Surface: GRVL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,066 Borough: Dillingham Census Area

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$625.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$61,408.17Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:05/13/2019

Airfield Manager: Jon Taylor, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB & New Airport

3-02-0436-003-2006

Acquire Land	Х
Construct crosswind 04/22 runway (3,300' x 60')	
Construct Passenger Shelter	
Construct Tie-Downs	X
Construct Toilet Facilities	
Construct ultimate taxiway	
Drainage Maintenance & Repair	X
Dust Control	X
Expand the RSAs	
Expand the runway to 5,000' x 100'	
Grader	
Install NAVAIDs	X
Minor Gravel Resurfacing	X
Rehabilitate Apron	X
Rehabilitate Runway	X
Rehabilitate Surfaces	
Rehabilitate Taxiway	X
Replace Runway Lighting	X
Replace Taxiway Lighting	X
Transformer replacement	

Runways: 15/33 - 2,202 Surface: GRVL-P Lighting:

Classification: Community Off-Road CY18 Enplanements: 2,449 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$42,057.65Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/11/2016

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate TW, RW 15/33, & Apron

3-02-0194-005-2017

Construct 1,098' Runway Extension	Х
Construct 1-bay 1 heated SREB	X
Construct Passenger Shelter	
Construct Toilet Facilities	
Dust Control	
Grader	
Install VGSI (PAPI)	
Minor Gravel Resurfacing	
Newtok Airport Relocation - Stage 2	X
Replace 2 Wind Cones	
Segmented Circle	

Runways: 03/21 - 3,200 Surface: GRVL-DIRT-F Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 2,134 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$45,771.61Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/22/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 2/20, Expand Apron, Construct SREB

3-02-0195-001-2007

Acquire Additional Equipment
Airport master plan
Apply Dust Palliative
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Install ASOS or AWOS
Install VGSI (PAPI)
Miscellaneous SREB Cleanup
Rehabilitate Runway, Taxiway, and Apron X
Repair Sinking/Settling Runway End
Surface Rehabilitation

Runways: 05/23 - 4,001 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 23 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$55,372.36

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 09/27/2017

Airfield Manager: Steffen Strick, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW, Improve SREB, Rehabilitate RW

3-02-0357-001-2001

NPIAS: ---

Runways: 10/28 - 2,400 Surface: GRAVEL-G Lighting:

Classification: Local Non-NPIAS CY15 Enplanements: 0 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$1,756.90USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$659.64Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:08/12/2020

Airfield Manager: Sean Presley, 907-567-3463

Hours of Operation:

Last Major Improvement: None

Install Cones

UNATNDD

NEEDS:	In Project NEEDS:	In Project
Cone and Marker Repair / Replacement		
Dust Palliative		

Install Fence
Level Safety Area
Minor Gravel Resurfacing

Replace Segmented Circle and Repair Wind Sock

Runways: 01/19 - 3,992 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,673 Borough: Northwest Arctic Borough

 Air Carrier Hub:
 No
 Medical Facility:
 No
 FY20 Revenue:
 \$11,396.07

 USPS Hub:
 Yes
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$140,610.16

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 10/05/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 18/36, Expand Apron, Install RW

Lighting, Improve SREB 3-02-0198-002-1992

Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Expand RPZ	
Expand RSA	
Fuel Tank Upgrades	
Grader	
Install GPS Approach	
Loader	
Noatak Airport Relocation - Stage 1	Х
Noatak Airport Relocation - Stage 2	Х
Relocate Equipment building	
Remove existing road	
Remove existing storage building	
Repair SREB	
Replace Segmented Circle and Wind Cone Tower	
Snow Blower	
Update ALP	
Widen runway by 15'	

Surface: ASPH-G **Runways:** 03/21 - 6,176

10/28 - 6,009 ASPH-G Lighting: MED HIGH

Classification: Regional CY20 Enplanements: 21,261

Borough: Nome Census Area

Air Carrier Hub: Yes **Medical Facility:** FY20 Revenue: \$189,983.64 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$2,140,041.65

Part 139 Cert: Yes On/Off Road: Off **Last CIMP Inspection Date:** 07/11/2017

Hours of Operation:

ALL/ALL/0700-2100

Airfield Manager: Darrin Otton, 907-443-2500

Last Major Improvement:

Reconstruct 370' of RW 10/28 that has settled

unevenly

3-02-0199-028-2019

NEEDS:	In Project	NEEDS:	In Project
Acquire Land		Install 12' Fencing around ARFF Building	
Add Obstruction Light to Ravn Hangar		Install aircraft tie-downs	
Airport Operations Vehicle		Install Electronic Access Controls for airfield	
Apply Dust Palliative		Install More Fencing	
Apron reconstruction stage I		Master Plan Update	
Apron resurfacing phase II		Miscellaneous Building Repair	
Apron resurfacing phase III		Need Long-Range Plan for Compatible Uses for	Security and
Coastal Launch Program Site		Operational Issues	X
Construct drainage improvements and a new GA facility		Nome Airport Paving	
Construct Fencing		Pavement Markings	
Construct Full Parallel Taxiway		Prepare Land Use Plan and Property Acquisition	on
Construct gravel Runway 03L /21 R		Provide Additional Tie-Downs	
Construct new airport access road		Purchase EMAS Broom	
Construct New EEB		Purchase New 1,500 gal. ARFF Truck	X
Construct new GA runway		Reconstruct Runway 10/28 Subgrade Stage I	
Construct parallel taxiway		Reconstruct Runway 10/28 Subgrade Stage II	
Construct RSA 03/21		Reconstruct Runway 10/28 Subgrade Stage III	
Construct RSA 10/28		Rehabilitate 650,535 sq. ft. apron, taxiway and r pavement including Runway 10/28	runway
Construct Tie-Downs		Repave Runway 3/21	_
Construct vehicle access road and parking area		Replace Existing Loader	
Crack sealing and ponding repairs		Replace Runway 10-28 Lighting	
De-icing Fluids Storage/Treatment study/design		Replace tow behind broom	_
Expand GA Runway stage II		Restripe 10/28 Runway	
Extend Runway 10/28		Restripe RW 3/21 Markings	
Fence perimeter of airfield and Perimeter Roads		Runway 10/28 increase pavement strength	
Identify additional lease lots		Runway Light Cleaning Plow	
Increase pavement strength to accommodate larger aircr	raft		

NOME (OME) NPIAS: 02-0199

Shorten RW, RSA, ROFA, and ROFZ, lengthen RSA beyond RW ends and RPZ (21L) and RW 03/21L $\,$

Taxiway D & F Grading

Taxiway G Crack Seal

NPIAS: ---

Surface: GRVL-G Lighting: **Runways:** 03/21 - 1,950

Classification: Local Non-NPIAS No Enplanements: Borough: Nome Census Area

Air Carrier Hub: No **Medical Facility:** Yes FY20 Revenue: \$10,233.51 USPS Hub: No School Facility: PK - 12 FY20 Ops Cost: \$3,317.40

Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:**

Hours of Operation: Airfield Manager: Darrin Otton, 907-443-2500 **UNATNDD**

Last Major Improvement: None

NEEDS:	In Project NEEDS:	In Project
Brush Cutting		

Dahl Creek Airport improvements Dahl Creek Airport Lease Lot Development Install aircraft tie-downs Install Fencing Relevel or replace wind cone tower and sock Replace Cones Replace Segmented Circle Survey and Develop more lease lots Survey and Expand Apron Update ALP

NONDALTON (5NN)

NPIAS: 02-0432

Runways: 02/20 - 2,800 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 853 Borough: Lake and Peninsula Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$37,556.17

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 11/13/2017

Airfield Manager: Clint Anelon, 907-571-1261

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0432-002-2003

NEEDS: In Project NEEDS: In Project

Apply Dust Palliative

Construct 500' Runway Extension

Construct Passenger Shelter

Construct Toilet Facilities

Excavate Area North of RW 2/20 and 9/27 Intersection to meet Line of Sight Standards

Provide Fence Access as Needed

Remove Brush

Repair Damaged Lighting

Replace a 1-Bay SREB

Update ALP

Runways: 05/23 - 5,100 **Surface:** ASPH-G **Lighting:** MED

Classification: Community On-Road CY16 Enplanements: 3 Borough: Southeast Fairbanks Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$7,667.38

 USPS Hub:
 No
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$84,640.39

 Part 139 Cert:
 No
 On/Off Road:
 On
 Last CIMP Inspection Date:
 10/06/2016

Airfield Manager: Sam Jennings, 907-883-5129

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0203-003-1993

NEEDS: In Project NEEDS: In Project

Apply dust palliative

Construct Passenger Shelter

Crack Sealing

Lighting Repairs

RSA Grading on Southside of Runway

SREB Repairs

Runways: 03/21 - 4,011 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 691 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$250.00

USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$103,321.41

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 03/26/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, Rehabilitate Apron, Access Road

& RW 2/20

3-02-0204-004-2010

Apply Dust Palliative	
Compactor	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Grader	
Install AWOS (Various)	X
Install VGSI (PAPI)	
Lighted Supplemental Wind Cone	
Rehab Apron	
Rehab Runway	
Rehab Taxiway	
Survey, Clear Obstructions & Mark Property Boundary	
Wx Reporting Needed	

NUNAM IQUA (SXP)

Runways: 01/19 - 3,015

Air Carrier Hub: No

USPS Hub: No

Part 139 Cert: No

09W/27W - 15,000

18W/36W - 15,000

Classification: Community Off-Road

WATER

WATER

Surface: GRAVEL-F

CY20 Enplanements: 315

Medical Facility:

School Facility: K-12

On/Off Road: Off

FY20 Ops Cost: **Last CIMP Inspection Date:**

FY18 Revenue:

Hours of Operation:

MED

Kusilvak Census Area

NPIAS: 02-0262

\$0.00

\$69,699.35

09/29/2014

Lighting:

Borough:

UNATNDD

Airfield Manager: John Wilson, 907-624-3261

Last Major Improvement: Extend RW 2/20, Construct TW & Apron

3-02-0262-003-1999

Access Road and Causeway Construction	
Apply Dust Palliative	_
Brush Cutter	_
Brush Cutting	_
Construct 985' Runway Extension	_
Construct Passenger Shelter	_
Construct Tie-Downs	_
Construct Toilet Facilities	_
Install ASOS or AWOS	_
Install VGSI (PAPI)	_
new ULSD tank	_
Nunam Iqua Airport Improvements	(
Regrade, recover D-1 and re-establish crown on runway	_
Repair/ Replace secondary wind come tower	_
Repair/Replace Light Can Bases as Needed	_
Update ALP	_
Widen and Extend Runway	_

NUNAPITCHUK (16A)

Runways: 18/36 - 2,420

NE/SW - 3,000

Surface: GRVL-DIRT-G

WATER

Lighting: MED

Classification: Community Off-Road

CY18 Enplanements: 3,443

Borough: Be

Bethel Census Area

NPIAS: 02-0446

Air Carrier Hub: No

Medical Facility:

FY18 Revenue:

\$0.00

USPS Hub: Yes

School Facility: PK - 12

FY20 Ops Cost:

\$34,470.77

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

08/08/2016

Airfield Manager:

Last Major Improvement:

Joe Laraux, 907-453-2495

Hours of Operation: UNATNDD

Extend RW 18/36, Construct SREB

3-02-0446-001-2007

Airport Access Road Improvements	
Apply Dust Palliative	X
Construct 2 each 24' x 48' SREB (1 heated/1 unheated)	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Installed 2 fuel storage tanks on the aviation support area	
New RW & TW Lighting	X
Reconstruct SREB & Mitigate Tank Spill	
Rehabilitate Runway	X
Widen Runway Safety Area	

OLD HARBOR (6R7)

NPIAS: 02-0421

Runways: 03/21 - 2,750 **Surface:** GRAVEL-P **Lighting:**

Classification: Community Off-Road CY18 Enplanements: 2,163 Borough: Kodiak Island Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$1,196.84USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$14,448.50Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/11/2016

Airfield Manager: Phil Smith, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Construct RW 2/20, Improve SREB & Access

Road, Construct TW & Apron 3-02-0421-001-1992

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Add a GPS Approach
Apply Dust Palliative
Brush cutting (M&O OR)
clean/organize SREB
Construct 550' Runway Extension
Construct a New 1-Bay SREB
Construct Passenger Shelter
Construct Toilet Facilities
Extend Power and Light Runway
Grader and Loader
Install ASOS or AWOS
Install MIRL Runway Lighting
Install Perimeter Fence
Install VGSI (PAPI)
Reestablish Runway Crown and Compact Surface
Remove ROFA Obstructions
Replace and Realign Runway Cones
Replace Surface Course
Replace Windsock
Resurface Runway
SREB Repairs
Widen the runway to 75'

OPHIR (Z17) NPIAS: 02-0209

Runways: 11/29 - 1,940 **Surface:** GRVL-DIRT-P **Lighting:**

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: No School Facility: FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/23/2016

Airfield Manager: Steffen Strick, 907-524-3241

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Gravel surfacing

Windsock Replacement

Runways: 08/26 - 3,300 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 1,347 Borough: Kodiak Island Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$44,031.01Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/10/2016

Airfield Manager: Phil Smith, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport 3-02-0480-002-2011

3-02-0480-002-2011

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dust control (M&O SPM)
Emergency eye wash station
Grader, loader, snow removal attachments
Install Perimeter Fence
Install VGSI (PAPI)
Relocate wind cone
Replace cone bands
supplemental Wind Cone evaluation
Tree Removal

Runways: 09/27 - 3,002 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 122 Borough: Lake and Peninsula Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

 USPS Hub:
 Yes
 School Facility:
 FY20 Ops Cost:
 \$56,869.27

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 11/13/2017

Airfield Manager: Clint Anelon, 907-571-1261 Hours of Operation: UNATNDD

Last Major Improvement: Rehabilitate & Extend RW 9/27, Install RW

Lighting, Acquire Land 3-02-0215-003-1986

Aeronautical Survey and Remove Part 77 Penetrations
Airport Perimeter Fence X
Apply Dust Palliative
Clean/organize SREB
Clear Vegetation in Runway Safety Areas, and Segmented Circle
Conduct Master Plan
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Install Concrete Parking Pads on Apron
Install External Speakers on Equipment
Install VASI and PAPI
Install VGSI (PAPI)
Loader and Blower
Purchase fire extinguishers/emergency eye wash station
Regrade Safety Areas
Rehabilitate RWY surface X
Removal of Debris at Runway End
Remove Old Threshold Panels
Repair Shoulder Erosion on Taxiways and Ramp
Repair SRE Building
Repair/replace light lenses
Replace Runway Edge Cones
Replace/Repair 1-bay SREB
Visual Aid Repair

Runways: 02/20 - 3,300 Surface: GRAVEL-P Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 163 Borough: Lake and Peninsula Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

 USPS Hub:
 Yes
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$20,912.62

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 07/25/2019

Airfield Manager: Floyd Wilson, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, RW, & Apron, Modify Access

Road

3-02-0218-001-2005

Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Grader	
Gravel resurfacing	
Install AWOS (Various)	
RWY resurface & dust palliative	Х
Visual aid replacement	

PETERSBURG JAMES A JOHNSON (PSG)

Runways: 05/23 - 6,400 Surface: ASPH-G Lighting: HIGH

Classification: Regional CY20 Enplanements: 8,073 Borough: Petersburg Borough

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$72,872.03USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$415,762.97Part 139 Cert:YesOn/Off Road:OffLast CIMP Inspection Date:08/04/2014

Airfield Manager: Barry Youngberg, 907-772-4624 Hours of Operation:

Last Major Improvement: Add/replace perimeter fencing, gates, and gate APR-SEP/SAT-SUN/0830-1630

controllers

3-02-0219-017-2019

OCT-MAR/ALL/0500-1600

APR-SEP/MON-FRI/0600-1630

NPIAS: 02-0340

NEEDS:	In Project NEEDS:	In Proje
Apron and Taxiway Rehab	Х	
Construct Full Parallel Taxiway	X	
Construct Tie-Downs		
Construct Toilet Facilities		
fuel tank signage/security upgrades		
Grader		
Mill and pave old portion of Apron		
wildlife attractant reduction		

PILOT POINT (PNP)

NPIAS: 02-0222

Runways: 07/25 - 3,280 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 345 Borough: Lake and Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,471.60USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$36,802.42Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/25/2019

Airfield Manager: Floyd Wilson, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB

3-02-0222-002-2003

NEEDS:	In Project NEEDS:	In Project

Apply Dust Palliative

Construct 49' taxiway

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

Expand apron

Expand the RSAs

Expand the runway to 5,050' x 100'

Extend existing access road

Repair SREB

RSA edges repair

Visual aid replacement

PILOT STATION (0AK)

NPIAS: 02-0223

Runways: 04/22 - 4,000 **Surface:** GRVL-DIRT-P **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 3,016 Borough: Kusilvak Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$149,618.25USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$109,238.13Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: Erik Weingarth, 907-438-2416

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport

3-02-0477-002-2017

In Project NEEDS:	In Project
	In Project NEEDS:

Apply Dust Palliative
Construct 1,459' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Expand Ramp
Grader, loader wheel, snow plow, snow removal attachments
Install ASOS or AWOS
Install ULSD Tank
Install VGSI (PAPI)
Loader
Reclaim and Resurface Runway and Safety Area
Relocate Airport
Remove/Replace Threshold Panels
Replace Segmented Circle
Replace SRE Building
Replace Threshold Markers
Resurface Runway
Update ALP

In Project

Runways: 14/32 - 5,000 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 115 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$573.38USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$52,353.15Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/18/2017

In Project NEEDS:

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB, RW, TW, & Apron

NEEDS:

3-02-0224-002-2-2009

Apply Dust Palliative
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Determine if Wildlife Hazard Program is Needed
Develop lease lots
Loader
Miscellaneous SREB Cleanup
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Replace runway lighting
Replace taxiway lighting

Runways: N/S - 4,000 Surface: WATER Lighting:

Classification: Local NPIAS Lower CY20 Enplanements: 9 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,600.00USPS Hub:NoSchool Facility:PK - 12FY18 Ops Cost:\$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Gray, 907-465-4512

Hours of Operation:
DALGT

Last Major Improvement: Acquire Land, Construct Apron

3-02-0423-001-1994

POINT HOPE (PHO)

NPIAS: 02-0226

Runways: 01/19 - 3,992 **Surface:** ASPH-F **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 1,487 Borough: North Slope Borough

Air Carrier Hub:NoMedical Facility:NoFY19 Revenue:\$1,250.71USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$179,275.82Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/05/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB 3-02-0226-003-2000

	-,
Coastal Launch Program Site	
Construct access road	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
crack sealing	
Expand TSA	
Float Rehabilitation	
Fuel Tank Upgrade	
Increase the RSA to meet the current design standards.	
Pavement maintenance and marking repairs	
Pavement Markings	
Point Hope Airport Runway Realignment	X
Realign Runway - Stage 2	X
Realign the runway and increase the length by 8 feet to 4,000 feet.	
Rehabilitate Runway Pavement	
Replace Segmented Circle	
Replace Threshold Markers	
SREB Maintenance	
Update ALP	
Widen taxiway	

Runways: N/S - 3,000 Surface: WATER Lighting:

Classification: Community Off-Road CY18 Enplanements: 15 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No Medical Facility: No FY17 Revenue: \$0.00 USPS Hub: Yes School Facility: PK - 12 FY17 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Gray, 907-465-4512

Hours of Operation:
UNATNDD

Last Major Improvement:

PORT GRAHAM (PGM)

NPIAS: 02-0233

Runways: 12/30 - 1,975 **Surface:** GRVL-DIRT-F **Lighting:**

Classification: Community Off-Road CY20 Enplanements: 829 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$23,392.17

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/27/2016

Airfield Manager: Kevin Jones, 907-235-5217

Hours of Operation:
UNATNDD

Last Major Improvement: None

	-
Airport brushing	
Airport relocation	
Construct Passenger Shelter	
Construct Toilet Facilities	
Drainage Maintenance & Repair	
Grader	
improve drainage around SREB /abandoned vehicle removal	_
Install ASOS or AWOS	
Install AWOS or ASOS	
Install MIRL Runway Lighting	
Nanwalek/Port Graham Airport Relocation - Stage 1	X
Nanwalek/Port Graham Airport Relocation - Stage 2	X
Nanwalek/Port Graham Airport Relocation - Stage 3	X
Obstruction Removal	
Regrade Runway and Safety Areas	
Replace and re-establish runway marking cones	
Replace Wind Cone Tower	
Runway resurfacing	
-	

PORT HEIDEN (PTH)

Runways: 06/24 - 5,000

Surface: GRAVEL-F

GRAVEL-F

Lighting: MED MED

14/32 - 4,000

Classification: Community Off-Road

CY20 Enplanements: 105

Borough: Lake and Peninsula Borough

Air Carrier Hub: No

Medical Facility: N

FY20 Revenue:

\$21,850.67

NPIAS: 02-0234

USPS Hub: Yes

On/Off Road: Off

i izu itevellue.

\$107,200.22

Part 139 Cert: No

School Facility: PK - 12

FY20 Ops Cost:
Last CIMP Inspection Date:

07/25/2019

Airfield Manager:

Floyd Wilson, 907-246-3325

Hours of Operation:

UNATNDD

Last Major Improvement: R

Rehabilitate RW 5/23 & 13/31, Construct RSAs

3-02-0234-004-2003

NEEDS: In Project NEEDS: In Project

Airport has known contamination issues from DOD activities from WWII.

Clear brush

Construct additional lease lots

Construct Passenger Shelter

Construct Tie-Downs

Construct Toilet Facilities

General shop maintenance

Grader

Gravel resurface and dust palliative

Loader Wheel and Aviation Radio

Replace secondary wind cone

Snow blower

SREB floor drains

Update ALP

PORT LIONS (ORI)

NPIAS: 02-0235

Runways: 07/25 - 2,200 **Surface:** GRAVEL-G **Lighting:** MED

Classification: Community Off-Road CY20 Enplanements: 837 Borough: Kodiak Island Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$33,619.89Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/10/2016

Airfield Manager: Phil Smith, 907-487-4952

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW Lighting 7/25 Regulator Building

3-02-0235-004-2011

	-,
Brush cutting (M&O OR)	
Construct Passenger Shelter	
Construct Toilet Facilities	
Dust control (M&O SPM)	
Expand RPZ	
Grader and Loader	
Install New Lighting System, Rotating Beacon and Wind Cones	X
Install Perimeter Fence	
Install VGSI (PAPI)	X
Land acquisition (5 parcels)	
Obliterate old access road	X
Obstruction removal	
Realign and Extend Runway	X
Reconstruct or relocate airport access road	X
Remove 20:1 ground penetrations and tree obstructions on RWY 7 approach	
Repair/replace runway lights.	X
replace segmented circle	
Replace threshold cones with updated markers	X
Resurface Runway	
SREB	X
Update ALP	

PORT PROTECTION (19P)

NPIAS: 02-0448

UNATNDD

Runways: NW/SE - 4,000 Surface: WATER Lighting:

Classification: Community Off-Road CY18 Enplanements: 52 Borough: Prince of Wales-Hyder Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00 USPS Hub: No School Facility: PK - 12 FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Gray, 907-465-4512

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Conduct Master Plan

Port Protection Seaplane Float Replacement X

PORTAGE CREEK (A14)

Runways: 10/28 - 1,920

01/19 - 1,470

Surface: GRVL-DIRT-F

GRVL-DIRT-G

Lighting:

Classification: Local NPIAS Lower

No Enplanements:

Borough:

Dillingham Census Area

Air Carrier Hub: No

Medical Facility: No FY18 Revenue:

\$0.00

NPIAS: 02-0348

USPS Hub: No

School Facility:

FY20 Ops Cost:

\$14,882.78

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

Hours of Operation: UNATNDD

Airfield Manager:

Last Major Improvement:

Jon Taylor, 907-842-5511

Rehabilitate RW 1/19, TW & Apron, Construct RW

9/27, Improve SREB, Remove Obstructions

3-02-0348-001-1984

NEEDS: In Project NEEDS: In Project

Grader Loader Minor Gravel Resurfacing **Obstruction Removal** Renew MLT Airport Lease Repair Erosion on Both Runway Edges

Runways: 01/19 - 4,968 Surface: GRVL-G Lighting: MED

Classification: Local NPIAS Lower CY20 Enplanements: 99 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: No School Facility: None FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Last CIMP Inspection Date:

Airfield Manager: Jeff Russell, 907-451-2207

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Obstruction removal (O+M Operating)

NPIAS: ---

Runways: 04/22 - 2,200 **Surface:** GRVL-DIRT-G **Lighting:**

Classification: Local Non-NPIAS CY18 Enplanements: 2 Borough: Kenai Peninsula Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00 USPS Hub: No School Facility: KG-12 FY20 Ops Cost: \$2,354.46

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date: 09/23/2020

Airfield Manager: Rob Smith, 907-595-1262

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Additional tie-downs

Brush Cutting/Tree removal

E-1 Lift

Wildlife Plan and Install Fence

QUARTZ CREEK /KOUGAROK/ (5QC)

NPIAS: ---

Runways: 12/30 - 2,960 **Surface:** GRVL-DIRT-G **Lighting:**

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$962.36USPS Hub:NoSchool Facility:FY18 Ops Cost:\$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 07/12/2017

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Apply Dust Palliative

Replace Faded Cones/Markers

Verify Sublease Situtation

Wildlife Mitigation

RALPH M CALHOUN MEMORIAL (TAL)

NPIAS: 02-0290

Runways: 07/25 - 4,400 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 756 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,457.29USPS Hub:NoSchool Facility:K - 12FY20 Ops Cost:\$101,443.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 06/25/2014

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 7/25, Construct SREB, Extend

RSA, Expand Apron 3-02-0290-002-2004

NEEDS: In Project NEEDS: In Project

Construct Passenger Shelter

Construct Tie-Downs

Dust Pallative
install a light on Beacon tower

Install external speaker on equipment

Loader

Purchas a portable eye wash station

Replace Fuel Storage Tank and Enhance Security Measures

Snow Blower, Grader and Loader Wheel

Supplemental Wind Cone

Survey, Clear obstructions and Mark Property Boundary

RALPH WIEN MEMORIAL (OTZ)

NPIAS: 02-0160

Runways: 09/27 - 6,300 Surface: ASPH-G Lighting: HIGH

18/36 - 3,876 GRVL-F MED

Classification: Regional CY20 Enplanements: 21,504 Borough: Northwest Arctic Borough

Air Carrier Hub: Yes Medical Facility: Yes FY20 Revenue: \$146,940.59
USPS Hub: No School Facility: PK - 12 FY20 Ops Cost: \$1,823,028.96

Part 139 Cert: Yes On/Off Road: Off Last CIMP Inspection Date: 07/28/2016

Airfield Manager: Alvin Werneke, 907-442-3147

Last Major Improvement: Construct TW to NE Apron, Expand GA Apron

ALL/WED-MON/0600-2000

ALL/TUE/0600-2100

3-02-0160-021-2016

Equipment Engine Repairs

Hook Up SSB Deicing Tank for Use

Kotzebue Airport Security Upgrades

Purchase Bobcat & Landscape Trailer

Purchase New 1,500 gal. ARFF Truck

Main Runway & TW Drainage
Pave Short Term Parking Area

Pavement Markings

Rehab apron

Kotzebue Airport Apron Expansion Stage 1
Kotzebue Airport Apron Expansion Stage 2

Kotzebue Airport Crosswind Runway Improvements

Handicap Pass Loader

Install Equipment Radios

Loader

NEEDS:	In Project	NEEDS:	In Project
Airport Operations Vehicle (NON-AIP)		Rehab taxi lanes A, B, D & E	Х
Apply Dust Palliative		Repair Apron Cracking & Ponding	X
Blower (7,500 ton per hour)		Repair Wind Sock & Segmented Circle	
Coastal Launch Program Site		Replace lighting	X
Cold Storage Building Rehabilitation		Replace Pavement Markings	
Construct Full Parallel Taxiway		Resurface Runway 18/36, taxiways and the GA Apron	
Construct Perimeter Fence & Repair Gates		Runway Light Cleaning Plow	
Create Airport Parking Plan		Seasonal Pavement Marking Painting	
Culvert Replacements, Lighting System, Fence/Gate Repairs,		Shift taxilane south	X
Striping, Signage, and Storm Drainage		SREB Rehabilitation	
Deicer Truck		Towed Broom 22'+ Width	
Dozer			

Χ

Χ

Χ

Runways: 11/29 - 3,520 Surface: GRAVEL-G Lighting: MED

Classification: Local NPIAS Lower CY20 Enplanements: 119 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: Yes School Facility: FY20 Ops Cost: \$115,697.26

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Expand Apron, Rehabilitate RW

3-02-0244-003-2-2001

NEEDS: In Project NEEDS: In Project

Compactor Grader

Lighted Supplemental Wind Cone

Loader

PAPI, WX Reporting & WX Cameras Needed

Rehabilitate airport for all-season operations, including runway surface repairs and vegetation clearing.

SRE Building Replacement

Survey, Clear Obstructions and Mark Property Boundary

Runways: 10/28 - 4,820 Surface: GRVL-F Lighting:

Classification: Local NPIAS High CY20 Enplanements: 26 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$969.53USPS Hub:YesSchool Facility:FY20 Ops Cost:\$53,164.96Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/19/2018

Airfield Manager: Ricky Ciletti, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: Remove Obstructions, Construct SREB

3-02-0246-001-2005

NEEDS:

In Project NEEDS: In Project

Construct a new taxiway and apron
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dozer
Dust Control
External Directional speakers for equipment
Grader
Install ASOS or AWOS
Install MIRL Runway Lighting
Install VGSI (PAPI)
Obstruction Removal
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Timers for lighting
Update ALP

ROBERT/BOB/CURTIS MEMORIAL (D76)

NPIAS: 02-0201

Runways: 06/24 - 4,000 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 4,584 Borough: Northwest Arctic Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$73,670.47Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/06/2015

Airfield Manager: Alvin Werneke, 907-442-3147 Hours of Operation: UNATNDD

Last Major Improvement: Construct New Airport

3-02-0201-004-2001

NELDO.	iii Projec
Construct access road	
Construct Lease area	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Expand RSA, ROFA, & ROFZ	
Extend Runway	
Install one or two apron concrete parking pads	
Install RCO	
Lighted Supplemental Wind Cone and Segmented Circle	:
new lighted wind cone	
Noorvik Airport Rehabilitation	X
Noorvik SRE Building Replacement	
papi Repair	
Repair/Replace Overhead Doors	
Replace Fire Extinguisher	
Shoulder/slope repairs	
Update ALP	

Runways: 03/21 - 4,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 603 Borough: Yukon-Koyukuk Census Area

 Air Carrier Hub:
 No
 Medical Facility:
 No
 FY19 Revenue:
 \$1,125.00

 USPS Hub:
 Yes
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$118,212.59

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 06/25/2015

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 3/31, Expand Apron, Install RW

Lighting, Rehabilitate TW 3-02-0248-001-1992

Apply Dust Palliative	
Brush Cutter	
Clean up SREB interior and exterior	
Clear Vegetation Around Airport	
Compactor	
Construct a SREB	X
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Fuel Tank Upgrade	
Install PAPI and AWOS	
Install Supplemental Wind Cone	
Purchase compactor attachment	
Reconstruct Runway	X
Regrade Runway and Safety Areas	
Rehabilitate SRE Building	
Relocate Road, Improve Approach, and Protect Safety Areas	X
Remove Unknown Barrels	
Resurface Runway	
Re-Surface Runway, Apron and Taxiway, Apply Dust Palliative, and Upgrade Airport Lighting System	X
Update ALP	

RUSSIAN MISSION (RSH)

In Project NEEDS:

Runways: 18/36 - 3,620

18W/36W - 3,000

Surface: GRAVEL-G

WATER

Lighting: MED

Borough:

Classification: Community Off-Road

CY20 Enplanements: 596

Air Carrier Hub: No

Medical Facility:

FY18 Revenue:

USPS Hub: Yes

School Facility: PK - 12

FY20 Ops Cost: \$106,677.96

Kusilvak Census Area

Part 139 Cert: No

On/Off Road: Off

Hours of Operation:

09/29/2014

\$0.00

In Project

NPIAS: 02-0249

Airfield Manager:

NEEDS:

Last Major Improvement:

Erik Weingarth, 907-438-2416

UNATNDD

Last CIMP Inspection Date:

Improve SREB, Construct RW 17/35

3-02-0249-001-2000

20:1 Clearance
Aeronautical Survey
Apply Dust Palliative
Brush Cutting
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dozer
Fire extinguisher and emergency eyewash station replacement
Grader
Grader and Loader
Obstruction Removal
Rehab Apron
Rehab Runway
Rehabilitate Taxiway
Repair/Renovate SRE Building & Replace Overhead Doors
Repair/Replace PAPI
Replace ULSD Tanks
Replace Windsock Tower
Survey for approach clearance
Update ALP

SALMON LAKE (Z81)

NPIAS: ---

Runways: 15/33 - 2,000 Surface: GRAVEL-G Lighting:

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:FY18 Ops Cost:\$0.00Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/12/2017

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: None

NEEDS:

In Project NEEDS: In Project

Dust Palliative
Install aircraft tie-downs
Install Segmented Circle
Install Updated Threshold Markers
Obtain wind data (crosswind runway needed?)
Relocate Threshold to 1860'
Remove Part 77 obstructions
Remove Road that Provides Direct Access
Replace Cones
Resurface runway, apron and taxiway
Revise ALP for Safety Areas and Ultimate Plan
Signage For "No Admittance"
Surface Safety Areas
Wildlife Hazards

SAND POINT (SDP)

NPIAS: 02-0253

Runways: 14/32 - 5,213 Surface: ASPH-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 341 Borough: Aleutians East Borough

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$24,020.99USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$542,207.69

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 11/19/2019

Airfield Manager: Hap Kremer, 907-532-5000

JAN - DEC/SUN-SAT/0800-1600

Last Major Improvement: Extend RSA 13/31 3-02-0253-010-2005

0-02-0230-010-2000

NEEDS:	In Project	NEEDS:	In Projec
ARFF Vehicle		Repair ponding areas in apron	
BROOM RUNWAY TOWED		RW Rehab and Extension; RSA Embankment at	nd Shore
Construct a New 2-Bay SRE/ARFF Building		Protection (Phase 1)	
Construct New Heated Sand Storage Building		RW Rehab and Extension; Widen/Extend RSA, Roads; Replace RW Lighting	Pave Access
Construct Tie-Downs		Sander	
Construct Toilet Facilities		Snow Blower	
Demo existing Sand Storage Building and construct ne Sand Storage and SRE/ARFF buildings	W	SREB Addition	
Demolish existing sand storage building and attach freight office build		Update ALP	
		Utility Wagon	
Grader		Vehicle gates with push button electric	_
			_

Widen and extend RSA

Loader

Loader wheel and Snow Blower

Installation of FAA weather cameras

Maintain pavement markings and crack seal

Install water and sewer for SRE/ARFF building

Minor Pavement Repairs

Part 139 Certification

Perimeter fencing repairs/replacement X

Place a fabric type barrier on riprap on the bayside to prevent

rock topping runway

Preventative maintenance on 542,900 sq. ft. apron/taxiway pavement

Preventative Maintenance on 788,850 sq. ft. runway pavement

Re-Grade Runway Surface

Remove Part 77 obstructions from bluffs east of runway

Repaint all airport markings Layout and repair pavement markings on runway, taxiways and apron.

Runways: 05/23 - 4,400 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,464 Borough: Nome Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$124,380.32

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: Rehabilitate RW 5/23 & Lighting

3-02-0254-005-2009

Coastal Launch Program Site
Construct Passenger Shelter
Construct taxiway
Construct Tie-Downs
Construct Toilet Facilities
Expand apron
Expand RPZ
Expand RSA
Improve GPS Approach
Install Lighted Windsock with Segmented Circle
Install PAPI
Savoonga runway repairs
Snow Blower Attachment
Upgrade Building Lighting and Siding

SCAMMON BAY (SCM)

NPIAS: 02-0255

In Project

Surface: DIRT-G Lighting: **Runways:** 10/28 - 3,001 MED

Classification: Community Off-Road CY20 Enplanements: 1,304 Borough: Kusilvak Census Area

Air Carrier Hub: No **Medical Facility:** FY18 Revenue: \$0.00 USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$43,780.85 Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 08/16/2017

In Project NEEDS:

Hours of Operation: Airfield Manager: LJ Davis, 907-543-2498 **UNATNDD**

Last Major Improvement: Construct SREB 3-02-0255-002-2003

NEEDS:

	•
Acquire Parcel 4 (East RW End)	
Construct 299' Runway Extension	
Construct a New 1-Bay SREB	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Elevate Runway	
Elevate Runway, Taxiway, Apron and Access Road	X
Install NAVAIDS	
Lighting upgrades	
Loader	
Minor Gravel Resurfacing	
Miscellaneous SREB Cleanup	
Repair Erosion Issues (FEMA)	
Update ALP	
Upgrade Runway Lighting	
Visual Aids	

SELAWIK (WLK)

Surface: GRAVEL-G **Runways:** 04/22 - 3,002

NEEDS:

09/27 - 2,659 **GRAVEL-G** Lighting: MED MED

Borough:

Classification: Community Off-Road CY20 Enplanements:

1,732

Air Carrier Hub: No **Medical Facility:** FY18 Revenue: \$0.00

USPS Hub: Yes School Facility: PK - 12 FY20 Ops Cost: \$97,122.98 Part 139 Cert: No On/Off Road: Off **Last CIMP Inspection Date:** 10/06/2015

In Project NEEDS:

Hours of Operation: Airfield Manager: Alvin Werneke, 907-442-3147 **UNATNDD**

Last Major Improvement: Improve RSA 3/21, Install RW VGS & Lighting,

Rehabilitated Apron 9/27 3-02-0256-003-19-1998

Northwest Arctic Borough

NPIAS: 02-0256

In Project

Acquire Land RW 3/21 RPZ	
Apply Dust Palliative	
Brush Cutting	
Conduct Airport Master Plan Update	X
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Extend Runway 4/22 to 4,000'	X
Install PAPI on west 3/21 & 9-27	
New BRL (ALP)	
Rehab Apron	
Rehab Rwy 4-22	
Rehab Rwy 9-27	
Rehab Taxiway	
Repair existing 48" culvert	
Repair/Replace Wind Cone Tower	
Reshape and Re-establish Crown	X
Selawik SRE Building Upgrade	
Update ALP	
Widen RSA for both runways	
Widen TSA and TOFA	

Runways: 16/34 - 1,845 Surface: GRAVEL-G Lighting:

Classification: Community Off-Road CY20 Enplanements: 1,950 Borough: Kenai Peninsula Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$14,824.21USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$60,889.47Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:06/26/2015

Airfield Manager: Tyler Tucker, 907-234-7818

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0258-004-2009

Construct Paved Access Road and Sidewalk
Construct Taxiway
Construct Tie-Downs
Expand Alpha Apron
Expand aviation support area lots
Extend taxiway
Install VGSI (PAPI)
Obstruction Removal
Remove Brush in OFA
Remove Part 77 Encroachments
Replace threshold markers
Replace Wind Sock
Resolve Airport Boundary

SEWARD (SWD)

Runways: 13/31 - 4,249

16/34 - 2,289

Surface: ASPH-G

ASPH-G

Lighting: MED

USPS Hub: Yes

Air Carrier Hub: No

Classification: Community On-Road

CY20 Enplanements: 12

Medical Facility:

School Facility: PK - 12

Part 139 Cert: No On/Off Road: On Borough: Kenai Peninsula Borough

FY20 Revenue:

\$27,828.24

FY20 Ops Cost:

\$42,680.99

NPIAS: 02-0259

Last CIMP Inspection Date:

05/29/2019

In Project

Hours of Operation:

UNATNDD

Airfield Manager: Jason Lange, 907-288-2428

Last Major Improvement: Improve Airport Drainage

3-02-0259-003-1995

NEEDS:	In Project	NEEDS:
Acquire RPZ and address compatible land use	Х	
Airfield lighting repairs and security signage		
Clear Vegetation Around Airport		
Coastal Launch Program Site		
Construct a Helipad	X	
Construct New Regulator Building		
Construct Runway 16/34	X	
Construct Tie-Downs	X	
Construct Toilet Facilities		
Crack Seal		
Drainage work	X	
Dump Truck w/Sander		
Install Runway Direction Signs at Runway Ends		
Install Runway Lighting and New EEB	X	
Land Acquisition	X	
Master Plan Update		
Painting All Airport Markings	X	
Pavement Markings	X	
Removal of Trees in the Approach Path	X	
Repave Apron	X	
Replace threshold markers		
Replace Wind Sock	X	
Runway 12/30 Reconstruction		
Seward SREB and Sand Storage Building	X	
Shift Runway	X	

SHAGELUK (SHX)

Runways: 16/34 - 3,400

18W/36W - 5,000

Surface: GRVL-DIRT-G

WATER

Lighting: MED

Classification: Community Off-Road

Relocate Beacon Off of Building
Repair/Renovate SRE Building

Repair/Replace Segmented Circle

Replace Cones

Replace SRE Building

Roadway Reconstruction

Resurface Runway

Update ALP

CY20 Enplanements: 124

Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No

No Medical Facility:

FY18 Revenue: \$0.00

NPIAS: 02-0370

In Project

USPS Hub: Yes

School Facility: PK - 12

FY20 Ops Cost: \$136,749.94

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date: 09/29/2014

Airfield Manager: Erik Weingarth, 907-438-2416

Hours of Operation:

Last Major Improvement: Extend RW 16/34 & Improve SREB

3-02-0370-002-2000

UNATNDD

NEEDS:	In Project	NEEDS:
20:1 Clearance on 16 Approach		
Access road erosion repair		
Aeronautical Survey		
Apply Dust Palliative		
Clear Vegetation Around Airport		
Construct Passenger Shelter		
Construct Tie-Downs		
Construct Toilet Facilities		
Dozer		
Grader		
Install ULSD Tank		
Loader		
Raise Runway Embankment		
Reclaim Airport Material		

SHAKTOOLIK (2C7)

NPIAS: 02-0401

Runways: 15/33 - 4,001 Surface: GRVL-F Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 2,659 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$62,060.67Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport

3-02-0401-001-1998

Apply Dust Palliative	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Install Erosion Control	X
Install Lighted Windsock	
Install PAPIs	
Install ULSD Tank	
Reclaim and Resurface Runway	
Relocate Beacon	
Relocate Segmented Circle	
Relocate segmented circle & install new wind cones	X
Remove vegetation in and around lights.	
Repair/Renovate SRE Building	
Replace Runway Edge Cones	
Replace Wind Cone Tower	
resurface and apply dust palliative	X
Update ALP	
Upgrade lighting & electrical	X

SHEEP MOUNTAIN (SMU)

NPIAS: - - -

Runways: 05/23 - 2,270 **Surface:** GRVL-DIRT-P **Lighting:**

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Matanuska-Susitna Borough

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$440.00USPS Hub:NoSchool Facility:FY19 Ops Cost:\$28,446.26

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/30/2016

Airfield Manager: Andy Weiland, 907-745-5116

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

CASC

Cone and Marker Repair / Replacement

Construct Parking Apron

Improve Drainage

Install Perimeter Fence

Level the Runway

SHISHMAREF (SHH)

NPIAS: 02-0404

Runways: 05/23 - 4,997 Surface: ASPH-P Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,144 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$3,639.76USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$155,887.55Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/08/2015

Airfield Manager: Darrin Otton, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate RW 5/23, Apron, Lighting, & TW

3-02-0404-007-2015

Airport Resurfacing	
Building Improvements	_
Construct Tie-Downs	
Construct Toilet Facilities	
Fuel Tank Upgrade	
Fuel Tank Upgrades	
Improve GPS Approach	
Install aircraft tie-downs	
Leasing area	
Pavement Markings	
Rehabilitate Ramp surface	
Repair RCO	
Replace cones and markers	
Replace Segmented Circle and Wind Cone Tower	
Shishmaref Airport Erosion Control	X
Update ALP	

Runways: 10/28 - 4,001 Surface: GRAVEL-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 873 Borough: Northwest Arctic Borough

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$3,544.07USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$109,305.26Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/07/2015

Airfield Manager: Alvin Werneke, 907-442-3147

Hours of Operation:
UNATNDD

Last Major Improvement: Install Lighting, Extend TW & RW 9/27, Improve

SREB & Access Road 3-02-0265-001-1996

Brush Cutting
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Regrade RW and Re-establish Crown
Rehab Airport Lighting
Rehab SREB
Repair/replace cones and or markers
Resurface runway, taxiway and apron
SREB Heavy Maintenance
Update ALP

SITKA ROCKY GUTIERREZ (SIT)

NPIAS: 02-0268

Runways: 11/29 - 7,200 Surface: ASPH-G Lighting: HIGH

Classification: Regional CY20 Enplanements: 27,254 Borough: City and Borough of Sitka

 Air Carrier Hub:
 No
 Medical Facility:
 Yes
 FY20 Revenue:
 \$86,533.13

 USPS Hub:
 No
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$1,092,849.75

 Part 139 Cert:
 Yes
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 06/29/2015

Airfield Manager: Kelly Boddy, 907-966-2960

Hours of Operation:
ALL/ALL/

Last Major Improvement: Install Perimeter Fence

3-02-0268-031-2017

Construct Full Parallel Taxiway	
Construct Partial Parallel TWY	
Crack Seal Apron and Taxiways	
Crack seal runway 11/29	
Expand GA Apron and Lease Lots	X
GA Apron Development (Charcoal Island)	X
Installation of FAA Weather Camera at Bioka Island	
Old ARFF building repairs	
Property Acquisition	
Sitka Airport Access Road Relocation	
Sitka Sand Storage/Dry Chemical Building	
Sitka SRE Building Rehabilitation	X
Terminal Modification	X
Vegetation Management	

SKAGWAY (SGY)

NPIAS: 02-0270

Runways: 02/20 - 3,550 **Surface:** ASPH-G **Lighting:** MED

Classification: Community On-Road CY20 Enplanements: 1,376 Borough: Municipality of Skagway

 Air Carrier Hub:
 No
 Medical Facility:
 No
 FY20 Revenue:
 \$19,647.09

 USPS Hub:
 Yes
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$46,996.19

 Part 139 Cert:
 No
 On/Off Road:
 On
 Last CIMP Inspection Date:
 04/06/2015

Airfield Manager: Shaun McKnight, 907-983-2323

Hours of Operation:
UNATNDD

Last Major Improvement: Construct TW 3-02-0270-006-2003

Brush Cutting on RSA 2/20	
Construct SRE Building	X
Construct Tie-Downs	
Crack Seal Pavement	
Exterior Paint	
Install Segmented Circle	
Install VGSI (PAPI)	
Land Acquisition	
Repaint Markings	
Repair Terminal Building	
Repair/Replace HVAC	
Repair/Replace Wind Cone	
Replace Airport Lighting System	
replace fencing	
Replace REIL	
Replace Terminal Flooring	
Tow broom	

Runways: 10/28 - 3,400 Surface: GRAVEL-G Lighting: MED

Classification: Local NPIAS Lower CY20 Enplanements: 48 Borough: Matanuska-Susitna Borough

Air Carrier Hub: No Medical Facility: No FY20 Revenue: \$2,506.72

USPS Hub: No School Facility: FY20 Ops Cost: \$46,286.02

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/07/2016

Airfield Manager: Harry Hensel, 907-745-2159

Hours of Operation:
UNATNDD

Last Major Improvement: Extend RW 9/27, Install RW Lighting, Improve

Access Road, Rehabilitate RW, Construct TW &

Apron

3-02-0411-001-1987

	III I I OJCC
Cone and Marker Repair / Replacement	Х
Construct 2-bay SREB	
Erosion	
Erosion Protection	
FY'14 ARFF Truck	
Move the existing maintenance shop and generator	
Rehabilitate apron	_
Rehabilitate runway	
Rehabilitate taxiway	
Replace runway lighting	
Replace Taxiway Lighting	
Replace threshold markers	Х
Segmented Circle	
Snow Blower	
Snow Removal Equipment Building	
Tree removal (M&O OR)	
Upgrade airport lighting	Х

Runways: 14/32 - 3,100 Surface: GRAVEL-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 51 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$49,693.11

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 07/19/2018

Airfield Manager: Ricky Ciletti, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: None

Brush Cutting	Х
Construct 2-bay SREB	
Construct new access road	
Construct new apron and taxiway	
Construct Passenger Shelter	
Construct Toilet Facilities	
Grader	
Gravel Resurfacing	X
Install VGSI (PAPI)	
Loader w/LDMT snow blower	
Obstruction Removal	
Sleetmute Test Airport Runway Resurfacing	X
SREB	
Update ALP	
Wildlife	

SOUTH NAKNEK NR 2 (WSN)

NPIAS: 02-0186

Runways: 05/23 - 2,264 Surface: GRVL-DIRT-F Lighting: HIGH

13/31 - 3,314 GRVL-DIRT-F HIGH

Classification: Local NPIAS Lower CY20 Enplanements: 39 Borough: Bristol Bay Borough

 Air Carrier Hub:
 No
 Medical Facility:
 No
 FY20 Revenue:
 \$1,000.00

 USPS Hub:
 No
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$25,245.77

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 07/15/2014

Airfield Manager: Floyd Wilson, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate Access Road; Install Airport Beacons;

Install Misc NAVAIDS; Reconstruct RW Lighting 05/23 and 13/31; Rehabilitate Apron, Taxiway and

RW 05/23 and 13/31

NEEDS: 3-02-0186-002-2019 In Project NEEDS: In Project

Repair and extend lighting system

Repair RSAs

South Naknek Runway X

South Naknek Runway Resurfacing X

Runways: 02/20 - 4,001 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,007 Borough: Nome Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00 USPS Hub: No School Facility: PK - 12 FY20 Ops Cost: \$70,942.47 Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 09/29/2014

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB, Rehabilitate RW 2/20, Apron, &

Access Road 3-02-0276-003-2016

Construct New Segmented Circle
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Embankment Erosion and Shoulder Repair
Fuel Tank Upgrade
Install VGSI (PAPI)
Move and re-level electrical enclosure building
New ULSD tank
Update ALP

STEBBINS (WBB)

NPIAS: 02-0279

UNATNDD

Runways: 05/23 - 2,999 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,156 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$63,706.25Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:09/29/2014

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: John Wilson, 907-624-3261

Hours of Operation:

Last Major Improvement: Improve SREB, Install RW Lighting, Extend RW

5/23, Construct Apron 3-02-0279-001-1995

Apply Dust Palliative
Construct 1,001' Runway Extension
Construct SREB
Construct Tie-Downs
Construct Toilet Facilities
Expand/Widen Runway, Expand Apron and Taxiway, Reduce Obstructions, and Apply Dust Palliative.
Extend Runway
Grader
Install ASOS or AWOS
Install VGSI (PAPI)
Loader
New ULSD Tank
Rehab Apron
Rehab Runway
Rehab Taxiway
Repair Airport Lighting
Repair/Renovate SRE Building
Repair/Replace Wind Cone Photo Cell
Replace Runway Edge Cones
Replace Segmented Circle
Replace Wind Cone Tower
Update ALP

STEVENS VILLAGE (SVS)

NPIAS: 02-0280

Runways: 05/23 - 4,000 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 128 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:FY20 Ops Cost:\$105,602.50

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 06/26/2017

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport & SREB

3-02-0444-002-2005

Brush Clearing	
Compactor	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	_
Drainage Improvements	
Dust Palliative Application	
Fuel Tank Upgrades	_
Grader	
Install ASOS or AWOS	
Lighted Supplemental Wind Cone	
Replace Fuel Storage Tank and Enhance Security Measures	
Replace MIRL	_
Stevens Village Airport Lighting & Resurfacing	X
Survey, Clear Obstructions, and Mark Property Boundary	
WX Reporting Needed	

STONY RIVER 2 (SRV)

NPIAS: 02-0281

Runways: 18/36 - 2,601 **Surface:** GRVL-DIRT-F **Lighting:**

Classification: Community Off-Road CY20 Enplanements: 19 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$70,591.02Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/19/2018

Airfield Manager: Ricky Ciletti, 907-675-4345

Hours of Operation:
UNATNDD

Last Major Improvement: None

Acquire Parcels 1-3 and 8-10.	
Airport requires lease lot acquisition	
Apply Dust Palliative	
Brush Cutter	
Construct 2-bay SREB	X
Construct 699' Runway Extension	
Construct a Separated Apron and Taxiway	
Construct apron	
Construct Passenger Shelter	
Construct runway	
Construct taxiway	
Construct Temporary Equipment Building	
Construct Toilet Facilities	
Dozer	
Erosion	
Floatplane dock	
Grader	
Grader and Dozer	
Improve drainage by runway	
Install ASOS or AWOS	
Install VGSI (PAPI)	
Master Plan update	
Obstruction Removal	
Resurface Runway	

NPIAS: ---

Runways: 03/21 - 3,814 **Surface:** GRAVEL-G **Lighting:**

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Matanuska-Susitna Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: No School Facility: FY20 Ops Cost: \$1,633.53

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:
UNATNDD

Last Major Improvement: None

Runways: 04/22 - 3,300 Surface: GRAVEL-P Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 215 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$82,914.98

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/23/2016

Airfield Manager: Steffen Strick, 907-524-3241 Hours of Operation:

Last Major Improvement: Construct New Airport

3-02-0472-001-2009

Building Repairs - Repair Leaking Roof Above Man Door	
Construct 700' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Gravel Repairs	
Install NAVAIDS	X
Install VGSI (PAPI)	
Rehabilitate Runway, Taxiway, Apron and Access Road	
Repair Broken and Missing Lighting, Signs, & Cones	
Replace Runway Lighting	X
Replace Taxiway Lighting	Χ
Resurface Access Road	X
Resurface Apron	X
Resurface Runway	Χ
Resurface Taxiway	X
Runway Cracking Repair	

TALKEETNA (TKA)

NPIAS: 02-0287

Runways: 01/19 - 3,500 Surface: CONC-G Lighting: MED

Classification: Community On-Road CY20 Enplanements: 0 Borough: Matanuska-Susitna Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$106,497.52USPS Hub:NoSchool Facility:PK - 6FY20 Ops Cost:\$212,677.20

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date: 06/19/2019

Airfield Manager: Chris Drews, 907-733-2278 Hours of Operation:

Last Major Improvement: Construct TW & Apron, Rehabilitate RW 18/36 & DEC-MAR/SUN-SAT/1500-0130

TW, Remove Obstructions, Acquire Land

3-02-0287-005-2016

NEEDS:	In Project	NEEDS:	In Project
Aeronautical Survey		SRE Dump Truck	
Airport Paving and Improvements		Vegetation Control	
Apron Lease Lot Development and Flood Mitigation		Vehicle gates with push button electric	
Asphalt Repair		Wind Cone	
Beacon	X	Wind Cone Pole	X
Construct Toilet Facilities			
Crack Seal			
Crack Seal Pavement			
Drainage Maintenance & Repair			
Equipment			
Expand Apron			
Expand Maintenance Facility			
Fencing			
Install Pedestrian trail and signage			
Lighting			
Man Doors			
Mower			
Pavement Markings			
Plow Truck			
Purchase Fire Extinguishers			
Regrade Surfaces and Repair Airport Lights			
Renovate Drains in M&O Shop			
Re-Paint All Markings			
Replace Airport Lighting			
Replace Cones Around Lights			
Sander			
Snow Blower			

\$0.00

Runways: 13/31 - 3,701

13W/31W - 8,000

Surface: GRAVEL-G

WATER

Lighting: MED

FY18 Revenue:

Classification: Community Off-Road

CY18 Enplanements: 9

Borough: Valdez-Cordova Census Area

Air Carrier Hub: No

Medical Facility: No

. . . .

vicultal racinty.

FY20 Ops Cost: \$79,974.93

USPS Hub: No
Part 139 Cert: No

School Facility: PK - 12
On/Off Road: Off

Last CIMP Inspection Date:

Airfield Manager: Scott Smith, 907-835-5658

Hours of Operation:

UNATNDD

Last Major Improvement: Improve Bui

Improve Building & Access Road, Extend TW, RW

12/30, & Apron, Install RW Lighting

3-02-0342-002-1995

Brush Cutter	
Construct 299' Runway Extension	
Construct Passenger Shelter	
Construct Tie-Downs	
Construct Toilet Facilities	
Install ASOS or AWOS	
Install VGSI (PAPI)	
Rehab Access Road	
Replace lighting & electrical components	Х
Resurface and Apply Dust Palliative	X
Tatitlek SRE Building Replacement	
Update ALP	
VWOS Site Location	

NPIAS: ---

Runways: 13/31 - 1,200 **Surface:** GRAVEL-G **Lighting:**

Classification: Local Non-NPIAS No Enplanements: 0 Borough: Valdez-Cordova Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: No School Facility: PK - 12 FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: John Hoffman, 907-822-3222

Hours of Operation:
UNATNDD

Last Major Improvement: None

Runways: 08/26 - 2,983 **Surface:** GRVL-DIRT-G **Lighting:** MED

Classification: Community Off-Road CY18 Enplanements: 1,506 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$95,809.45

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/20/2020

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation:

Last Major Improvement: Extend RW 7/25

3-02-0333-002-1999

NEEDS:	In Project	NEEDS:
Construct New SREB	Х	
Install New Runway Lighting	X	
Install New Segmented Circle & Primary Windcone	X	
Install New Taxiway Lighting	X	
Rehab Apron	X	
Rehab Runway	X	
Rehab Taxiway	X	
Rehabilitate Access Road	X	
Wildlife Hazard Mitigation	X	

Runways: E/W - 10,000 Surface: WATER-F Lighting:

3-02-0295-001-2005

Classification: Community Off-Road CY20 Enplanements: 328 Borough: Hoonah-Angoon Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00

USPS Hub: No School Facility: K - 12 FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Gray, 907-465-4512 Hours of Operation:

Last Major Improvement: Rehabilitate SPB

MED

Lighting:

Runways: 08/26 - 3,300 Surface: GRAVEL-G

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Southeast Fairbanks Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

 USPS Hub:
 No
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$49,647.95

 Part 139 Cert:
 No
 On/Off Road:
 On
 Last CIMP Inspection Date:
 10/06/2016

Airfield Manager: Sam Jennings, 907-883-5129

Hours of Operation:
UNATNDD

Last Major Improvement: Construct SREB 3-02-0467-002-2004

NEEDS: In Project NEEDS: In Project

Brush Cutting

Replace Primary Wind Cone Light

Runways: 03/21 - 4,400

10/28 - 982

Surface: GRVL-DIRT-G

GRVL-DIRT-F

Lighting: MED

Classification: Community Off-Road

CY20 Enplanements: 573

Borough: Dillingham Census Area

Air Carrier Hub: Yes

Medical Facility: No

FY20 Revenue: \$7,169.07

USPS Hub: Yes

School Facility: PK - 12

On/Off Road: Off

FY20 Ops Cost: \$82,710.20

Part 139 Cert: No

ochoon acmity. TR-12

Last CIMP Inspection Date: 10/15/2015

Airfield Manager: Jon Taylor, 907-842-5511

Hours of Operation:

UNATNDD

Last Major Improvement: Construct SREB 3-02-0402-001-2016

In Project	NEEDS:	In Project
	Resurface gravel runways, taxiways, and apron	
ne Snow Blower		
	SREB repairs	
	Togiak Airnort Improvements	
	Togiak Aliport Improvements	
	Togiak Airport Resurfacing/Lighting Replacement	X
	Update ALP	
	Visual Aids	
	ne	Snow Blower SREB repairs Togiak Airport Improvements Togiak Airport Resurfacing/Lighting Replacement Update ALP

Add two 3,000 gallon double wall fire rated fuel tanks; one with fuel dispenser
Clear and Repair Segmented Circle
Construct a new crosswind runway
Construct a separate electrical enclosure
Construct Tie-Downs
Construct Toilet Facilities
Dust Control
Extend OFA for RW 10-28
Extend RSA
Fix Part 77 obstructions
Install PAPI
Install Perimeter Fence
Loader
Minor Gravel Resurfacing
Obstruction Removal
Pave Runway 03/21
Pave taxiway and apron
Placards for fuel tank
Regrade Airport and Re-establish Crown
repair/replace wind cone tower
Replace Electrical Lighting Vault and Transformer
Replace Existing 2-Bay SREB with Heated 2-Bay SREB and Rotating Beacon
Replace faded light globes/ repair lighting
Replace the Airport Lighting
Replace/repair Threshold Markers

TOK JUNCTION (6K8)

NPIAS: 02-0412

Runways: 07/25 - 2,509 **Surface:** ASPH-G **Lighting:** MED

Classification:Community On-RoadCY18 Enplanements:187Borough:Southeast Fairbanks Census AreaAir Carrier Hub:YesMedical Facility:YesFY20 Revenue:\$21,055.62USPS Hub:NoSchool Facility:PK - 12FY20 Ops Cost:\$21,145.49

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date: 07/31/2017

Airfield Manager: Sam Jennings, 907-883-5129

ALL/MON-FRI/0800-1800

Last Major Improvement: Construct Apron & TW 3-02-0412-002-1999

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Construct 1,491' Runway Extension	
Construct New EEB	X
Construct Tie-Downs	
Crosswind Runway Construction	
Install AWOS (Various)	X
Install VGSI (PAPI)	
SNOW BLOWER	
Tok Runway Extension	X
Update ALP	

TOKSOOK BAY (OOK)

NPIAS: 02-0441

Runways: 16/34 - 3,218 Surface: GRVL-F Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 1,476 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$2,550.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$30,569.02Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/08/2016

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Reconstruct RW Lighting 16/34 and TW Lighting;

Install Misc NAVAIDS; Construct SREB; Rehabilitate Apron, TW, Access Road and RW

16/34

NEEDS: 3-02-0441-002-2019 In Project NEEDS: In Project

Build up the airport access road and resurface, associated utility and NAVAID modification Construct a 1-Bay SREB Construct a new RSA Construct Passenger Shelter Construct Tie-Downs **Construct Toilet Facilities** Grader **Gravel Resurfacing** Loader Rehabilitate apron Rehabilitate runway Rehabilitate taxiway Rehabilitate the Runway & Taxiway Repair soft spot/rebuild taxiway Repair Windsock Tip Down Mechanism Taxiway repair Χ Toksook Bay Airport and Access Road Plus SHREB Visual Glide Slope Indicator Lighting Replacement

Runways: 15/33 - 3,300 Surface: GRVL-DIRT-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 591 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:K - 12FY20 Ops Cost:\$45,971.36Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/20/2014

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport 3-02-0484-002-2009

Apply Dust Palliative
clean and organize building
Clean up abandoned materials
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Dust Control
install external speakers on equipment
Install VGSI (PAPI)
Master Plan Update
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Repair / Replace Concrete Floors in SREB
Scarify, reshape and recompact runway, taxiway and apron

TUNTUTULIAK (A61)

NPIAS: 02-0303

Runways: 02/20 - 3,005 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 4,296 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$36,116.90

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 08/08/2016

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport

3-02-0303-002-2006

-
Apply Dust Palliative
Beacon
Construct Tie-Downs
Construct Toilet Facilities
Expand runway safety area
Expand taxiway safety area
Install VGSI (PAPI)
Loader
Maintenance & Erosion
Rehabilitate apron
Rehabilitate runway
Rehabilitate taxiway
Repair Windsock
Replace runway lighting
Replace taxiway lighting
Scarify, reshape, and recompact runway, taxiway, and apron surface (M&O SPM)
SREB Safety
Update ALP

Runways: 16/34 - 3,300 Surface: GRAVEL-F Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 2,041 Borough: Bethel Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$44,110.46Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:08/18/2017

Airfield Manager: Joe Laraux, 907-453-2495

Hours of Operation:
UNATNDD

Last Major Improvement: Construct New Airport 3-02-0486-002-2013

Build a new SREB (in design)
Construct 1,522' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Expand apron
Install AWOS (Various)
Install VGSI (PAPI)
Install Weather Cameras
Minor Gravel Resurfacing
Miscellaneous SREB Cleanup
Rehabilitate Apron
Rehabilitate Runway
Rehabilitate Taxiway

TWIN HILLS (A63)

NPIAS: 02-0356

Runways: 18/36 - 3,000 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 26 Borough: Dillingham Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

 USPS Hub:
 Yes
 School Facility:
 PK - 8
 FY20 Ops Cost:
 \$26,027.70

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 09/02/2020

Airfield Manager: Jon Taylor, 907-842-5511

Hours of Operation:
UNATNDD

Last Major Improvement: Install RW Lighting, Improve Access Road, SREB,

& RSA 1/19, Construct TW & Apron, Acquire Land

3-02-0356-001-1994

Fire extinguishers out of annual maintenance

Fueling area not protected agaisnt collision

Flexible Threshold Markers

Install emergency eye station

Install No Smoking sign on fuel tank

Insufficient lighting around fueling area.

Need fire extinguisher near fueling area

Install ASOS or AWOS

Install MIRL, and REILs

Minor Gravel Resurfacing

Need emergency fuel shutoff

Need placards on fuel tanks

Install VGSI (PAPI)

Loader

NEEDS:	In Project	NEEDS:	In Projec
Abonded materials present		No locks on fuel dispensor	
Add distance between airport and waste facilities		Overhead door repairs	
Add two 3,000 gallon double wall fire rated fuel tanks; or	ne	Rehabilitate Apron	
with fuel dispenser		Rehabilitate Runway	
Beacon		Rehabilitate Taxiway	
Brush Cutting (M&O OR)		Relevel wind cone tower	
Building cluttered			
Construct Additional Heated 1-Bay SREB and Rotating Beacon	X	Repair Airfield Lighting replace fuel tank placards	
Construct Passenger Shelter		Replace Runway Lighting	
Construct Tie-Downs		Replace Segmented Circle	
Construct Toilet Facilities		Replace Taxiway Lighting	
Cracked glass on grader		Replace wind cones	
Dust Control		Unlit obstruction near Airport	

Runways: 06/24 - 3,100 Surface: GRAVEL-G Lighting:

Classification: Local NPIAS Lower CY18 Enplanements: 60 Borough: Lake and Peninsula Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

 USPS Hub:
 No
 School Facility:
 FY20 Ops Cost:
 \$9,098.29

 Part 139 Cert:
 No
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 07/25/2019

Airfield Manager: Paul Hansen, 907-246-3325

Hours of Operation:
UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Add distance between airport and waste facilities

Construct Tie-Downs

Cut Brush

Gravel and Dust Palliative

Remove and replace SREB

Replace wind cones and segmented circle

Runways: 06/24 - 5,583 Surface: GRVL-DIRT-P Lighting:

Classification: Local Non-NPIAS CY20 Enplanements: 49 Borough: North Slope Borough

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$118,564.15USPS Hub:NoSchool Facility:FY20 Ops Cost:\$7,403.63

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date:

Airfield Manager: Scott Randby, 907-451-5127

Hours of Operation:

Last Major Improvement: None

UNATNDD

NEEDS:	In Project NEEDS:	In Project
Airfield lighting installation		
Construct SREB		

Grader

Identify Pad and Install AWOS

Lighting Repairs

Construct Tie-Downs

PAPI, WX Reporting & WX Cameras Needed

Umiat Airport Lease Lot Development

UNALAKLEET (UNK)

3,561

Runways: 09/27 - 1,900

15/33 - 5,900

Surface: ASPH-G

ASPH-G

Lighting: MED

HIGH

Classification: Regional

CY20 Enplanements:

Borough: Nome Census Area

Air Carrier Hub: Yes

Medical Facility:

FY20 Revenue:

USPS Hub: Yes

School Facility: PK - 12

FY20 Ops Cost:

Part 139 Cert: No

On/Off Road: Off

Last CIMP Inspection Date:

\$665,925.07 07/26/2017

\$26,237.27

NPIAS: 02-0309

Airfield Manager: John Wilson, 907-624-3261

Last Major Improvement:

Construct SREB 3-02-0309-005-2009 **Hours of Operation:** ALL/MON-FRI/0800-1600

Coastal Launch Program Site
Concrete repair or replacement
Construct Full Parallel Taxiway
Construct Tie-Downs
Dozer
Fencing
Fuel Tank Upgrades
Grader
Grooves
Install snow fence
Lease lot compliance
Pavement Markings
Power overhead doors
Rehabilitate Runway 8/26
Repaint Runway Markings
Resurface taxiway
Slip resistant coating on painted floor.

UNALASKA (DUT)

Runways: 13/31 - 4,500 **Surface:** ASPH-F **Lighting:** MED

Classification: Regional CY20 Enplanements: 6,281 Borough: Aleutians West Census Area

Air Carrier Hub:YesMedical Facility:YesFY20 Revenue:\$85,470.24USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$934,131.58

Part 139 Cert: Yes On/Off Road: Off Last CIMP Inspection Date: 09/23/2015

Airfield Manager: Floyd Wilson, 907-581-1786 Hours of Operation:

Last Major Improvement: Construct SREB & Sand Storage

NEEDS:

3-02-0082-015-2015

In Project NEEDS: In Project

ALL/ALL/0800-1630

NPIAS: 02-0082

NEEDS.	in Project	NLLDS.	in Project
Access Road Improvements		extend ROFA 284'	
Acquire Land		Extend ROFA 300'	
Airfield Earthwork/Construction		Extend RSA 200'	
Airfield/Roadway Improvements		Extend RSA 400'	
Airport ramp B repairs	X	Fence and Gate Repair	
Apron A repairs	X	Maintain crack seal	
Apron Improvements	X	Maintain pavement markings (M&O SPM)	
ARFF bunker gear		Master Plan Update	
ARFF SCBA compressor		Misc Site Improvements	
ARFF water rescue access		Move residential trailers off airport property	
Badging computer, software upgrade and printers		New Beacon Tower	
Building Demolition to Clear OFA		New tow broom	
Cargo Building Improvements		Parking Improvements	
Coastal Launch Program Site		Pave road by Ramp A gate	
Construct 900' Runway Extension		Pave RSA	
Construct additional lease lots		Perimeter fencing and gate repairs/replacement	
Construct Blast Pad		Reclaim Land	
Construct Boat Launch Ramp for Emergency Response		Reconstruction of Demolished Buildings	
Construct Full Parallel Taxiway		Rehabilitate pavement (hangar/terminal apron, txwy A) X
Construct new buildings		Rehabilitate the SREB	
Construct Tie-Downs	X	Rehabilitate WWII Hangar	
Correct Mt. Ballyhoo		Relocate Service road	
Correct power plant hill		Relocated/Modify Facilities to Clear OFA	
Deicer truck		Remove Buildings	
Embankment Protection at Center Southside RW	X	Remove existing guard rail	
Environmental analysis		Remove part of east front road	
Extend OFZ		Remove traffic control signals	

Repair Apron B	X
Repair/replace rusted doors and siding.	
Replace 3 drive through gates and 3 pedestrian gates	
Replace 4,600' of 8' fence, 150' of 4' fence	
Shore Erosion	X
Terminal Building Improvements	
Toe of Fill	
Unalaska Chemical Storage & SRE Building Rehab	
Unalaska Mower Replacement	
Unalaska Ramp A Repair	X
Unalaska Ramp B Repair	X
Unalaska Torpedo Bldg Demo & Clean Up	
Update Airport Master Plan	X
Vehicle gates with electronic swipe capability	

VALDEZ PIONEER FIELD (VDZ)

NPIAS: 02-0311

Runways: 06/24 - 6,500 Surface: ASPH-G Lighting: HIGH

Classification: Regional CY20 Enplanements: 898 Borough: Valdez-Cordova Census Area

Air Carrier Hub: No Medical Facility: Yes FY20 Revenue: \$127,668.99

 USPS Hub:
 No
 School Facility:
 PK - 12
 FY20 Ops Cost:
 \$858,391.51

 Part 139 Cert:
 Yes
 On/Off Road:
 Off
 Last CIMP Inspection Date:
 09/06/2016

Airfield Manager: Robert Dunning, 907-834-1039 Hours of Operation:

Last Major Improvement: Extend RSA 6/24 MAY-SEPT/ALL/0700-1830

CT-APR/ALL/0600-1830

3-02-0311-008-2007

NEEDS: In Project NEEDS:	In Project
--------------------------	------------

NELDS.	in Project
Add a GPS or RNAV Approach	
Airport Operations Vehicle	
ARFF building heavy maintenance	
ARFF Vehicle	
Broom Runway Push	
Coastal Launch Program Site	
Construct Tie-Downs	
Handicap Pass Loader	
Install thaw pipes	
Repair roofing	
Replace Existing SREB Annex	
Replace fuel tanks	
Replace SREB	
Replace UREA building	
Resurface Runway and new lights	
Runway Light Cleaning Plow	
Sand Shed Storage Addition - Urea	X
Sand Stacker	
Snow Blower	
Snow Plow	
Snow Wing Truck	
Terminal parking area paving	
Towed Runway Broom with Plow 22'+ width	
Truck Plow Airport	
Valdez Airport Security Upgrades	
Valdez SREB Replacement	X
Weather Reporting Equipment Upgrade	

In Project

Runways: 18/36 - 3,990 Surface: GRAVEL-G Lighting: MED

Classification: Community Off-Road CY18 Enplanements: 1,328 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY20 Revenue:\$625.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$111,751.55Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:10/08/2015

In Project NEEDS:

Airfield Manager: Darrin Otton, 907-443-2500

Hours of Operation:
UNATNDD

Last Major Improvement: Rehabilitate SREB

3-02-0337-003-2002

NEEDS:

Acquire land **Building Improvements** Coastal Launch Program Site Construct Access Road Construct apron and leasing area Construct AWSS and Pad Construct New Segmented Circle and Wind Cone Tower Construct New SREB and EEB Construct Passenger Shelter Construct taxiway Construct Tie-Downs **Construct Toilet Facilities** Demolish access road **Dust Palliative** Expand RPZ Х Fuel Tank Upgrade Improve GPS Approach Install aircraft tie-downs PAPI Regrade Safety Area patches to remove oversize rock Rehabilitate Runway Surface Remove existing taxiway and apron Replace or remove supplemental cones Replace Rotating Beacon **Snow Fence Repairs** Wales Airport improvements

Weather Reporting Improvements

WHITE MOUNTAIN (WMO)

NPIAS: 02-0319

Runways: 15/33 - 3,000 Surface: GRVL-G Lighting: MED

Classification: Community Off-Road CY20 Enplanements: 876 Borough: Nome Census Area

Air Carrier Hub:NoMedical Facility:NoFY18 Revenue:\$0.00USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$107,716.10Part 139 Cert:NoOn/Off Road:OffLast CIMP Inspection Date:07/25/2017

Airfield Manager: Darrin Otton, 907-443-2500 Hours of Operation: UNATNDD

Last Major Improvement: Reconstruct RW 15/33 Lighting, Rehabilitate

Apron, TW, Lighting & RW 15/33, Install NAVAIDs

& Segmented Circle 3-02-0319-002-2018

NEEDS: In Project NEEDS: In Project

Wildlife Mitigation

All visual aids Apply Dust Palliative Construct 1,000' Runway Extension Construct Access Road Construct apron Construct Passenger Shelter **Construct Taxiway** Construct Tie-Downs **Construct Toilet Facilities** Demolish existing apron **Drainage Improvements** Equipment storage Building & Pad **Expand OFA** Expand RSA Fuel Tank Upgrades Improve GPS Approach Install aircraft tie-downs Install VGSI (PAPI) Lease lots Lighted Supplemental Wind Cone Relinquish land Rotating beacon Update ALP Wales SRE Building Replacement White Mountain Airport Improvements White Mountain SRE Upgrade

Widen TSA

Runways: 04/22 - 1,480 Surface: GRAVEL-F Lighting:

Classification: Community On-Road No Enplanements: 0 Borough: Valdez-Cordova Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: No **School Facility:** PK - 12 **FY20 Ops Cost:** \$13,414.75

Part 139 Cert:NoOn/Off Road:OnLast CIMP Inspection Date:09/18/2019

Airfield Manager: Paul Bertholl, 907-783-2232

Hours of Operation:
UNATNDD

Last Major Improvement: None

Airport master plan
Brush and clear runway and adjacent areas
Coastal Launch Program Site
Construct 1,820' Runway Extension
Construct Passenger Shelter
Construct Tie-Downs
Construct Toilet Facilities
Fencing
Install markers and cones
Install MIRL Runway Lighting
Install VGSI (PAPI)
Large rock removal
Secure runway

WILEY POST-WILL ROGERS MEMORIAL (BRW)

Runways: 07/25 - 7,100 Surface: ASPH-F Lighting: HIGH

Classification: Regional CY20 Enplanements: 15,645 Borough: North Slope Borough

Air Carrier Hub:YesMedical Facility:YesFY20 Revenue:\$273,911.68USPS Hub:NoSchool Facility:PK-12FY20 Ops Cost:\$1,789,523.58Part 139 Cert:YesOn/Off Road:OffLast CIMP Inspection Date:08/30/2016

Hours of Operation:

ALL/ALL/0600-2030

NPIAS: 02-0026

Airfield Manager: John Olsen, 907-852-6199

Construct Full Parallel Taxiway

East Parallel Taxiway Extension

Fire extinguisher re certification

Install RW 25 Approach Lights

Construct Tie-Downs

GA Parking Apron

Master Plan Upgrade

North Apron Expansion

Deicer Truck

Fencing

Last Major Improvement: Construct ARFF Building

3-02-0026-018-2019

Rehabilitate RW 7/25 and TW Lighting;

3-02-0026-019-2019

NEEDS:	In Project	NEEDS:	In Project
Add Vehicle Parking Space		Okpik Street Improvements	
Airport Operations Vehicle		PAPI repair	
Apron Expansion		Regrade Runway Safety Areas	
Apron Rehabilitation		Remove and Re-establish Markings per the Current A/C	;
Barrow Ahkovak Road Improvements (FHWA Funding)		Replace secondary Wind Cone Tower	
Barrow Airport Runway Surface Repairs		Replace segmented circle	
Barrow Airport Security Upgrades		Runway Light Cleaning Plow	
Barrow Airport South Side Parallel Taxiway		Runway Overlay	
Barrow Airport Stormwater Management Plan		Runway Rehabilitation	
Barrow Apron Expansion		Runway Safety Area Improvements	
Barrow Deicing Chemical Storage Building		RW 24 Approach Lighting	
Barrow SREB/ARFF Building Replacement		RW 25 ILS Approach	
Blower (7,500 ton per hour)		RW 6 Obstruction Removal	
Broom Runway Towed		Safety area erosion control	
Coastal Launch Program Site		Taxiway Overlay	
Combined M&O Facility - Phase I		West Parallel Taxiway Extension	
Combined M&O Facility - Phase II	X		

Χ

WILLOW (UUO)

NPIAS: 02-0320

In Project

Runways: 13/31 - 4,400 Surface: GRAVEL-G Lighting: MED

Classification: Local NPIAS High CY18 Enplanements: 3,002 Borough: Matanuska-Susitna Borough

 Air Carrier Hub:
 No
 Medical Facility:
 No
 FY20 Revenue:
 \$87,003.23

 USPS Hub:
 No
 School Facility:
 K - 12
 FY20 Ops Cost:
 \$159,796.57

 Part 139 Cert:
 No
 On/Off Road:
 On
 Last CIMP Inspection Date:
 09/28/2020

In Project NEEDS:

Airfield Manager: Raymond Adams, 907-495-6286

Hours of Operation:
UNATNDD

Last Major Improvement: Improve SREB

NEEDS:

3-02-0320-002-1999

mrroject	NEEDS. III F TOJECT	
Aircraft Highway Crossing Improvement	Perimeter fencing repairs/replacement	
Building Maintenance	Property Acquisition	
Complete Routine Maintenance/Cleanup	Reassess Removing Displaced Threshold	
Construct 1-bay SREB	Reduce RSA	
Construct Gravel/Ski Strip	Rehabilitate Runway	
Construct new lighted segmented circle	Rehabilitate Taxiway	
Construct Road and Helipad	Rehabilitation/extension of the existing access road	
Construct Toilet Facilities	Removal of Part 77 Obstructions	
Cut trees and remove hill by South Taxiway (M&O OR)	Remove taxiway	
Evaluate/Rectify Electrical Safety Concern	Repair man doors	
Expand SREB X	Repair window	
Expand Tie Down, Road Access, and Taxiway Connection	Replace Runway Lighting	
near RW 31	Replace Taxiway Lighting	
Fencing	Replace Windsock	
Gate repairs	Resurface Runway	
Grader	Shift taxiway 90' left	
Heliport RPZ	Shot Gun Cove Rd expansion	
Improve Blind Corner on S. End of Runway	Ski Runway RSA, OFA, & OFZ	
Install barrier fencing behind the floatplane leaseholds	Snow Blower	
Install Emergency Eye Wash Station(s)	Storage Building	
Install Fire Extinguisher	SW Airport Tiedown Expansion	
Install Perimeter Fence	Taxiway, Road, and Lease Lot Expansion Near RW 13	
Lease Areas	Tree Clearing/Fencing/Signage	
Loader	Vehicle gates with push button electric	
Minor Gravel Resurfacing & Dust Control	Vehicle Parking	
NE Airport Lease Lots and Tiedowns	Willow Airport Improvements	
Obstruction Removal	Willow Automated Weather Observation System (AWOS)	
	willow Automated Weather Observation System (AWOS)	

NPIAS: ---

Runways: 13W/31W - 3,600 Surface: WATER Lighting:

Classification: No Enplanements: 0 Borough: Matanuska-Susitna Borough

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00
USPS Hub: No School Facility: K - 12 FY18 Ops Cost: \$0.00

Part 139 Cert: No On/Off Road: Off Last CIMP Inspection Date: 09/28/2020

Airfield Manager: Raymond Adams, 907-495-6286 Hours of Operation: UNATNDD

Last Major Improvement: None

NEEDS: In Project NEEDS: In Project

Purchase Boat, Replace Buoys

Removal of island on Willow Lake

Transient Floatplane Parking and Dock

Water Level Maintenance Study

Runways: 02/20 - 2,000 Surface: TURF-DIRT-P Lighting:

Classification: Local NPIAS Lower No Enplanements: 0 Borough: Yukon-Koyukuk Census Area

Air Carrier Hub: No Medical Facility: No FY18 Revenue: \$0.00

USPS Hub: No School Facility: FY20 Ops Cost: \$853.00

Part 139 Cert: No On/Off Road: On Last CIMP Inspection Date:

Airfield Manager: Jeff Russell, 907-451-2207

Last Major Improvement: None

UNATNDD

NEEDS:	In Project NEEDS:	In Project

Airport master plan

Brushing, and tree clearing.

Develop ALP

Wiseman Airport Access Road Improvements

Wiseman Airport Rehabilitation

WRANGELL (WRG)

NPIAS: 02-0323

Runways: 10/28 - 6,000 Surface: ASPH-G Lighting: HIGH

Classification: Regional **CY20 Enplanements:** 4,705 **Borough:** City and Borough of Wrangell

Air Carrier Hub:NoMedical Facility:YesFY20 Revenue:\$47,582.52USPS Hub:YesSchool Facility:PK - 12FY20 Ops Cost:\$421,869.29

Part 139 Cert: Yes On/Off Road: Off Last CIMP Inspection Date: 12/12/2016

Airfield Manager: William Bloom, 907-874-3107

Hours of Operation:
ALL/ALL/0600-1700

Last Major Improvement: Rehabilitate TW & Apron

3-02-0323-014-2015

NEEDS:	In Project NEEDS:	In Project
--------	-------------------	------------

Aeronautical Survey
Apron Lease Lot Development
Chip seal apron
Construct Dry Storage Building
Construct Full Parallel Taxiway
Construct Parallel Taxiway
Construct Tie-Downs
Construct Toilet Facilities
Emergency Power Generator
Expand GA Apron
Install Light Timers and Repair Heater
Install MALSR on Runway 10
Pickup Truck
Rehabilitate Taxiway and Apron
Replace VASIs with PAPIs
RSA Compaction
Runway Broom
Runway Rehabilitation
Self Propelled Runway Broom
Tractor Mower
Tree Removal
Update ALP
WHA/WHMP Update

YAKUTAT (YAK)

Runways: 02/20 - 6,475

Surface: CONC-G 11/29 - 7,732 ASPH-G

Lighting: HIGH HIGH

Classification: Regional

Air Carrier Hub: No

Airfield Manager:

CY20 Enplanements: 3,409

FY20 Revenue: **Medical Facility:** \$201,776.83

USPS Hub: Yes School Facility: PK - 12

FY20 Ops Cost: \$856,747.05

NPIAS: 02-0327

Part 139 Cert: Yes On/Off Road: Off **Last CIMP Inspection Date:** 06/30/2014

Robert Lekanof, Jr., 907-784-3476

Hours of Operation: ALL/ALL/1700-0400Z WINTER;

Borough: City and Borough of Yakutat

RW 11/29 Rehabilitation Phase II **Last Major Improvement:**

3-02-0327-021-2016

NEEDS:	In Project NEEDS:	In Project
NEEDO.	III PIOJECL NEEDS.	III FIOIEC

Aeronautical Survey
Airport Perimeter Fence X
Apron Drainage Rebuild X
Brush Cutting X
Brush Cutting on RSA 11/29
Coastal Launch Program Site
Construct Full Parallel Taxiway
Construct Tie-Downs
Construct Toilet Facilities
Construct Ultimate Apron
Inspect Fire Extinguisher
Install Emergency Eye Wash Stations in ARFF Building
Install Placards and Signs at Fuel Tank
Obstruction Removal X
Obstruction Survey
Obstruction/Tree Removal on Runway 2/20
Pave Glide slope
Pavement repairs
Rehabilitate apron X
Rehabilitate Runway 11/29
Repair Exterior Light
WHA/WHMP Update