

ITB #20-01-207635  
Whittier Corrosion Inspection Repairs  
02/06/2020

ITEM #	Contractor ITEM DESCRIPTION	UNIT OF Measure	QTY:	Brice Incorporated	
				Unit Price	Extended Price
1	Mobilization	Lump Sum	1.0	\$ 87,000.00	\$ 87,000.00
2	Structural Steel & Hardware	Lump Sum	1.0	\$ 51,000.00	\$ 51,000.00
3	Removal & Re-installment of Deck Panels	Lump Sum	1.0	\$ 76,000.00	\$ 76,000.00
4	Falsework and/or Scaffolding	Lump Sum	1.0	\$ 55,000.00	\$ 55,000.00
5.1	Replacement of Identified Structural Components	Lump Sum	1.0	\$ 168,000.00	\$ 168,000.00
5.2	Repair of Un-Identified Structural Components	Hour	0.0	\$ 777.00	\$ -
6.1	Spray Metalization	SF	800.0	\$ 235.00	\$ 188,000.00
6.2	Containment	Lump Sum	1.0	\$ 52,000.00	\$ 52,000.00
<b>Total Base Bid</b>		<b>Total</b>		<b>\$ 677,000.00</b>	
6.1-M.1	Adjust Upslope Trench For Upslope Inlets	SF	800.0	\$ (1.50)	\$ (1,200.00)
6.1-M.2	Clean Upslope Inlets	SF	800.0	\$ (0.75)	\$ (600.00)
<b>Total Additive Alternate Bid</b>		<b>Total</b>		<b>\$ (1,800.00)</b>	
<b>Grand Total Bid</b>				<b>\$ -</b>	<b>\$ 675,200.00</b>



2-6-20

Fori Teknik  
2-6-2020