

Datasheet

Gebalon PC Ultimate G0 FR (y)

Gebalon PC Ultimate G0 FR (y) Designation according to ISO 1043 >PC (REC100) FR(40)< (y) corresponds to four-digit colour code UL Referenz E346354-20111114

Properties

Polycarbonate injection molding type, based on recyclate, easy to demold, halogen free, flame retardant.

Areas of application

Technical Injection Molded Parts.

Properties ¹⁾²⁾³⁾⁴⁾	Test condition	Unit	Standard	Value
Mechanical properties				
Charpy impact strength	23°C	23°C kJ/m²		no break
Charpy notched impact strength	23°C	kJ/m²	ISO 179/1eA	10
Tensile modulus of elasticity	1 mm/min MPa		ISO 527-1	2.200
Tensile stress at yield	50 mm/min	MPa	ISO 527-1	60
Tensile strain at yield	50 mm/min	%		6,2
Thermal properties				
Vicat softening temperature, VST	50 N, 50 K/h	°C	ISO 306 B50	141
Heat deflection temperature, HDT A	1.80 MPa	°C	ISO 75-2 A	124
Heat deflection temperature, HDT B	0.45 MPa	°C	ISO 75-2 B	136
Test specimen manufacturing operations				
Injection molding mass temperature	-	°C	ISO 294	290
Injection molding mold temperature	-	°C	ISO 294	110
Other properties				
Density	23°C	g/cm³	ISO 1183-1 A	1,20
Burning behaviour ⁴⁾	1,5 mm	Class	UL 94	VO
Burning behaviour ⁴⁾	3,0 mm	Class	UL 94	VO
Glow-wire flammability index, GWFI	1,5 mm/960°C	-	IEC 60695-2-12	passed

¹⁾ Typical values for uncolored products. Deviations within normal tolerances are possible.

²⁾ Guideline values for material comparison - not the basis for component and tool design.

³⁾ The processing shrinkage depends on the process control and the component and tool design.

⁴⁾ Own measurement according to UL 94.

geba Kunststoffcompounds GmbH

Industriestraße 11-21

59320 Ennigerloh

info@geba.eu

Perfektion im Ganzen. Präzision im Detail.


Processing recommendations

Drying conditions

Recommended drying temperatures and times	
Drying temperature (dry air dryer)	100 - 120°C
Drying	2 - 4 h
max. residual moisture	<0,02 %

For downtimes of 4 hours or more, we recommend lowering the temperature of the dryer by 40°C.

Processing temperatures



Melt temperature: 270 - 295°C							
5. Mold	4. Nozzle	3. Zone	2. Zone	1. Zone	Feeding Zone		
80 - 120°C	290 - 295°C	290 - 295 °C	280 - 295°C	270 - 280°C	80 – 90°C		

The values given are based on empirical values and are to be understood as guideline values.

Test values

Unless expressly stated otherwise, the stated values were determined on standardised test specimens at room temperature. The figures are to be regarded as indicative, but not as binding minimum values. Please note that the properties can be significantly influenced by the tool design, the processing conditions and the colouring processing.

Processing instructions

During processing, small amounts of fission products can be released under the recommended processing conditions. According to the safety data sheet, compliance with the specified occupational exposure limits must be ensured by adequate extraction and ventilation at the workplace so as not to impair the health and well-being of the machine operators. The prescribed processing temperatures must not be significantly exceeded in order to avoid greater partial decomposition of the polymer and cleavage of volatile decomposition products. Please note that all processing data given is for guidance only and may vary depending on individual processing units. Please contact your sales or technical representative for details.

Disclaimer

All of the data contained in this Data Sheet Published information, documents and illustrations are the sole property of geba. Permission to use them is subject to the proviso that the copyright notice appears on all copies, that the information is used only personally and is not commercially exploited, that the information is not changed in any way and that all representations of the website are only used together with the accompanying text. geba assumes no liability or warranties whatsoever with regard to the in the information posted in this area, documents and representations. geba is not responsible for any damages of any kind that may result from the use or existence of the website and the information, documents and representations contained therein. The user bears full responsibility for all risks arising from the use of this data sheet for him. With regard to the documents and information posted, geba reserves the right to make changes or additions at any time without prior notice. The user of the website is fully responsible for all information he sends to geba, with regard to content and accuracy, as well as responsible for ensuring that the rights of other persons are not violated.