



19
20

EASEMENT NOTES:
 EXCEPTION 17 772/80 SEWER AND RELOCATED 38' ROAD EASEMENT NOT LOCALIZABLE BY RECORD
 EXCEPTION 17A 1659/274 CONTIGUOUS OF EXCEPTION 17 "38' ROAD ACCESS"

REVISIONS	JOB NUMBER 3377-02
	DRAWN BY JMS
	CHECKED BY
	DATE 06/09/2008

**TOPOGRAPHIC SURVEY
 OF
 RICHMOND FIELD STATION**

1 OF 2 RICHMOND

MUIR CONSULTING, INC.
 139 CHURCH AVENUE
 OAKDALE, CA 95361
 (209) 845-8630 FAX (209) 845-8639
 SURVEYING • G.I.S. • G.P.S.
 www.muirconsulting.com

CALIFORNIA