

January 15, 2021

Sammy Cummings and Angie Spear Fairbanks International Airport 6450 Airport Way, Suite 1 Fairbanks, Alaska 99709

RE: BLOCK 4 LOT 2 SOIL SAMPLING DATA REPORT, FAIRBANKS INTERNATIONAL AIRPORT, FAIRBANKS, ALASKA Shannon & Wilson, Inc. has prepared this letter report to document soil sample collection at hangar site at lease lot Block 4, Lot 2 of the Fairbanks International Airport (FAI) in Fairbanks, Alaska. This final report supersedes the draft submitted on August 21, 2020. Figure 1 shows the location of the hangar site on FAI property. The effort summarized herein was conducted by Shannon & Wilson on behalf of the FAI under Alaska Department of Transportation and Public Facilities (DOT&PF) Professional Services Agreement Number 25-19-1-013. This sampling effort was authorized by Notice to Proceed 4-13, issued on July 23, 2020. The FAI is listed by the Alaska Department of Environmental Conservation (DEC) as an active contaminated site due to the presence of per- and polyfluoroalkyl substances (PFAS) in groundwater and surface water (File Number 100.38.277, Hazard ID 26816). BACKGROUND plans to build the hangar during the 2020 and 2021 construction seasons. Design drawings dated July 2, 2020 are enclosed. According to the drawings, excavate an approximately 200 feet by 150 foot area with a depth of at least one foot for the hangar pad. Utilities will include buried water, sanitary sewer, electrical, and natural gas. The four utilities will run approximately 300 from the hangar to the property boundary. The planned excavation area is displayed in Figures 2 and 3. The depth at which the utilities will be installed and number of trenches required for utility installation are not specified. The hangar groundbreaking was held on July 16, 2020. The FAI is not aware of a past release of aqueous film-forming foam or other PFAS-containing substances at or adjacent to the hangar site. However, the FAI requested that soil samples be collected prior to excavation to test for the presence of PFAS.



The purpose of this sampling effort was to evaluate PFOS and PFOA concentrations with respect to soil handling and disposal requirements.

SCOPE OF SERVICES

Our scope of services for this project included:

- reviewing construction design drawings (enclosed);
- preparing a Site Safety and Health Plan for work at the site;
- collecting up to 15 surface and subsurface soil samples prior to or during construction of the hangar;
- submitting analytical samples to Eurofins TestAmerica Sacramento (TestAmerica) laboratory for analysis of 18 PFAS by EPA Method 537.1M;
- reviewing the analytical data; and
- preparing this letter report.

CONTAMINANTS OF CONCERN AND ACTION LEVELS

The primary contaminants of concern at the site are perfluorooctanesulfonic acid (PFOS) and perfluorooctanoic acid (PFOA), two PFAS commonly found at airports and fire training areas. Shannon & Wilson compared soil sample results to the DEC soil-cleanup levels found in 18 Alaska Administrative Code 75 *Table B1. Method Two – Soil Cleanup Levels (Migration to Groundwater)*. Applicable soil-cleanup levels are 3.0 micrograms per kilogram (µg/kg) PFOS and 1.7 µg/kg PFOA. There are no cleanup levels for other PFAS compounds.

FIELD ACTIVITIES

On July 23, 2020, Shannon & Wilson personnel Ashley Jaramillo, Chemist, and Adam Wyborny, Environmental Engineer-in-Training, collected seven soil samples from within the hangar and utility footprint using hand tools. The surface-soil samples were collected from immediately beneath the vegetation, where present. Field staff noted several inches of sandy gravel beneath the vegetation, underlain by sandy silt.

On July 24, Ashley Jaramillo and Craig Beebe, Geologist, collected three subsurface samples and one field duplicate sample from within the utility footprint. They advanced shallow soil borings to approximately 4.5 feet below the ground surface using a gas-powered auger and hand auger. These individuals are State of Alaska Qualified Samplers per 18 AAC 75.333[b]

Soil Sampling Data Report.docx



and 18 AAC 78.088[b]. Soil-sample locations are displayed in Figures 2 and 3. A copy of Shannon & Wilson's field notes are appended.

Sample Custody, Storage, and Transport

Immediately after collection, Shannon & Wilson placed the soil-sample jars in Ziploc bags and stored them in a designated sample cooler maintained between 0°C and 6°C with ice substitute. Shannon & Wilson is aware of the potential for cross-contamination of PFAS samples from numerous everyday household items and took appropriate precautions to prevent cross-contamination.

Shannon & Wilson shipped the sample cooler to TestAmerica in West Sacramento, California on Monday, July 27, 2020, using Alaska Air Cargo priority overnight service. This allowed sufficient time for the laboratory to analyze the samples within holding-time requirements for the analytical method. The samples were submitted for determination of the 18 PFAS listed in EPA Method 537.1, a drinking water method, by 537M.

ANALYTICAL RESULTS

PFOS was detected above the laboratory limit of quantitation (LOQ) in two surface-soil samples: at 1.2 μg/kg in sample 20FAI-LM-02, and 1.0 μg/kg in sample 20FAI-LM-03. PFOA was not detected above the LOQ. PFOS and/or PFOA were detected at estimated concentrations below the LOQ in samples 20FAI-LM-01, 20FAI-LM-04, 20FAI-LM-05, and 20FAI-LM-06. PFOS and PFOA were not detected in the subsurface samples collected from approximately 4 to 4.5 feet below the surface. In addition, perfluorohexanesulfonic acid (PFHxS) was detected in sample 20FAI-LM-05; there is no established DEC cleanup level for this compound. Analytical results are summarized in Table 1 and Figured 2 and 3.

QUALITY ASSURANCE / QUALITY CONTROL

Quality Assurance/Quality Control (QA/QC) procedures assist in producing data of acceptable quality and reliability. Shannon & Wilson reviewed the analytical results for laboratory QC samples and conducted a QA assessment for this project. The QA assessment included a review of the chain-of-custody records and laboratory-receipt forms to check that custody was not breached, sample holding-times were met, and the samples were properly handled from the point of collection through analysis by the laboratory. The QA review procedures allowed Shannon & Wilson to document the accuracy and precision of the analytical data, as well as check the analyses were sufficiently sensitive to detect analytes at levels below regulatory standards.



The laboratory's detection limit (DL) is the lowest analyte concentration that can be measured. The laboratory's LOQ or reporting limit is the lowest analyte concentration that can be routinely measured in the sampled matrix within a specified limit of precision and bias, or the point at which a concentration is considered quantitative. Sample matrix, instrument performance, sample dilutions, and other factors may affect the DL and LOQ. If the analyte is detected between the DL and the LOQ, its concentration is considered an estimate. These values are flagged with a 'J' in the analytical results table; this flag is applied by the laboratory.

Shannon & Wilson reviewed the data using the current DEC Laboratory Data Review Checklist (LDRC) and applied a standardized set of flags. During the QC review, Shannon & Wilson applied flags indicating estimated data or analytical bias due to QC failures as follows.

- The PFOS result for sample 20FAI-LM-01 is considered estimated, biased high, and flagged 'JH' due to high recovery of the analyte in the matrix spike (MS) sample.
- The PFHxS result for sample 20FAI-LM-05 is considered estimated and flagged 'J' because the transition mass ratio did not meet laboratory acceptance criteria. This issue is typically observed due to matrix interference. The laboratory analyst used professional judgement to identify the analyte but there is some degree of uncertainty in this determination.

We consider the results to be acceptable and representative for assessing site conditions at the times and locations they were collected, with the applied qualifiers. No samples were rejected as unusable due to QC failures. Details regarding results of our QA analyses are presented in the appended TestAmerica laboratory report 320-63125-1 and associated LDRC.

DISCUSSION AND CLOSURF

PFOS and PFOA were not detected above their respective DEC migration-to-groundwater cleanup levels in soil samples from the hangar site. There are therefore no PFAS-related disposal or handling requirements related to soil excavated during construction. This conclusion should be re-evaluated if regulatory limits change prior to completion of the hangar, observations during construction suggest the presence of PFAS, or other information becomes available regarding the potential for PFAS to be present.

Shannon & Wilson has prepared the enclosed document "Important Information about Your Geotechnical/Environmental Report" to assist you and others in understanding the use and

Soil Sampling Data Report.docx 102519-014



limitations of this report. This data report was prepared for the exclusive use of the FAI and their representatives in accordance with our scope of services. Regulatory agencies may reach different conclusions than Shannon & Wilson.

Shannon & Wilson's observations represent site conditions as they existed during our July 2020 sampling effort. Our observations are specific to the locations and dates noted herein and may not be applicable to all areas of the site. This analytical testing effort cannot precisely predict the characteristics, quality, or distribution of PFAS throughout the site. Potential variations include, but are not limited to:

- The conditions between sampling points may be different.
- The passage of time or intervening causes (natural and manmade) may result in changes to site conditions.
- Contaminant concentrations may change seasonally or in response to other natural conditions, chemical reactions, and/or other events.
- The presence, distribution, and concentration of contaminants may vary from our sampling locations. Our tests may not represent the highest contaminant concentrations at the site.

The report should not be used without our approval if any of the following occurs:

- Project details change or new information becomes available, such as revised regulatory levels or the discovery of additional source areas.
- Conditions change due to natural forces or human activity at, under, or adjacent to the project site.
- If the site ownership or land use has changed.
- If the land use or site ownership has changed.
- Regulations, laws, or cleanup levels change.
- If the site's regulatory status has changed.

If any of these occur, we should be retained to review the applicability or our analyses, conclusions, and recommendations.

Soil Sampling Data Report.docx 102519-014



We appreciate this opportunity to be of service to you.

Sincerely,

SHANNON & WILSON

Marcy Nadel Geologist

DHF:MDN:CBD/mdn

Enc. Figure 1 – Hangar Site Vicinity

Figure 2 – Surface Soil Sample Results

Figure 3 – Subsurface Soil Sample Results

PDC Engineers Alaska Hangar Design Drawings

Table 1 – Summary of Soil Sample Analytical Results

Field Notes

TestAmerica Analytical Laboratory Report 320-63125-1 and Laboratory Data Review


Checklist


Important Information about Your Geotechnical/Environmental Report


Cc: Theresa Harvey, FAI Operations Manager

Katrina LeMieux, FAI Environmental Manager

Soil Sampling Data Report.docx 102519-014







Excavation limits

Future hangar footprint Block 4 Lot 2 nit ss 0 100 200

Feet

Fairbanks International Airport Fairbanks, Alaska

SURFACE SOIL SAMPLE RESULTS

January 2021


102519-014


SHANNON & WILSON, INC. GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS


Figure 2


NOTES:

- J Estimated concentration, detected greater than the detection limit and less than the limit of quantitation. Flag applied by the laboratory.
- < Analyte not detected; listed as less than the reporting limit unless otherwise flagged due to quality-control failures.
- JH* Estimated concentration, biased high, due to quality control failures. Flag applied by Shannon & Wilson, Inc.
- bgs below ground surface









Feet

Fairbanks International Airport Fairbanks, Alaska

SUBSURFACE SOIL SAMPLE RESULTS

January 2021

102519-014

SHANNON & WILSON, INC.

GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS

Figure 3

NOTES:

- J Estimated concentration, detected greater than the detection limit and less than the limit of quantitation. Flag applied by the laboratory.
- < Analyte not detected; listed as less than the reporting limit unless otherwise flagged due to quality-control failures.

bgs below ground surface

ABBREVIATIONS: LEGEND: CENTER LINE — BRL —— BUILDING RESTRICTION LINE AC ASPHALT CONCRETE EXISTING EDGE OF PAVEMENT ALASKA DEPARTMENT OF TRANSPORTATION ADOT APPROX — PROPOSED EDGE OF PAVEMENT BLDG BUILDING ---EG----EG--- EXISTING EDGE OF GRAVEL BOTT BOTTOM ALIGNMENT BEGINNING OF PROJECT BUILDING RESTRICTION LINE ---- EXISTING CONTOUR BRL BOTTOM OF EXCAVATION BTM EX CO CLEANOUT EXISTING GAS LINE CONC CONCRETE CMP CORRUGATED METAL PIPE PROPOSED GAS LINE CU COPPER EXISTING SANITARY SEWER DIAMETER Ø DEMO DEMOLITION — — — ss — PROPOSED SANITARY SEWER **DUCTILE IRON PIPE** DIP EXISTING WATER LINE EL, ELEV **ELEVATION** EDGE OF PAVEMENT PROPOSED WATER LINE EX, (E) **EXISTING** — OH — EXISTING OVERHEAD UTILITIES FIRE PROTECTION FIRE DEPARTMENT CONNECTION FDC — — — UGE —— EXISTING UNDERGROUND FF/FFE FINISHED FLOOR ELEVATION ELECTRIC FINISHED GRADE FG HEADBOLT HEATER HIGH DENSITY POLYETHYLENE HOT MIX ASPHALT HBH HDPE HMA FILL EXTENTS INSIDE DIAMETER ---- PROPERTY LINE IE/I.E. INVERT ELEVATION PROPOSED CONTOUR LT LEFT ±ME MATCH EXISTING GRADE MAX MAXIMUM EXISTING TOP OF EMBANKMENT ONE-THOUSANDTH OF AN INCH MIL MIN — - - - - TOP - - - - TOP — PROPOSED TOP OF EMBANKMENT NTS NOT TO SCALE · · TOE · · · · · TOE EXISTING TOE OF EMBANKMENT OC ON CENTER OUTSIDE DIAMETER OD TOE TOE PROPOSED TOE OF OHE OVERHEAD ELECTRIC **EMBANKMENT** PCC PORTLAND CONCRETE CEMENT EXISTING TREELINE PΕ POLYETHYLENE — DITCH — DITCH LINE RADIUS REQ'D REQUIRED EXISTING LIGHT RIGHT RT R/W, R.O.W RIGHT OF WAY PROPOSED BOLLARDS SQUARE FOOT @ CLEANOUT STD DWG STANDARD DRAWING SANITARY SEWER SS EXISTING COMM PEDESTAL S/W SIDEWALK STORM DRAIN SD EXISTING GUY ANCHOR TBM TEMPORARY BENCH MARK EXISTING PROPERTY CORNER, TOC TOP OF CONCRETE • CONTROL MONUMENT TYP TYPICAL UNDERGROUND TELEPHONE LINE EXISTING SIGN UD UTILIDUCT **EXISTING UTILITY POLE** UGE UNDERGROUND ELECTRIC USA UTILITY SERVICES OF ALASKA NEW UTILITY POLE W WATER T ELECTRICAL TRANSFORMER W/ WITH FLOW DIRECTION SURVEY SET REBAR & CAP WATER SURFACE LEVEL DEMOLITION CONCRETE SURFACE ASPHALT SURFACE (SS) SANITARY SEWER MANHOLE \otimes

TEMPORARY BENCH MARK

HEADBOLT OUTLET

NOTES:

- ALL UTILITY CONSTRUCTION SHALL CONFORM TO CURRENT UTILITY SERVICES OF ALASKA (USA) STANDARDS OF CONSTRUCTION.
- 2. ALASKA DIG LINE MUST BE CONTACTED AND ALL EXISTING UTILITIES LOCATED BEFORE COMMENCING GROUND DISTURBING ACTIVITIES.
- 3. WATER AND SANITARY SEWER MAINS TO BE FIELD LOCATED AND VERIFIED PRIOR TO CONSTRUCTION. TIE IN LOCATIONS SHOWN BASED UPON SYSTEM MAPS AND UTILITY LOCATED ADJACENT TO SITE. PDC TO CONFIRM LOCATION IN JULY OF 2020.





Hangar Alaska


¥ airbanks, No. Description Date


GENERAL NOTES AND LEGEND

19319FB 07/03/2020 Drawn by DES KAB

As Noted







NOTES:

- MAINTAIN A SECURE FENCELINE TO AIRFIELD AT ALL TIMES DURING CONSTRUCTION. COORDINATE DEMOLITION OF EXISTING FENCES WITH AIRPORT MANAGER.
- OBTAIN UTILITY LOCATES PRIOR TO EXCAVATION. SITE CONTAINS ABANDONED 10 GA WATERLINE APPROXIMATELY HALFWAY ACROSS SITE.DO NOT DISTURB EXISTING UTILITIES WITHOUT ADVANCE AUTHORIZATION FROM UTILITY COMPANY.
- 3. PROPOSED FOUNDATION PREPARATION IS DESIGNED BASED UPON THE RECOMMENDATIONS PROVIDED IN THE GEOTECHNICAL REPORT PREPARED BY PDC ON FEBRUARY 27, 2020. SEE REPORT FOR BORELOGS AND FOUNDATION PREPARATION REQUIREMENTS. THE APPROXIMATE DEPTH TO GROUNDWATER AND SAND/GRAVEL LAYER AT THE TIME OF SUBSURFACE EXPLORATION HAS BEEN DEPICTED ON C-401 SITE SECTIONS FOR REFERENCE.
- REMOVE ALL SURFACE ORGANICS AND DELETERIOUS MATERIALS WITHIN PAD AND ACCESS ROAD FOOTPRINT PRIOR TO PLACEMENT OF FILL.





Alaska Hangar

Fairbanks, AK

No.	Description	Date



Project number	19319FB
Date	07/03/2020
Drawn by	DES
Checked by	KAB

CD-001
le As Noted



NOTES:

50 25 0

- MAINTAIN A SECURE FENCELINE TO AIRFIELD AT ALL TIMES DURING CONSTRUCTION. COORDINATE DEMOLITION OF EXISTING FENCES WITH AIRPORT MANAGER.
- 2. OBTAIN UTILITY LOCATES PRIOR TO EXCAVATION. SITE CONTAINS ABANDONED 10 GA WATERLINE APPROXIMATELY HALFWAY ACROSS SITE.DO NOT DISTURB EXISTING UTILITIES WITHOUT ADVANCE AUTHORIZATION FROM UTILITY COMPANY.
- PROPOSED FOUNDATION PREPARATION IS DESIGNED BASED UPON THE RECOMMENDATIONS PROVIDED IN THE GEOTECHNICAL REPORT PREPARED BY PDC ON FEBRUARY 27, 2020. SEE REPORT FOR BORELOGS AND FOUNDATION PREPARATION REQUIREMENTS. THE APPROXIMATE DEPTH TO GROUNDWATER AND SAND/GRAVEL LAYER AT THE TIME OF SUBSURFACE EXPLORATION HAS BEEN DEPICTED ON C-401 SITE SECTIONS FOR REFERENCE.
- REMOVE ALL SURFACE ORGANICS AND DELETERIOUS MATERIALS WITHIN PAD AND ACCESS ROAD FOOTPRINT PRIOR TO PLACEMENT OF FILL.





Alaska Hangar


Fairbanks, AK

No.	Description	Date	

OVERALL SITE PLAN

Project number	19319FB
Date	07/03/2020
Drawn by	DES
Checked by	KAB

As Noted







Alaska Hangar


No. Description Date

SITE PLAN

bject number 19319FB
te 07/03/2020
awn by DES
ecked by KAB

C-102

7/2/2020 3:33:23 PM







Alaska Hangar

No. Description Date

SITE GRADING

 Project number
 19319FB

 Date
 07/03/2020

 Drawn by
 DES

 Checked by
 KAB

C-201

As Noted

2/2020 3:32:50 PM


SITE SECTION: PARALLEL TO BUILDING

NOTES:

- 1. SEE STRUCTURAL FOR FOUNDATION AND SLAB REQUIREMENTS.
- SEE SHEET C-502 FOR TYPICAL PAVEMENT SECTIONS, AND PLANS FOR PAVEMENT LOCATION.
- 3. SEPARATION GEOTEXTILE SHALL BE MIRAFI RS580i, INSTALLED TO MANUFACTURER'S INSTRUCTIONS. SEAMS SHALL BE OVERLAPPED A MINIMUM OF 36 INCHES OR SEWN.

452 452 448 448 444 444 FINISHED 440 440 HANGAR FFE=436.0' 436 436 432 432 428 428 424 STRUCTURAL FILL 424 12" MIN STRUCTURAL FILL 420 420 SEPARATION 416 416 POORLY-GRADED SAND WITH TRACE GRAVEL PER 1/23/2020 GEOTEXTILE 412 -ESTIMATED 412 WATER TABLE SUBSURFACE INVESTIGATION 408 408 0+10 1+00 2+00 3+00 3+80

B SITE SECTION: PERPENDICULAR TO BUILDING



456 SEEDING 452 SEEDING 452 448 444 444 440 440 436 436 432 432 428 428 FINISHED GROUND 424 424 GRADE 420 420 416 416 412 -ESTIMATED WATER TABLE 412 408 408

C SITE SECTION: DRIVEWAY

D SITE SECTION: ACROSS ACCESS ROAD





Alaska Hangar


o. Description Date


Fairbanks, AK


SITE SECTIONS

C-401

As Noted







NOTES:

APPLIES TO ACCESS
 DRIVEWAY AND PARKING
 AREA WEST OF BRL.

NOTES:

APPLIES TO ALL HMA
 PAVEMENT EAST OF BRL.

A C-502


NON-AIRFIELD HMA TYPICAL SECTION




AIRFIELD HMA APRON TYPICAL SECTION
N.T.S.



PCC-APRON TYPICAL SECTION



D DETAIL: TYPE 3 CURB



E DETAIL: VALLEY CURB

(E)

TS





Alaska Hangar


scription [

DETAIL (2 OF :	

roject number	19319FB
ate	07/03/2020
rawn by	DES
hecked by	KAB

C-502

As Noted



PER TYPICAL SECTION —

THICKENED EDGE EXPANSION JOINT

TYPICAL SECTION:

DRILL & GROUT

DOWEL IN NEW OR

EXISTING PAVEMENT

C-503

DETAIL: PCC APRON

LONGITUDINAL & TRANSVERSE JOINT

18"x1"Ø EPOXY COATED

LIGHTLY OIL ONE HALF OF DOWEL

STEEL DOWEL BAR,

BUILDING SLAB

SEE STRUCTURAL

C-503

TWO 2" COURSES

TACK COAT VERTICAL SURFACE AND SURFACE

OF FIRST AC COURSE -

C-503

N.T.S.

PAVEMENT

PCC SLABS

0.5"

DETAIL: PCC-HMA JOINT SEAL

- 1. DEPTH (D) AND WIDTH (W) OF CONCRETE GROOVE SHALL BE AS RECOMMENDED BY MANUFACTURER, EXCEPT THE DEPTH SHALL NOT BE LESS THAN 1.5 INCHES. WIDTH (W), 1/2 INCH MINIMUM TO 5/8 INCH MAXIMUM.
- 2. TOP OF PREFORMED SEAL SHALL BE 1/4 INCH, ±1/8 INCH BELOW THE PAVEMENT SURFACE. IN AREAS TO BE GROOVED, THE JOINT SEAL SHALL BE RECESSED BELOW THE DEPTH OF THE GROOVES.
- THE NOMINAL WIDTH OF THE UNCOMPRESSED SEAL SHALL BE 1 INCH.
- COMPRESSION SEALS MUST BE IN COMPRESSION AT ALL
- 5. DOWELS IN TRANSVERSE JOINTS SHALL NOT BE CLOSER THAN 18" TO LONGITUDINAL JOINTS; DOWELS IN LONGITUDINAL JOINTS SHALL NOT BE CLOSER THAN 12" TO TRANSVERSE JOINTS.
- THE PCC APRON CONCRETE SHALL BE PROPORTIONED TO ACHIEVE A 7-DAY FLEXURAL STRENGTH THAT MEETS A FLEXURAL STRENGTH OF 650 PSI PER ASTM C78. THE MIX SHALL BE DEVELOPED USING THE PROCEDURES CONTAINED IN THE PORTLAND CEMENT ASSOCIATION'S (PCA) PUBLICATION, "DESIGN AND CONTROL OF CONCRETE MIXTURES"
- 7. DOWEL BARS SHALL BE PLAIN STEEL BARS CONFORMING TO ASTM A615 AND SHALL BE FREE FROM BURRING OR OTHER DEFORMATION RESTRICTING SLIPPAGE IN THE CONCRETE. BEFORE DELIVERY TO THE CONSTRUCTION SITE EACH DOWEL BAR SHALL BE EPOXY COATED PER ASTM A1078. THE DOWELS SHALL BE COATED WITH A BOND-BREAKER RECOMMENDED BY THE MANUFACTURER





Hangar Alaska


Fairbanks,

No.	Description	Date


DETAILS (3 OF 5)


19319FB 07/03/2020 Drawn by DES

C-503 As Noted



7/2/2020 4:05:40 PM







49 TH X

AMEN AND BOOLEY

MAREN AND RADY

7/2/2020 19

80/00 SROYESSION

1'-6" VERTICAL OUTRIGGER (4) STRANDS OF BARBED - WIRE, EQUALLY SPACED

TRUSS ROD

- BRACE RAIL

BACKFILL WITH

NFS MATERIAL

- CONCRETE BACKFILL (TYP)

12' CENTER -TO - CENTER



Alaska Hangar

Fairbanks, AK

No.	Description	Date

DETAILS (5 OF 5)

Project number	19319FB
Date	07/03/2020
Drawn by	DES
Checked by	KAB

C-505

5 Noted

CD-001 DEMOLITION POINTS					
POINT #	NORTHING	EASTING	ELEVATION	DESCRIPTION	
101	3960343.77	1351884.68	431.00	BTM EX	
102	3960444.47	1351968.44	431.00	BTM EX	
103	3960450.76	1351960.87	431.00	BTM EX	
104	3960491.39	1351994.67	431.00	BTM EX	
105	3960406.21	1352097.09	431.00	BTM EX	
106	3960264.88	1351979.53	431.00	BTM EX	
107	3960181.09	1351940.92		FNC DEMO	
108	3960473.79	1352073.02		FNC DEMO	
109	3960514.26	1351631.82		FNC DEMO	
110	3960558.82	1351673.35		FNC DEMO	
111	3960529.49	1351600.31		SAWCUT	
112	3960606.78	1351672.56		SAWCUT	

	C-101 POINTS				
POINT #	NORTHING	EASTING	DESCRIPTION		
11	3960281.44	1351978.25	GRID D-7		
12	3960404.45	1352080.57	GRID A-7		
13	3960474.79	1351996.00	GRID A-1		
14	3960345.39	1351901.37	GRID D-2		

C-102 SITE FEATURES				
POINT #	NORTHING	EASTING	DESCRIPTION	
151	3960558.36	1351948.64	RIPRAP	
152	3960550.15	1351946.43	RIPRAP	
153	3960551.41	1351961.62	RIPRAP	
154	3960546.79	1351957.78	RIPRAP	
155	3960438.77	1352109.85	HINGE	
156	3960272.61	1351962.03	TANK	
157	3960251.50	1351987.40	TANK	
158	3960245.15	1351946.21	BOLLARD	
159	3960258.99	1351957.72	BOLLARD	
160	3960256.11	1351961.18	BOLLARD	
161	3960242.27	1351949.67	BOLLARD	
162	3960414.08	1351879.91	PVMT MRKG	
163	3960544.03	1351987.99	PVMT MRKG	
164	3960359.04	1351876.57	PVMT MRKG	
165	3960459.42	1351960.06	PVMT MRKG	
166	3960495.83	1352012.02	PVMT MRKG	
167	3960425.49	1352096.59	PVMT MRKG	

			G POINTS	T
POINT #	NORTHING	EASTING	ELEVATION	DESCRIPTION
201	3960529.49	1351600.31	434.28	EP
202	3960528.01	1351601.89	434.22	EP
203	3960530.15	1351636.14	433.97	EP
204	3960507.12	1351663.83	433.94	EP
205	3960388.42	1351806.54	433.50	EP
206	3960360.26	1351809.13	433.23	EP
207	3960334.61	1351787.79	433.14	EP
208	3960255.21	1351883.25	434.40	EP
209	3960218.86	1351926.95	434.40	EP
210	3960280.37	1351978.11	436.00	EP
211	3960410.17	1352086.07	435.50	EP
212	3960441.07	1352111.77	435.19	EP
213	3960556.82	1351972.62	434.69	EP
214	3960546.54	1351964.07	433.94	EP
215	3960545.14	1351962.90	433.94	EP
216	3960529.76	1351950.11	433.97	EP
217	3960409.46	1351850.05	433.97	EP
218	3960406.87	1351821.89	433.50	EP
219	3960525.57	1351679.18	433.94	EP
220	3960532.71	1351672.05	433.95	EP
221	3960539.90	1351666.99	433.97	EP
222	3960549.17	1351662.62	433.98	EP
223	3960558.94	1351660.08	434.00	EP
224	3960605.34	1351674.10	434.21	EP
225	3960606.78	1351672.56	434.28	EP
226	3960539.38	1351643.81	434.19	CROWN
227	3960516.35	1351671.51	434.18	CROWN
228	3960397.65	1351814.21	433.74	CROWN
229	3960524.60	1351605.55	433.15	EG
230	3960526.31	1351632.94	433.82	EG
231	3960503.28	1351660.64	433.79	EG
		1351803.34		
232	3960384.58		433.35	EG
233	3960363.45	1351805.28	433.08	EG
234	3960333.96	1351780.75	432.97	EG
235	3960251.37	1351880.05	434.25	EG
236	3960215.02	1351923.75	434.25	EG
237	3960560.01	1351968.77	434.54	EG
238	3960412.66	1351846.21	433.82	EG
239	3960410.72	1351825.08	433.35	EG
240	3960529.42	1351682.38	433.79	EG
241	3960601.93	1351677.76	433.20	EG
242	3960518.62	1351626.55	431.82	DITCH BOTT
243	3960510.92	1351620.17	431.82	DITCH BOTT
244	3960372.40	1351786.71	432.05	DITCH BOTT
245	3960376.89	1351796.95	432.05	DITCH BOTT
246	3960369.85	1351797.59	432.06	DITCH BOTT
247	3960331.37	1351752.59	432.10	DITCH BOTT
248	3960332.67	1351766.67	432.11	DITCH BOTT
249	3960235.99	1351867.26	432.25	DITCH BOTT
250	3960243.68	1351873.66	432.25	DITCH BOTT
251	3960316.71	1351934.41	436.00	FG
			435.89	

POINT #	NORTHING	EASTING	ELEVATION	DESCRIPTION
253	3960291.14	1351965.16	436.00	FG
254	3960286.91	1351961.64	435.89	FG
255	3960324.01	1351917.04	435.50	FG
256	3960344.48	1351892.43	435.50	FG
257	3960345.19	1351900.17	436.00	FG
258	3960376.85	1351919.35	435.50	FG
259	3960373.34	1351923.58	436.00	FG
260	3960388.38	1351928.94	435.50	FG
261	3960384.87	1351933.17	436.00	FG
262	3960435.39	1351968.04	435.50	FG
263	3960431.88	1351972.27	436.00	FG
264	3960443.41	1351981.86	436.00	FG
265	3960446.92	1351977.64	435.50	FG
266	3960453.22	1351970.07	435.50	FG
267	3960460.94	1351976.50	435.56	FG
268	3960457.42	1351980.73	436.00	FG
269	3960465.11	1351987.12	436.00	FG
270	3960468.63	1351982.89	435.56	FG
271	3960470.53	1351964.96	435.14	FG
272	3960478.22	1351971.36	435.14	FG
273	3960483.65	1351995.38	435.50	FG
274	3960410.81	1352085.30	435.48	FG
275	3960409.02	1352085.11	435.50	FG
276	3960446.37	1352081.65	435.10	FG
277	3960447.90	1352082.93	435.10	FG
278	3960273.97	1351985.79	435.93	FG
279	3960398.39	1352089.28	435.93	FG
280	3960404.79	1352081.59	436.00	FG
281	3960522.84	1351608.08	432.96	CMP IE
282	3960583.39	1351667.74	433.37	CMP IE

C-301 UTILITY POINTS					
POINT #	NORTHING	EASTING	DESCRIPTION		
301	3960597.69	1351599.73	WTR TIE IN		
302	3960351.21	1351896.07	WTR SVC		
303	3960563.92	1351657.08	GAS TIE-IN		
304	3960359.01	1351902.56	GAS SVC		
305	3960564.90	1351692.54	SS TIE-IN		
306	3960376.97	1351917.50	SS SVC		
307	3960374.15	1351920.84	SS CO		
308	3960557.97	1351679.81	ELEC TIE-IN		
309	3960366.61	1351908.88	ELEC SVC		





Alaska Hangar

Fairbanks, #

No.	Description	Date
\vdash		
\vdash		
-		
\vdash		

CONTROL POINTS

oject number	19319FB
ite	07/03/2020
awn by	DES
ecked by	KAB

C-701

As Noted

Table 1 - Summary of Soil Sample Analytical Results

	San	ıple Name	20FAI-LM-01	20FAI-LM-02	20FAI-LM-03	20FAI-LM-04	20FAI-LM-05	20FAI-LM-06	20FAI-LM-07	20FAI-	LM-08	20FAI-LM-09	20FAI-LM-10
	D	escription		Han	gar footprint, ≤1 f	t bgs		Hangar, 2.2 ft bgs	Utility center, 0.7 ft bgs	Utility center	er, 4.5 ft bg	Utility northwest, 4.5 ft bg	Utility southeast, 4.5 ft bg
Analyte	DEC Cleanup Level †	Units	7/23/20	7/23/20	7/23/20	7/23/20	7/23/20	7/23/20	7/23/20	7/24/20	7/24/20	7/24/20	7/24/20
Perfluoro-hexane sulfonic acid (PFHxS)		μg/kg	0.20 J	0.033 J	0.056 J	<0.20	1.1 J*	0.064 J	<0.20	0.034 J	0.033 J	0.090 J	0.081 J
Perfluorohexanoic acid (PFHxA)		μg/kg	<0.22	<0.20	<0.21	<0.20	0.39	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perfluoro-heptanoic acid (PFHpA)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perfluoro-nonanoic acid (PFNA)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perluoro-butane sulfonic acid (PFBS)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perfluorodecanoic acid (PFDA)		μg/kg	<0.22	0.027 J	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perfluoroundecanoic acid (PFUnA)		μg/kg	0.13 J	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perfluoro-dodecanoic acid (PFDoA)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perfluorotridecanoic acid (PFTrDA)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Perfluoro-tetradecanoic acid (PFTeA)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
N-Methyl perfluorooctane sulfonamidoacetic acid (N-MeFOSAA)		μg/kg	<2.2	<2.0	<2.1	<2.0	<2.8	<2.2	<2.0	<2.0	<2.0	<2.0	<2.4
N-Ethyl perfluorooctane sulfonamidoacetic acid (N-EtFOSAA)		μg/kg	<2.2	<2.0	<2.1	<2.0	<2.8	<2.2	<2.0	<2.0	<2.0	<2.0	<2.4
9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid (9CI-PF3ONS)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid (11Cl-PF3OUdS)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
4,8-Dioxa-3H-perfluorononanoic acid (DONA)		μg/kg	<0.22	<0.20	<0.21	<0.20	<0.28	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24
Hexafluoropropylene oxide dimer acid (HFPO-DA)		μg/kg	<0.28	<0.25	<0.26	<0.25	< 0.35	<0.27	<0.26	<0.25	<0.25	<0.25	<0.30
Perfluorooctanesulfonic acid (PFOS)	3.0	μg/kg	0.82 JH*	1.2	1.0	0.25 J	0.30 J	0.30 J	<0.51	<0.49	<0.51	<0.50	<0.60
Perfluorooctanoic acid (PFOA)	1.7	μg/kg	<0.22	<0.20	<0.21	<0.20	0.20 J	<0.22	<0.20	<0.20	<0.20	<0.20	<0.24

μg/kg micrograms per kilogram

[†] Alaska Department of Environmental Conservation (DEC) under-40-inch zone migration-to-groundwater soil cleanup level

⁻⁻ Cleanup level not established

bgs below ground surface

< Analyte not detected; listed as less than the reporting limit (RL) unless otherwise flagged due to quality-control (QC) failures.

J Estimated concentration, detected greater than the method detection limit (MDL) and less than the RL. Flag applied by the laboratory.

J* Result considered estimated due to a QC failure. Flag applied by Shannon & Wilson, Inc.

JH* Result considered estimated, biased high, due to a QC failure. Flag applied by Shannon & Wilson, Inc.

FIELD ACTIVITIES DAILY LOG

Date 7/23/20
Sheet 1 of 1
Project No. 102519 - 014
Project Name: BLOCK 4 Lot 2 FAI hangar
Field activity subject: Surface soil and subsurface soil Sample collection (PFAs)
Description of daily activities and events:
1430 - arrived onsite met with Katring to gain access to the
site, Matt arrived to unlock gate. Discussed securing the
gate. Told to lock gate after done and notify operations.
1440 - began Walking Site - Ashley and Adam. Adam setup
GPS For sample collection? Began digging to collect
samples. Adam collected GPS points for each location.
Ashiey collected the samples."
1520- Sample 20FAI- LAM -OZ collected → surface, Footprint
1526 - Sample 20FAI-LM-OI collected - surface, Footprint
1545 - Sample 20FAI - LM - 03 Wheted > surface, Footprint
1554 - Sample 20FAI - LM - 04 Collected > surface, footprint
1630 - sample 20 FAI-LM-DL collected & subsurface Footprint
1636 - Sample 20FAI-LM-O7 collected > surface, utilities
THE STATE STATE OF CONCESSION AND THE STATE OF THE STATE
11045 - offsite, called operations to inform them we were
offsite and gate had been locked
1655 - arrived at Office, samples were checked for
completness and stored with the chain-of- astody
In the environmental lab midge, to be Submitted
tomorrow (7/23/20).

Visitors on site: Katring LeMieux and Matt McClurg-helped with
site access
Changes from plans/specifications and other special orders and important decisions:
the 3 subsurface samples to be collected from the utilities
area will be collected 7/24/20, Samples to be submitted
tomorrow. Field duplicate will be collected 7/24/20.
Weather conditions: rain, Sunny Cloudy ~ 105-70°F
Important telephone calls: Phone of operations to inform them we had
Important telephone calls: <u>Phoned operations to inform them we had</u>
Personnel on site: Ashley Jaramillo and Adam Wyborny
Signature: Date: 7/23/30
(1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/

FIELD ACTIVITIES DAILY LOG

Date 7/24 /20 Sheet 1 of 1
Project No. 104519 - 014
Project Name: Block 4 Lot 2 FAI hangar
Field activity subject: SUBSURFACE SOIL Sample Collection
Description of daily activities and events:
1115-arrived onsite, Matt opened the gate Discussed
sewring the gate. Toid to lock gate after complete
and to call with when complete
Subsurface samples to collect. Crain advanced
3 holes using a gas powered aware. Holes
were forther advanted to collect samples
Using a hand auger.
1224 - 20FAI-LM - 88 (duplicate) and 20FAI-LM -08 (1234 timed)
collected -> subsurface, utilities
1232 - 20FAI - LM-10 collected > subsurface, utilities
1245 - 20FAI - LM - 09 Collected > subsurface, utilities
1305- pin Flagged sample Locations Names were
written on flags after discussions with
Kanina this manning.
1320 - backfilled holes to prestent tripping hazard
prove down supplies & packed truck
1415 - offsite, called mat to let him know we
were offsite.
1430 - arrived at office, samples checked and stored
with the chain-of-astroly in environmental
lab Ridge to be sto shipped \$127/20.
*
Visitors on site: Nat McCWrg- Nelped Waccess. GCI was also
working adjacent to site to splice line to job trailer.
Changes from plans/specifications and other special orders and important decisions:
Musunderstood shipping, samples are unable to ship
today. Will be shipped on 7/27/20
Weather conditions: Mps + Lu Cloude ~ 105° F.
Weather conditions: Mostly Cloudy ~ 15°F.
Important telephone calls: phone Mult to let him know we
Were offsite.
Personnel on site: Ashley Jaramillo and Craig Beeble
Signature: Date: 7/24/20

SOIL SAMPLE COLLECTION LOG

oject Nur	mber: 102519-014	Project Name: Block 4 Lot 2 FAI	Hange						Page of
ampler: [WI/ARW/C	AB	0						
				Sample	Depth	Sample	PID		
Date	Sample ID	Location		Time	(ft)	Type	Reading		Analyses
7/23	10-M1-1A76C	Hanger-SEquad	NIFL	1526	MOVALLA	ES	-	PEAS	537.1M X18
7/23	ODFAI-LIM-02	Handar-Negrad	NO.4FE	1520	WVAIN	ES			
7123	20FA1-LM-03	Harrack - NU) avad		1545	~0.7 A	ES	_		
1/23	20FA1-LIM-04	Handar-Swallad		1554	~0.66to	ES	-		- 1
H23	20FA1-LIM-05	Hangar - south half Hangar - north half			WI.BFE		-		
1/23	20FAI-LM-CL	Hangar-north half	10	1630 ·			_		
H23	20AH-HM-07	whilenes - center			NO.78		_		
124	20FAI-LM-08	utilities-center		1234	N4-45	PE ES			
124	20FA1-WM-09	vhuhes west		1245	N4-4.5	& ES			
124	20FA1-LM-10	Unithes - east		1232	44-45	A ES	_		
124	20FAI-LM-88	unites-center		1224	V44.5				V
						FI			
		W							
						F			
	-								
		•							
-				0					
									~
			11						
			1						
								x	
		5-							
				_		-			
_			1						
						-			



Environment Testing America

ANALYTICAL REPORT

Eurofins TestAmerica, Sacramento 880 Riverside Parkway West Sacramento, CA 95605 Tel: (916)373-5600

Laboratory Job ID: 320-63125-1

Client Project/Site: Fairbanks International Airport

For:

Shannon & Wilson, Inc 2355 Hill Rd. Fairbanks, Alaska 99709-5244

Attn: Marcy Nadel

Jamil Oltimo

Authorized for release by: 8/3/2020 1:14:01 PM

David Alltucker, Project Manager I (916)374-4383

David.Alltucker@Eurofinset.com

.....LINKS

Review your project results through

Total Access

Have a Question?



Visit us at:

www.eurofinsus.com/Env

The test results in this report meet all 2003 NELAC, 2009 TNI, and 2016 TNI requirements for accredited parameters, exceptions are noted in this report. This report may not be reproduced except in full, and with written approval from the laboratory. For questions please contact the Project Manager at the e-mail address or telephone number listed on this page.

This report has been electronically signed and authorized by the signatory. Electronic signature is intended to be the legally binding equivalent of a traditionally handwritten signature.

Results relate only to the items tested and the sample(s) as received by the laboratory.

2

3

_

6

0

9

4 4

12

13

Table of Contents

Cover Page	1
Table of Contents	2
Definitions/Glossary	3
Case Narrative	4
Detection Summary	5
Client Sample Results	7
Isotope Dilution Summary	18
QC Sample Results	19
QC Association Summary	23
Lab Chronicle	24
Certification Summary	28
Method Summary	29
Sample Summary	30
Chain of Custody	31
Receipt Checklists	32

4

6

8

10

12

13

Definitions/Glossary

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Qualifiers

		N/A	0
ш	U	V	J

POS

PQL

QC

RER

RPD

TEF

TEQ **TNTC**

RL

PRES

Positive / Present

Presumptive

Quality Control

Practical Quantitation Limit

Relative Error Ratio (Radiochemistry)

Toxicity Equivalent Factor (Dioxin) Toxicity Equivalent Quotient (Dioxin)

Too Numerous To Count

Reporting Limit or Requested Limit (Radiochemistry)

Relative Percent Difference, a measure of the relative difference between two points

Qualifier	Qualifier Description
F1	MS and/or MSD recovery exceeds control limits.
1	Value is EMPC (estimated maximum possible concentration).
.l	Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value

J	Result is less than the RE but greater than or equal to the MDE and the concentration is an approximate value.
Glossary	
Abbreviation	These commonly used abbreviations may or may not be present in this report.
¤	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent

Eurofins TestAmerica, Sacramento

8/3/2020

Case Narrative

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Job ID: 320-63125-1

Laboratory: Eurofins TestAmerica, Sacramento

Narrative

Job Narrative 320-63125-1

Receipt

The samples were received on 7/28/2020 11:15 AM; the samples arrived in good condition, and where required, properly preserved and on ice. The temperature of the cooler at receipt was 4.0° C.

LCMS

Method 537 (modified): The matrix spike (MS) recovery for Perfluorooctanesulfonic acid (PFOS) and 11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid in preparation batch 320-399186 and analytical batch 320-399992 was outside control limits. Sample matrix interference and/or non-homogeneity are suspected because the associated laboratory control sample (LCS) recovery was within acceptance limits.

Method 537 (modified): The "I" qualifier means the transition mass ratio for the indicated analyte was outside of the established ratio limits. The qualitative identification of the analyte has some degree of uncertainty. However, analyst judgement was used to positively identify the analyte in the following sample: 20FAI-LM-05 (320-63125-5).

No additional analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

General Chemistry

No analytical or quality issues were noted, other than those described in the Definitions/Glossary page.

Organic Prep

Method SHAKE: The following samples: 20FAI-LM-01 (320-63125-1), 20FAI-LM-02 (320-63125-2), 20FAI-LM-03 (320-63125-3), 20FAI-LM-04 (320-63125-4), 20FAI-LM-05 (320-63125-5), (320-63125-A-1 MS) and (320-63125-A-1 MSD) were slightly yellow after final volume.

No additional analytical or quality issues were noted, other than those described above or in the Definitions/Glossary page.

Job ID: 320-63125-1

Detection Summary Client: Shannon & Wilson, Inc Job ID: 320-63125-1 Project/Site: Fairbanks International Airport Lab Sample ID: 320-63125-1 Client Sample ID: 20FAI-LM-01 Analyte Result Qualifier RL **MDL** Unit Dil Fac D Method Prep Type Perfluoroundecanoic acid (PFUnA) 0.13 J 0.22 0.040 ug/Kg 1 \$\overline{\pi}\$ 537 (modified) Total/NA Perfluorohexanesulfonic acid (PFHxS) 0.20 J 0.22 0.034 ug/Kg 1 * 537 (modified) Total/NA Perfluorooctanesulfonic acid (PFOS) 1 537 (modified) Total/NA 0.82 F1 0.55 0.22 ug/Kg Client Sample ID: 20FAI-LM-02 Lab Sample ID: 320-63125-2 Analyte Result Qualifier **MDL** Unit Dil Fac D Method RL **Prep Type** 1 3 537 (modified) Perfluorodecanoic acid (PFDA) 0.027 J 0.20 0.022 ug/Kg Total/NA 1 537 (modified) Perfluorohexanesulfonic acid (PFHxS) 0.033 J 0.20 0.031 ug/Kg Total/NA 1 \$\pi\$ 537 (modified) Perfluorooctanesulfonic acid (PFOS) 1.2 Total/NA 0.51 0.20 ug/Kg Client Sample ID: 20FAI-LM-03 Lab Sample ID: 320-63125-3 Analyte Result Qualifier **MDL** Unit Dil Fac D Method RL Prep Type 0.056 J 0.032 ug/Kg 1 ≅ 537 (modified) Perfluorohexanesulfonic acid (PFHxS) 0.21 Total/NA Perfluorooctanesulfonic acid (PFOS) 1.0 0.52 0.21 ug/Kg 1 537 (modified) Total/NA Client Sample ID: 20FAI-LM-04 Lab Sample ID: 320-63125-4 Analyte Result Qualifier Dil Fac D Method RL MDL Unit **Prep Type** Perfluorooctanesulfonic acid (PFOS) 0.25 J 0.49 0.20 ug/Kg 1 \$\overline{\pi}\$ 537 (modified) Total/NA Client Sample ID: 20FAI-LM-05 Lab Sample ID: 320-63125-5 Analyte Result Qualifier RL **MDL** Unit Dil Fac D Method Prep Type Perfluorohexanoic acid (PFHxA) 0.39 0.28 0.059 ug/Kg 1 \$\overline{\pi}\$ 537 (modified) Total/NA

Client Sample ID: 20FALL M.	.06			Lah Sample ID: 320	1-63125-6
Perfluorooctanesulfonic acid (PFOS)	0.30 J	0.70	0.28 ug/Kg	1 🌣 537 (modified)	Total/NA
Perfluorohexanesulfonic acid (PFHxS)	1.1 I	0.28	0.043 ug/Kg	1 🌣 537 (modified)	Total/NA
Perfluorooctanoic acid (PFOA)	0.20 J	0.28	0.12 ug/Kg	1 🌣 537 (modified)	Total/NA

Analyte	Result	Qualifier	RL	MDL	Unit	Dil Fac	D	Method	Prep Type
Perfluorohexanesulfonic acid (PFHxS)	0.064	J	0.22	0.033	ug/Kg	1	₩	537 (modified)	Total/NA
Perfluorooctanesulfonic acid (PFOS)	0.30	J	0.54	0.22	ug/Kg	1	₩	537 (modified)	Total/NA

Client Sample ID: 20FAI-LM-07 Lab Sample ID: 320-63125-7

No Detections.

Client Sample ID: 20FAI-LM-08	Lab Sample ID: 320-63125-8

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Perfluorohexanesulfonic acid (PFHxS)	0.033 J	0.20	0.031 ug/Kg	1 \$\overline{\pi}\$ 537 (modified)	Total/NA

Client Sample ID: 20FAI-LM-09 Lab Sample ID: 320-63125-9

Analyte	Result (Qualifier	RL	MDL	Unit	Di	il Fac	D	Method	Prep Type	
Perfluorohexanesulfonic acid (PFHxS)	0.090	J	0.20	0.031	ug/Kg		1	₩	537 (modified)	Total/NA	

Client Sample ID: 20FAI-LM-10 Lab Sample ID: 320-63125-10

Analyte	Result Qualifie	r RL	MDL U	nit Dil F	ac D	Method	Prep Type
Perfluorohexanesulfonic acid (PFHxS)	0.081 J	0.24	0.037 uç	g/Kg	1 3	537 (modified)	Total/NA

This Detection Summary does not include radiochemical test results.

Eurofins TestAmerica, Sacramento

8/3/2020

Page 5 of 32

Detection Summary

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-88 Lab Sample ID: 320-63125-11

Analyte	Result Qualifier	RL	MDL Unit	Dil Fac D Method	Prep Type
Perfluorohexanesulfonic acid (PFHxS)	0.034 J	0.20	0.030 ug/Kg	1 🜣 537 (modified)	Total/NA

4

5

Q

9

4 4

12

14

1

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-01 Lab Sample ID: 320-63125-1

Method: 537 (modified) - Fluor Analyte		Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.22	0.046	ug/Kg	<u></u>	07/28/20 18:39	07/30/20 20:23	1
Perfluoroheptanoic acid (PFHpA)	ND		0.22	0.032	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
Perfluorooctanoic acid (PFOA)	ND		0.22	0.095	ug/Kg	☼	07/28/20 18:39	07/30/20 20:23	1
Perfluorononanoic acid (PFNA)	ND		0.22	0.040	ug/Kg	φ.	07/28/20 18:39	07/30/20 20:23	1
Perfluorodecanoic acid (PFDA)	ND		0.22	0.024	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
Perfluoroundecanoic acid (PFUnA)	0.13	J	0.22	0.040	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
Perfluorododecanoic acid (PFDoA)	ND		0.22	0.074	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
Perfluorotridecanoic acid (PFTriA)	ND		0.22	0.056	ug/Kg	☼	07/28/20 18:39	07/30/20 20:23	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.22	0.060	ug/Kg	☼	07/28/20 18:39	07/30/20 20:23	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.22	0.028	ug/Kg	\$	07/28/20 18:39	07/30/20 20:23	1
Perfluorohexanesulfonic acid (PFHxS)	0.20	J	0.22	0.034	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
Perfluorooctanesulfonic acid (PFOS)	0.82	F1	0.55		ug/Kg	₩	07/28/20 18:39	07/30/20 20:23	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.2	0.43	ug/Kg	\$	07/28/20 18:39	07/30/20 20:23	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.2	0.41	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.22	0.030	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.28	0.12	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND	F1	0.22	0.024	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.22	0.020	ug/Kg	₽	07/28/20 18:39	07/30/20 20:23	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	77		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C4 PFHpA	76		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C4 PFOA	76		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C5 PFNA	71		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C2 PFDA	69		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C2 PFUnA	67		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C2 PFDoA	72		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C2 PFTeDA	62		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C3 PFBS	68		25 - 150				07/28/20 18:39	07/30/20 20:23	1
1802 PFHxS	72		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C4 PFOS	65		25 - 150				07/28/20 18:39	07/30/20 20:23	1
d3-NMeFOSAA	73		25 - 150				07/28/20 18:39	07/30/20 20:23	1
d5-NEtFOSAA	63		25 - 150				07/28/20 18:39	07/30/20 20:23	1
13C3 HFPO-DA	69		25 - 150				07/28/20 18:30	07/30/20 20:23	1

Job ID: 320-63125-1

3

E

7

9

11

13

14

1

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-02

Lab Sample ID: 320-63125-2 Date Collected: 07/23/20 15:20 **Matrix: Solid**

Percent Solids: 90.8 Date Received: 07/28/20 11:15

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.20	0.043	ug/Kg	<u></u>	07/28/20 18:39	07/30/20 20:52	1
Perfluoroheptanoic acid (PFHpA)	ND		0.20	0.029	ug/Kg	≎	07/28/20 18:39	07/30/20 20:52	1
Perfluorooctanoic acid (PFOA)	ND		0.20	0.087	ug/Kg	₽	07/28/20 18:39	07/30/20 20:52	1
Perfluorononanoic acid (PFNA)	ND		0.20	0.036	ug/Kg		07/28/20 18:39	07/30/20 20:52	1
Perfluorodecanoic acid (PFDA)	0.027	J	0.20	0.022	ug/Kg	≎	07/28/20 18:39	07/30/20 20:52	1
Perfluoroundecanoic acid (PFUnA)	ND		0.20	0.036	ug/Kg	₩	07/28/20 18:39	07/30/20 20:52	1
Perfluorododecanoic acid (PFDoA)	ND		0.20	0.068	ug/Kg		07/28/20 18:39	07/30/20 20:52	1
Perfluorotridecanoic acid (PFTriA)	ND		0.20	0.052	ug/Kg	≎	07/28/20 18:39	07/30/20 20:52	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.20	0.055	ug/Kg	≎	07/28/20 18:39	07/30/20 20:52	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.20	0.025	ug/Kg		07/28/20 18:39	07/30/20 20:52	1
Perfluorohexanesulfonic acid (PFHxS)	0.033	J	0.20	0.031	ug/Kg	₩	07/28/20 18:39	07/30/20 20:52	1
Perfluorooctanesulfonic acid (PFOS)	1.2		0.51	0.20	ug/Kg	₩	07/28/20 18:39	07/30/20 20:52	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.0	0.40	ug/Kg	₽	07/28/20 18:39	07/30/20 20:52	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.0	0.38	ug/Kg	₩	07/28/20 18:39	07/30/20 20:52	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.20	0.027	ug/Kg	₩	07/28/20 18:39	07/30/20 20:52	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.25	0.11	ug/Kg	\$	07/28/20 18:39	07/30/20 20:52	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.20	0.022	ug/Kg	₩	07/28/20 18:39	07/30/20 20:52	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.20	0.018	ug/Kg	₩	07/28/20 18:39	07/30/20 20:52	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	87		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C4 PFHpA	89		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C4 PFOA	89		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C5 PFNA	93		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C2 PFDA	92		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C2 PFUnA	79		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C2 PFDoA	84		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C2 PFTeDA	70		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C3 PFBS	83		25 - 150				07/28/20 18:39	07/30/20 20:52	1
1802 PFHxS	88		25 - 150				07/28/20 18:39	07/30/20 20:52	1
13C4 PFOS	77		25 - 150				07/28/20 18:39	07/30/20 20:52	1
d3-NMeFOSAA	81		25 - 150					07/30/20 20:52	1
d5-NEtFOSAA	83		25 - 150					07/30/20 20:52	1
13C3 HFPO-DA	80		25 - 150					07/30/20 20:52	1

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-03

Date Collected: 07/23/20 15:45 Date Received: 07/28/20 11:15 Lab Sample ID: 320-63125-3

Matrix: Solid

Percent Solids: 93.2

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.21	0.044	ug/Kg	₩	07/28/20 18:39	07/30/20 21:01	1
Perfluoroheptanoic acid (PFHpA)	ND		0.21	0.030	ug/Kg	₩	07/28/20 18:39	07/30/20 21:01	1
Perfluorooctanoic acid (PFOA)	ND		0.21	0.090	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
Perfluorononanoic acid (PFNA)	ND		0.21	0.037	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
Perfluorodecanoic acid (PFDA)	ND		0.21	0.023	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
Perfluoroundecanoic acid (PFUnA)	ND		0.21	0.037	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
Perfluorododecanoic acid (PFDoA)	ND		0.21	0.070	ug/Kg		07/28/20 18:39	07/30/20 21:01	1
Perfluorotridecanoic acid (PFTriA)	ND		0.21	0.053	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.21	0.056	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.21	0.026	ug/Kg		07/28/20 18:39	07/30/20 21:01	1
Perfluorohexanesulfonic acid (PFHxS)	0.056	J	0.21	0.032	ug/Kg	≎	07/28/20 18:39	07/30/20 21:01	1
Perfluorooctanesulfonic acid (PFOS)	1.0		0.52	0.21	ug/Kg	₽	07/28/20 18:39	07/30/20 21:01	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.1	0.41	ug/Kg	₽	07/28/20 18:39	07/30/20 21:01	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.1	0.39	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.21	0.028	ug/Kg	☼	07/28/20 18:39	07/30/20 21:01	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.26		ug/Kg	₽	07/28/20 18:39	07/30/20 21:01	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.21	0.023	ug/Kg	≎	07/28/20 18:39	07/30/20 21:01	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.21	0.019	ug/Kg	≎	07/28/20 18:39	07/30/20 21:01	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	90		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C4 PFHpA	85		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C4 PFOA	90		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C5 PFNA	91		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C2 PFDA	84		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C2 PFUnA	84		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C2 PFDoA	81		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C2 PFTeDA	74		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C3 PFBS	84		25 - 150				07/28/20 18:39	07/30/20 21:01	1
1802 PFHxS	83		25 - 150				07/28/20 18:39	07/30/20 21:01	1
13C4 PFOS	77		25 - 150				07/28/20 18:39	07/30/20 21:01	1
d3-NMeFOSAA	86		25 - 150					07/30/20 21:01	1
d5-NEtFOSAA	83		25 - 150					07/30/20 21:01	1
13C3 HFPO-DA	80		25 - 150					07/30/20 21:01	1

3

5

7

9

11

13

14

15

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-04

Lab Sample ID: 320-63125-4 Date Collected: 07/23/20 15:54 Matrix: Solid Date Received: 07/28/20 11:15 Percent Solids: 94.1

Method: 537 (modified) - Fluorinated Alkyl Substances Result Qualifier Dil Fac Analyte RL **MDL** Unit D Prepared Analyzed ₩ Perfluorohexanoic acid (PFHxA) $\overline{\mathsf{ND}}$ 0.20 0.041 ug/Kg 07/28/20 18:39 07/30/20 21:10 Perfluoroheptanoic acid (PFHpA) ND 0.20 0.029 ug/Kg 07/28/20 18:39 07/30/20 21:10 Perfluorooctanoic acid (PFOA) ND 07/28/20 18:39 07/30/20 21:10 0.20 0.085 ug/Kg Perfluorononanoic acid (PFNA) ND 0.20 0.036 ug/Kg 07/28/20 18:39 07/30/20 21:10 Perfluorodecanoic acid (PFDA) ND 0.022 ug/Kg 07/28/20 18:39 07/30/20 21:10 0.20 Perfluoroundecanoic acid (PFUnA) ND 0.20 0.036 ug/Kg 07/28/20 18:39 07/30/20 21:10 0.066 ug/Kg Perfluorododecanoic acid (PFDoA) ND 0.20 07/28/20 18:39 07/30/20 21:10 Perfluorotridecanoic acid (PFTriA) ND 0.20 0.050 ug/Kg 07/28/20 18:39 07/30/20 21:10 ND 07/28/20 18:39 07/30/20 21:10 Perfluorotetradecanoic acid (PFTeA) 0.20 0.053 ug/Kg Perfluorobutanesulfonic acid (PFBS) ND 0.025 ug/Kg 07/28/20 18:39 07/30/20 21:10 0.20 Perfluorohexanesulfonic acid (PFHxS) ND 0.20 0.031 ug/Kg 07/28/20 18:39 07/30/20 21:10 0.49 0.20 07/28/20 18:39 07/30/20 21:10 Perfluorooctanesulfonic acid 0.25 J ug/Kg (PFOS) ND 2.0 0.39 ug/Kg 07/28/20 18:39 07/30/20 21:10 N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA) ND 20 0.37 ug/Kg © 07/28/20 18:39 07/30/20 21:10 N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA) ND 0.20 © 07/28/20 18:39 07/30/20 21:10 0.027 ug/Kg 9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid ND 0.25 0.11 ug/Kg © 07/28/20 18:39 07/30/20 21:10 Hexafluoropropylene Oxide Dimer Acid (HFPO-DA) 0.022 ug/Kg 07/28/20 18:39 07/30/20 21:10 11-Chloroeicosafluoro-3-oxaundecan ND 0.20 e-1-sulfonic acid ND 0.20 0.018 ug/Kg © 07/28/20 18:39 07/30/20 21:10 4,8-Dioxa-3H-perfluorononanoic acid (ADONA) Isotope Dilution %Recovery Qualifier Limits Prepared Analyzed Dil Fac 07/28/20 18:39 07/30/20 21:10 13C2 PFHxA 96 25 - 150 90 13C4 PFHpA 25 - 150 07/28/20 18:39 07/30/20 21:10 13C4 PFOA 92 25 - 150 07/28/20 18:39 07/30/20 21:10 13C5 PFNA 93 25 - 150 07/28/20 18:39 07/30/20 21:10 13C2 PFDA 91 25 - 150 07/28/20 18:39 07/30/20 21:10 13C2 PFUnA 77 25 - 150 07/28/20 18:39 07/30/20 21:10 13C2 PFDoA 87 25 - 150 07/28/20 18:39 07/30/20 21:10 13C2 PFTeDA 79 25 - 150 07/28/20 18:39 07/30/20 21:10 13C3 PFBS 85 25 - 150 07/28/20 18:39 07/30/20 21:10 1802 PFHxS 84 25 - 150 07/28/20 18:39 07/30/20 21:10 13C4 PFOS 81 25 - 150 07/28/20 18:39 07/30/20 21:10 d3-NMeFOSAA 100 25 - 150 07/28/20 18:39 07/30/20 21:10 25 - 150 d5-NEtFOSAA 92 07/28/20 18:39 07/30/20 21:10 07/28/20 18:39 07/30/20 21:10 13C3 HFPO-DA 86 25 - 150

6

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-05

Lab Sample ID: 320-63125-5 Date Collected: 07/23/20 16:22 **Matrix: Solid** Date Received: 07/28/20 11:15

Percent Solids: 69.2

Analyte	Result	Qualifier	RL	MDL		D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	0.39		0.28	0.059	ug/Kg	<u> </u>	07/28/20 18:39	07/30/20 21:39	1
Perfluoroheptanoic acid (PFHpA)	ND		0.28	0.041	ug/Kg	☼	07/28/20 18:39	07/30/20 21:39	1
Perfluorooctanoic acid (PFOA)	0.20	J	0.28	0.12	ug/Kg	₩	07/28/20 18:39	07/30/20 21:39	1
Perfluorononanoic acid (PFNA)	ND		0.28	0.050	ug/Kg	₩	07/28/20 18:39	07/30/20 21:39	1
Perfluorodecanoic acid (PFDA)	ND		0.28	0.031	ug/Kg	₩	07/28/20 18:39	07/30/20 21:39	1
Perfluoroundecanoic acid (PFUnA)	ND		0.28	0.050	ug/Kg	₩	07/28/20 18:39	07/30/20 21:39	1
Perfluorododecanoic acid (PFDoA)	ND		0.28	0.094	ug/Kg		07/28/20 18:39	07/30/20 21:39	1
Perfluorotridecanoic acid (PFTriA)	ND		0.28	0.071	ug/Kg	☼	07/28/20 18:39	07/30/20 21:39	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.28	0.076	ug/Kg	₩	07/28/20 18:39	07/30/20 21:39	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.28	0.035	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
Perfluorohexanesulfonic acid (PFHxS)	1.1	I	0.28	0.043	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
Perfluorooctanesulfonic acid (PFOS)	0.30	J	0.70	0.28	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.8	0.55	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.8	0.52	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.28	0.038	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.35	0.15	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.28	0.031	ug/Kg	₩	07/28/20 18:39	07/30/20 21:39	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.28	0.025	ug/Kg	₽	07/28/20 18:39	07/30/20 21:39	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	90		25 - 150				07/28/20 18:39	07/30/20 21:39	
13C4 PFHpA	84		25 - 150				07/28/20 18:39	07/30/20 21:39	1
13C4 PFOA	89		25 - 150				07/28/20 18:39	07/30/20 21:39	1
13C5 PFNA	93		25 - 150				07/28/20 18:39	07/30/20 21:39	
13C2 PFDA	84		25 - 150				07/28/20 18:39	07/30/20 21:39	1
13C2 PFUnA	70		25 - 150				07/28/20 18:39	07/30/20 21:39	1
13C2 PFDoA	72		25 - 150				07/28/20 18:39	07/30/20 21:39	1
13C2 PFTeDA	64		25 - 150				07/28/20 18:39	07/30/20 21:39	-
13C3 PFBS	87		25 - 150				07/28/20 18:39	07/30/20 21:39	
1802 PFHxS	95		25 - 150				07/28/20 18:39	07/30/20 21:39	
13C4 PFOS	90		25 - 150				07/28/20 18:39	07/30/20 21:39	
d3-NMeFOSAA	72		25 - 150				07/28/20 18:39	07/30/20 21:39	1
d5-NEtFOSAA	71		25 - 150				07/28/20 18:39	07/30/20 21:39	
13C3 HFPO-DA	82		25 - 150				07/29/20 19:20	07/30/20 21:39	1

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-06

Lab Sample ID: 320-63125-6 Date Collected: 07/23/20 16:30

Matrix: Solid Date Received: 07/28/20 11:15 Percent Solids: 91.0

Method: 537 (modified) - Fluor Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.22	0.045	ug/Kg	<u> </u>	07/28/20 18:39	07/30/20 21:48	1
Perfluoroheptanoic acid (PFHpA)	ND		0.22	0.031	ug/Kg	☼	07/28/20 18:39	07/30/20 21:48	1
Perfluorooctanoic acid (PFOA)	ND		0.22	0.092	ug/Kg	≎	07/28/20 18:39	07/30/20 21:48	1
Perfluorononanoic acid (PFNA)	ND		0.22	0.039	ug/Kg	☆	07/28/20 18:39	07/30/20 21:48	1
Perfluorodecanoic acid (PFDA)	ND		0.22	0.024	ug/Kg	≎	07/28/20 18:39	07/30/20 21:48	1
Perfluoroundecanoic acid (PFUnA)	ND		0.22	0.039	ug/Kg	≎	07/28/20 18:39	07/30/20 21:48	1
Perfluorododecanoic acid (PFDoA)	ND		0.22	0.072	ug/Kg		07/28/20 18:39	07/30/20 21:48	1
Perfluorotridecanoic acid (PFTriA)	ND		0.22	0.055	ug/Kg	₩	07/28/20 18:39	07/30/20 21:48	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.22	0.058	ug/Kg	₩	07/28/20 18:39	07/30/20 21:48	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.22	0.027	ug/Kg		07/28/20 18:39	07/30/20 21:48	1
Perfluorohexanesulfonic acid (PFHxS)	0.064	J	0.22	0.033	ug/Kg	₩	07/28/20 18:39	07/30/20 21:48	1
Perfluorooctanesulfonic acid (PFOS)	0.30	J	0.54	0.22	ug/Kg	₩	07/28/20 18:39	07/30/20 21:48	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.2	0.42	ug/Kg	\$	07/28/20 18:39	07/30/20 21:48	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.2	0.40	ug/Kg	₩	07/28/20 18:39	07/30/20 21:48	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.22		ug/Kg	☼	07/28/20 18:39	07/30/20 21:48	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.27	0.12	ug/Kg	☼	07/28/20 18:39	07/30/20 21:48	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.22		ug/Kg	‡	07/28/20 18:39	07/30/20 21:48	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.22	0.019	ug/Kg	₩	07/28/20 18:39	07/30/20 21:48	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	101		25 - 150				07/28/20 18:39	07/30/20 21:48	1
13C4 PFHpA	91		25 - 150				07/28/20 18:39	07/30/20 21:48	1
13C4 PFOA	93		25 - 150				07/28/20 18:39	07/30/20 21:48	1
13C5 PFNA	98		25 - 150				07/28/20 18:39	07/30/20 21:48	1
13C2 PFDA	92		25 - 150				07/28/20 18:39	07/30/20 21:48	
13C2 PFUnA	83		25 - 150				07/28/20 18:39	07/30/20 21:48	
13C2 PFDoA	86		25 - 150				07/28/20 18:39	07/30/20 21:48	• • • • • • • • • • • • • • • • • • • •
13C2 PFTeDA	81		25 - 150				07/28/20 18:39	07/30/20 21:48	1
13C3 PFBS	86		25 - 150				07/28/20 18:39	07/30/20 21:48	1
1802 PFHxS	92		25 - 150				07/28/20 18:39	07/30/20 21:48	1
13C4 PFOS	88		25 - 150				07/28/20 18:39	07/30/20 21:48	-
d3-NMeFOSAA	99		25 - 150				07/28/20 18:39	07/30/20 21:48	1
d5-NEtFOSAA	95		25 - 150				07/28/20 18:39	07/30/20 21:48	

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-07 Lab Sample ID: 320-63125-7

Date Collected: 07/23/20 16:36 **Matrix: Solid** Date Received: 07/28/20 11:15 Percent Solids: 91.0

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.20	0.043	ug/Kg	<u> </u>	07/28/20 18:39	07/30/20 21:57	1
Perfluoroheptanoic acid (PFHpA)	ND		0.20	0.030	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Perfluorooctanoic acid (PFOA)	ND		0.20	0.088	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Perfluorononanoic acid (PFNA)	ND		0.20	0.037	ug/Kg		07/28/20 18:39	07/30/20 21:57	1
Perfluorodecanoic acid (PFDA)	ND		0.20	0.022	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Perfluoroundecanoic acid (PFUnA)	ND		0.20	0.037	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Perfluorododecanoic acid (PFDoA)	ND		0.20	0.068	ug/Kg		07/28/20 18:39	07/30/20 21:57	1
Perfluorotridecanoic acid (PFTriA)	ND		0.20	0.052	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.20	0.055	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.20	0.026	ug/Kg	-	07/28/20 18:39	07/30/20 21:57	1
Perfluorohexanesulfonic acid (PFHxS)	ND		0.20	0.032	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Perfluorooctanesulfonic acid (PFOS)	ND		0.51		ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.0		ug/Kg		07/28/20 18:39	07/30/20 21:57	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.0	0.38	ug/Kg	≎	07/28/20 18:39	07/30/20 21:57	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.20	0.028	ug/Kg	₩	07/28/20 18:39	07/30/20 21:57	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.26	0.11	ug/Kg	₽	07/28/20 18:39	07/30/20 21:57	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.20	0.022	ug/Kg	₽	07/28/20 18:39	07/30/20 21:57	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.20	0.018	ug/Kg	☼	07/28/20 18:39	07/30/20 21:57	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	86		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C4 PFHpA	78		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C4 PFOA	81		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C5 PFNA	86		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C2 PFDA	77		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C2 PFUnA	72		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C2 PFDoA	80		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C2 PFTeDA	67		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C3 PFBS	77		25 - 150				07/28/20 18:39	07/30/20 21:57	1
1802 PFHxS	83		25 - 150				07/28/20 18:39	07/30/20 21:57	1
13C4 PFOS	75		25 - 150					07/30/20 21:57	1
d3-NMeFOSAA	85		25 - 150					07/30/20 21:57	1
d5-NEtFOSAA	82		25 - 150					07/30/20 21:57	1
13C3 HFPO-DA	74		25 - 150					07/30/20 21:57	1

Job ID: 320-63125-1

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-08

Date Collected: 07/24/20 12:34 Date Received: 07/28/20 11:15

Lab Sample ID: 320-63125-8

Matrix: Solid

Percent Solids: 92.5

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.20	0.043	ug/Kg	<u> </u>	07/28/20 18:39	07/30/20 22:07	1
Perfluoroheptanoic acid (PFHpA)	ND		0.20	0.029	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
Perfluorooctanoic acid (PFOA)	ND		0.20	0.087	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
Perfluorononanoic acid (PFNA)	ND		0.20	0.037	ug/Kg		07/28/20 18:39	07/30/20 22:07	1
Perfluorodecanoic acid (PFDA)	ND		0.20	0.022	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
Perfluoroundecanoic acid (PFUnA)	ND		0.20	0.037	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
Perfluorododecanoic acid (PFDoA)	ND		0.20	0.068	ug/Kg		07/28/20 18:39	07/30/20 22:07	1
Perfluorotridecanoic acid (PFTriA)	ND		0.20	0.052	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.20		ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.20		ug/Kg	-	07/28/20 18:39	07/30/20 22:07	1
Perfluorohexanesulfonic acid (PFHxS)	0.033	J	0.20			₩	07/28/20 18:39	07/30/20 22:07	1
Perfluorooctanesulfonic acid (PFOS)	ND		0.51	0.20	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.0	0.40	ug/Kg		07/28/20 18:39	07/30/20 22:07	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.0	0.38	ug/Kg	≎	07/28/20 18:39	07/30/20 22:07	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.20	0.027	ug/Kg	≎	07/28/20 18:39	07/30/20 22:07	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.25	0.11	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.20	0.022	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.20	0.018	ug/Kg	₩	07/28/20 18:39	07/30/20 22:07	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	100	<u> </u>	25 - 150				07/28/20 18:39	07/30/20 22:07	
13C4 PFHpA	93		25 - 150				07/28/20 18:39	07/30/20 22:07	1
13C4 PFOA	96		25 - 150				07/28/20 18:39	07/30/20 22:07	1
13C5 PFNA	94		25 - 150				07/28/20 18:39	07/30/20 22:07	1
13C2 PFDA	95		25 - 150				07/28/20 18:39	07/30/20 22:07	1
13C2 PFUnA	92		25 - 150					07/30/20 22:07	1
13C2 PFDoA	96		25 - 150					07/30/20 22:07	1
13C2 PFTeDA	84		25 ₋ 150					07/30/20 22:07	1
13C3 PFBS	88		25 ₋ 150					07/30/20 22:07	1
1802 PFHxS	98		25 - 150					07/30/20 22:07	
13C4 PFOS	89		25 - 150 25 - 150					07/30/20 22:07	1
d3-NMeFOSAA	100		25 - 150 25 - 150					07/30/20 22:07	1
d5-NEtFOSAA	95		25 - 150 25 - 150					07/30/20 22:07	· · · · · · · · 1
U.SENICICU.SAA	95		/O = 10U				01/20/20 10.39	01/30/20 22.0/	7

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-09

Date Collected: 07/24/20 12:45 Date Received: 07/28/20 11:15 Lab Sample ID: 320-63125-9

Matrix: Solid

Percent Solids: 91.8

Job ID: 320-63125-1

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.20	0.042	ug/Kg	<u> </u>	07/28/20 18:39	07/30/20 22:16	1
Perfluoroheptanoic acid (PFHpA)	ND		0.20	0.029	ug/Kg	₩	07/28/20 18:39	07/30/20 22:16	1
Perfluorooctanoic acid (PFOA)	ND		0.20	0.086	ug/Kg	☆	07/28/20 18:39	07/30/20 22:16	1
Perfluorononanoic acid (PFNA)	ND		0.20	0.036	ug/Kg		07/28/20 18:39	07/30/20 22:16	1
Perfluorodecanoic acid (PFDA)	ND		0.20	0.022	ug/Kg	☼	07/28/20 18:39	07/30/20 22:16	1
Perfluoroundecanoic acid (PFUnA)	ND		0.20	0.036	ug/Kg	☼	07/28/20 18:39	07/30/20 22:16	1
Perfluorododecanoic acid (PFDoA)	ND		0.20	0.067	ug/Kg		07/28/20 18:39	07/30/20 22:16	1
Perfluorotridecanoic acid (PFTriA)	ND		0.20	0.051	ug/Kg	≎	07/28/20 18:39	07/30/20 22:16	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.20	0.054	ug/Kg	₩	07/28/20 18:39	07/30/20 22:16	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.20	0.025	ug/Kg	₽	07/28/20 18:39	07/30/20 22:16	1
Perfluorohexanesulfonic acid (PFHxS)	0.090	J	0.20	0.031	ug/Kg	₩	07/28/20 18:39	07/30/20 22:16	1
Perfluorooctanesulfonic acid (PFOS)	ND		0.50	0.20	ug/Kg	≎	07/28/20 18:39	07/30/20 22:16	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.0	0.39	ug/Kg		07/28/20 18:39	07/30/20 22:16	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.0	0.37	ug/Kg	☼	07/28/20 18:39	07/30/20 22:16	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.20	0.027	ug/Kg	₩	07/28/20 18:39	07/30/20 22:16	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.25	0.11	ug/Kg	₿	07/28/20 18:39	07/30/20 22:16	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.20	0.022	ug/Kg	₽	07/28/20 18:39	07/30/20 22:16	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.20	0.018	ug/Kg	☼	07/28/20 18:39	07/30/20 22:16	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	88		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C4 PFHpA	89		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C4 PFOA	88		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C5 PFNA	91		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C2 PFDA	89		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C2 PFUnA	85		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C2 PFDoA	87		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C2 PFTeDA	76		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C3 PFBS	82		25 - 150				07/28/20 18:39	07/30/20 22:16	1
1802 PFHxS	88		25 - 150				07/28/20 18:39	07/30/20 22:16	1
13C4 PFOS	77		25 - 150					07/30/20 22:16	1
d3-NMeFOSAA	99		25 - 150					07/30/20 22:16	1
d5-NEtFOSAA	87		25 - 150					07/30/20 22:16	1

2

4

6

8

10

12

14

15

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-10 Lab Sample ID: 320-63125-10

Date Collected: 07/24/20 12:32 **Matrix: Solid** Date Received: 07/28/20 11:15 Percent Solids: 76.7

Analyte	Result	Qualifier	RL	MDL		D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.24	0.050	ug/Kg	<u> </u>	07/28/20 18:39	07/30/20 22:26	1
Perfluoroheptanoic acid (PFHpA)	ND		0.24	0.035	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
Perfluorooctanoic acid (PFOA)	ND		0.24	0.10	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
Perfluorononanoic acid (PFNA)	ND		0.24	0.043	ug/Kg	φ.	07/28/20 18:39	07/30/20 22:26	1
Perfluorodecanoic acid (PFDA)	ND		0.24	0.026	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
Perfluoroundecanoic acid (PFUnA)	ND		0.24	0.043	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
Perfluorododecanoic acid (PFDoA)	ND		0.24	0.080	ug/Kg	φ.	07/28/20 18:39	07/30/20 22:26	1
Perfluorotridecanoic acid (PFTriA)	ND		0.24	0.061	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.24	0.065	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.24	0.030	ug/Kg		07/28/20 18:39	07/30/20 22:26	1
Perfluorohexanesulfonic acid (PFHxS)	0.081	J	0.24	0.037	ug/Kg	≎	07/28/20 18:39	07/30/20 22:26	1
Perfluorooctanesulfonic acid (PFOS)	ND		0.60	0.24	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.4	0.47	ug/Kg		07/28/20 18:39	07/30/20 22:26	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.4	0.44	ug/Kg	≎	07/28/20 18:39	07/30/20 22:26	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.24	0.032	ug/Kg	₩	07/28/20 18:39	07/30/20 22:26	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.30	0.13	ug/Kg	₽	07/28/20 18:39	07/30/20 22:26	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.24	0.026	ug/Kg	₽	07/28/20 18:39	07/30/20 22:26	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.24	0.022	ug/Kg	₽	07/28/20 18:39	07/30/20 22:26	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	89		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C4 PFHpA	83		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C4 PFOA	82		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C5 PFNA	94		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C2 PFDA	86		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C2 PFUnA	82		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C2 PFDoA	77		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C2 PFTeDA	71		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C3 PFBS	85		25 - 150				07/28/20 18:39	07/30/20 22:26	1
1802 PFHxS	86		25 - 150				07/28/20 18:39	07/30/20 22:26	1
13C4 PFOS	82		25 - 150				07/28/20 18:39	07/30/20 22:26	1
d3-NMeFOSAA	98		25 - 150					07/30/20 22:26	1
d5-NEtFOSAA	88		25 - 150					07/30/20 22:26	1

Job ID: 320-63125-1

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-88 Lab Sample ID: 320-63125-11

Date Collected: 07/24/20 12:24 **Matrix: Solid** Date Received: 07/28/20 11:15 Percent Solids: 94.4

Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.20	0.041	ug/Kg	<u> </u>	07/28/20 18:39	07/30/20 22:35	1
Perfluoroheptanoic acid (PFHpA)	ND		0.20	0.029	ug/Kg	☼	07/28/20 18:39	07/30/20 22:35	1
Perfluorooctanoic acid (PFOA)	ND		0.20	0.085	ug/Kg	₩	07/28/20 18:39	07/30/20 22:35	1
Perfluorononanoic acid (PFNA)	ND		0.20	0.035	ug/Kg	₽	07/28/20 18:39	07/30/20 22:35	1
Perfluorodecanoic acid (PFDA)	ND		0.20	0.022	ug/Kg	☼	07/28/20 18:39	07/30/20 22:35	1
Perfluoroundecanoic acid (PFUnA)	ND		0.20	0.035	ug/Kg	₩	07/28/20 18:39	07/30/20 22:35	1
Perfluorododecanoic acid (PFDoA)	ND		0.20	0.066	ug/Kg	φ.	07/28/20 18:39	07/30/20 22:35	1
Perfluorotridecanoic acid (PFTriA)	ND		0.20	0.050	ug/Kg	₩	07/28/20 18:39	07/30/20 22:35	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.20	0.053	ug/Kg	₩	07/28/20 18:39	07/30/20 22:35	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.20	0.025	ug/Kg		07/28/20 18:39	07/30/20 22:35	1
Perfluorohexanesulfonic acid (PFHxS)	0.034	J	0.20	0.030	ug/Kg	₩	07/28/20 18:39	07/30/20 22:35	1
Perfluorooctanesulfonic acid (PFOS)	ND		0.49	0.20	ug/Kg	₩	07/28/20 18:39	07/30/20 22:35	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.0	0.38	ug/Kg	₽	07/28/20 18:39	07/30/20 22:35	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.0	0.36	ug/Kg	₽	07/28/20 18:39	07/30/20 22:35	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.20		ug/Kg	₽	07/28/20 18:39	07/30/20 22:35	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.25	0.11	ug/Kg	₽	07/28/20 18:39	07/30/20 22:35	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.20	0.022	ug/Kg	₽	07/28/20 18:39	07/30/20 22:35	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.20	0.018	ug/Kg	₽	07/28/20 18:39	07/30/20 22:35	1
Isotope Dilution	%Recovery	Qualifier	Limits				Prepared	Analyzed	Dil Fac
13C2 PFHxA	90		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C4 PFHpA	89		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C4 PFOA	90		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C5 PFNA	91		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C2 PFDA	88		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C2 PFUnA	86		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C2 PFDoA	86		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C2 PFTeDA	87		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C3 PFBS	84		25 - 150				07/28/20 18:39	07/30/20 22:35	1
1802 PFHxS	87		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C4 PFOS	84		25 - 150				07/28/20 18:39	07/30/20 22:35	1
d3-NMeFOSAA	89		25 - 150				07/28/20 18:39	07/30/20 22:35	1
d5-NEtFOSAA	88		25 - 150				07/28/20 18:39	07/30/20 22:35	1
13C3 HFPO-DA	84		25 - 150				07/28/20 18:39	07/30/20 22:35	1

Isotope Dilution Summary

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Method: 537 (modified) - Fluorinated Alkyl Substances

Matrix: Solid Prep Type: Total/NA

			Perce	ent Isotope	Dilution Re	covery (Ac	ceptance L	imits)			
		PFHxA	C4PFHA	PFOA	PFNA	PFDA	PFUnA	PFDoA	PFTDA		
Lab Sample ID	Client Sample ID	(25-150)	(25-150)	(25-150)	(25-150)	(25-150)	(25-150)	(25-150)	(25-150		
320-63125-1	20FAI-LM-01	77	76	76	71	69	67	72	62		
320-63125-1 MS	20FAI-LM-01	95	89	90	89	87	85	81	75		
320-63125-1 MSD	20FAI-LM-01	99	95	96	95	95	87	88	79		
320-63125-2	20FAI-LM-02	87	89	89	93	92	79	84	70		
320-63125-3	20FAI-LM-03	90	85	90	91	84	84	81	74		
320-63125-4	20FAI-LM-04	96	90	92	93	91	77	87	79		
320-63125-5	20FAI-LM-05	90	84	89	93	84	70	72	64		
320-63125-6	20FAI-LM-06	101	91	93	98	92	83	86	81		
320-63125-7	20FAI-LM-07	86	78	81	86	77	72	80	67		
320-63125-8	20FAI-LM-08	100	93	96	94	95	92	96	84		
320-63125-9	20FAI-LM-09	88	89	88	91	89	85	87	76		
320-63125-10	20FAI-LM-10	89	83	82	94	86	82	77	71		
320-63125-11	20FAI-LM-88	90	89	90	91	88	86	86	87		
LCS 320-399186/2-A	Lab Control Sample	81	80	81	82	78	72	75	77		
MB 320-399186/1-A	Method Blank	105	101	101	101	99	97	98	96		
		Percent Isotope Dilution Recovery (Acceptance Limits)									
		C3PFBS	PFHxS	PFOS		d5NEFOS		,			
Lab Sample ID	Client Sample ID	(25-150)	(25-150)	(25-150)	(25-150)	(25-150)	(25-150)				
320-63125-1	20FAI-LM-01	68	72	65	73	63	69				
320-63125-1 MS	20FAI-LM-01	87	90	79	40	36	85				
320-63125-1 MSD	20FAI-LM-01	91	91	86	90	87	90				
320-63125-2	20FAI-LM-02	83	88	77	81	83	80				
320-63125-3	20FAI-LM-03	84	83	77	86	83	80				
320-63125-4	20FAI-LM-04	85	84	81	100	92	86				
320-63125-5	20FAI-LM-05	87	95	90	72	71	82				
320-63125-6	20FAI-LM-06	86	92	88	99	95	87				
320-63125-7	20FAI-LM-07	77	83	75	85	82	74				
320-63125-8	20FAI-LM-08	88	98	89	100	95	92				
320-63125-9	20FAI-LM-09	82	88	77	99	87	84				
	20FAI-LM-10	85	86	82	98	88	82				
320-63125-10											
320-63125-10 320-63125-11	20FAI-LM-88	84	87	84	89	88	84				
	20FAI-LM-88 Lab Control Sample	84 73	87 79	84 77	89 80	88 71	84 75				

Surrogate Legend

PFHxA = 13C2 PFHxA

C4PFHA = 13C4 PFHpA

PFOA = 13C4 PFOA

PFNA = 13C5 PFNA

PFDA = 13C2 PFDA

PFUnA = 13C2 PFUnA

PFDoA = 13C2 PFDoA

PFTDA = 13C2 PFTeDA

C3PFBS = 13C3 PFBS

PFHxS = 18O2 PFHxS

PFOS = 13C4 PFOS

d3NMFOS = d3-NMeFOSAA

d5NEFOS = d5-NEtFOSAA

HFPODA = 13C3 HFPO-DA

Eurofins TestAmerica, Sacramento

Page 18 of 32

Job ID: 320-63125-1

Client: Shannon & Wilson, Inc Job ID: 320-63125-1

Project/Site: Fairbanks International Airport

Method: 537 (modified) - Fluorinated Alkyl Substances

Lab Sample ID: MB 320-399186/1-A

Matrix: Solid

Analysis Batch: 399992

Client Sample ID: Method Blank
Prep Type: Total/NA
Prep Batch: 399186

	MB	MB							
Analyte	Result	Qualifier	RL	MDL	Unit	D	Prepared	Analyzed	Dil Fac
Perfluorohexanoic acid (PFHxA)	ND		0.20	0.042	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluoroheptanoic acid (PFHpA)	ND		0.20	0.029	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorooctanoic acid (PFOA)	ND		0.20	0.086	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorononanoic acid (PFNA)	ND		0.20	0.036	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorodecanoic acid (PFDA)	ND		0.20	0.022	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluoroundecanoic acid (PFUnA)	ND		0.20	0.036	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorododecanoic acid (PFDoA)	ND		0.20	0.067	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorotridecanoic acid (PFTriA)	ND		0.20	0.051	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorotetradecanoic acid (PFTeA)	ND		0.20	0.054	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorobutanesulfonic acid (PFBS)	ND		0.20	0.025	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorohexanesulfonic acid (PFHxS)	ND		0.20	0.031	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Perfluorooctanesulfonic acid (PFOS)	ND		0.50	0.20	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
N-methylperfluorooctanesulfonamidoa cetic acid (NMeFOSAA)	ND		2.0	0.39	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
N-ethylperfluorooctanesulfonamidoac etic acid (NEtFOSAA)	ND		2.0	0.37	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
9-Chlorohexadecafluoro-3-oxanonan e-1-sulfonic acid	ND		0.20	0.027	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		0.25	0.11	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
11-Chloroeicosafluoro-3-oxaundecan e-1-sulfonic acid	ND		0.20	0.022	ug/Kg		07/28/20 18:39	07/30/20 20:05	1
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		0.20	0.018	ug/Kg		07/28/20 18:39	07/30/20 20:05	1

(ADONA)						
	MB	MB				
Isotope Dilution	%Recovery	Qualifier	Limits	Prepared	Analyzed	Dil Fac
13C2 PFHxA	105		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C4 PFHpA	101		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C4 PFOA	101		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C5 PFNA	101		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C2 PFDA	99		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C2 PFUnA	97		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C2 PFDoA	98		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C2 PFTeDA	96		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C3 PFBS	94		25 - 150	07/28/20 18:39	07/30/20 20:05	1
1802 PFHxS	97		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C4 PFOS	95		25 - 150	07/28/20 18:39	07/30/20 20:05	1
d3-NMeFOSAA	101		25 - 150	07/28/20 18:39	07/30/20 20:05	1
d5-NEtFOSAA	102		25 - 150	07/28/20 18:39	07/30/20 20:05	1
13C3 HFPO-DA	96		25 - 150	07/28/20 18:39	07/30/20 20:05	1

Lab Sample ID: LCS 320-399186/2-A

Matrix: Solid

Analysis Batch: 399992

Client Sample ID: La	b Control Sample
Pr	ep Type: Total/NA
P	rep Batch: 399186
%	Rec.

-	Spike	LCS	LCS				%Rec.
Analyte	Added	Result	Qualifier	Unit	D	%Rec	Limits
Perfluorohexanoic acid (PFHxA)	2.00	2.08		ug/Kg		104	71 - 131
Perfluoroheptanoic acid (PFHpA)	2.00	2.12		ug/Kg		106	71 ₋ 131
Perfluorooctanoic acid (PFOA)	2.00	2.07		ug/Kg		103	72 - 132
Perfluorononanoic acid (PFNA)	2.00	2.17		ug/Kg		108	73 - 133

Eurofins TestAmerica, Sacramento

8/3/2020

Page 19 of 32

2

3

_

6

8

10

11

13

14

13

QC Sample Results

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Job ID: 320-63125-1

Method: 537 (modified) - Fluorinated Alkyl Substances (Continued)

Lab Sample ID: LCS 320-399186/2-A **Client Sample ID: Lab Control Sample Matrix: Solid** Prep Type: Total/NA Analysis Batch: 399992 **Prep Batch: 399186**

7 maryolo Batom 000002	Spike	LCS	LCS				%Rec.
Analyte	Added	Result	Qualifier	Unit	D	%Rec	Limits
Perfluorodecanoic acid (PFDA)	2.00	2.13		ug/Kg		107	72 - 132
Perfluoroundecanoic acid	2.00	2.24		ug/Kg		112	66 - 126
(PFUnA)							
Perfluorododecanoic acid	2.01	2.16		ug/Kg		107	71 - 131
(PFDoA)							
Perfluorotridecanoic acid	2.00	2.23		ug/Kg		111	71 - 131
(PFTriA)							
Perfluorotetradecanoic acid	2.00	2.15		ug/Kg		108	67 - 127
(PFTeA)							
Perfluorobutanesulfonic acid	1.77	1.95		ug/Kg		110	69 - 129
(PFBS)	4.00	4.00				400	00 400
Perfluorohexanesulfonic acid	1.82	1.88		ug/Kg		103	62 - 122
(PFHxS)	1.06	0.45		/1/.~		116	60 141
Perfluorooctanesulfonic acid	1.86	2.15		ug/Kg		116	68 - 141
(PFOS) 9-Chlorohexadecafluoro-3-oxan	1.86	1.96		ug/Kg		105	74 - 134
onane-1-sulfonic acid	1.00	1.50		ug/itg		100	74 - 104
Hexafluoropropylene Oxide	2.00	2.23		ug/Kg		111	53 - 158
Dimer Acid (HFPO-DA)	2.00	2.20		ug/itg			00 - 100
11-Chloroeicosafluoro-3-oxaund	1.88	2.25		ug/Kg		119	66 - 136
ecane-1-sulfonic acid				-99			
4,8-Dioxa-3H-perfluorononanoic	1.88	2.35		ug/Kg		125	79 - 139
acid (ADONA)				5 0			

acid (ADONA) LCS LCS Isotope Dilution %Recovery Qualifier Limits 13C2 PFHxA 81 25 - 150 13C4 PFHpA 80 25 - 150 13C4 PFOA 81 25 - 150 13C5 PFNA 82 25 - 150 78 13C2 PFDA 25 - 150 13C2 PFUnA 72 25 - 150 75 25 - 150 13C2 PFDoA 13C2 PFTeDA 77 25 - 150 13C3 PFBS 73 25 - 150

79

77

80

71

75

Lab Sample ID: 320-63125-1 MS

1802 PFHxS

13C4 PFOS

d3-NMeFOSAA

d5-NEtFOSAA

13C3 HFPO-DA

Matrix: Solid Analysis Batch: 399992									Prep Type: Total/NA Prep Batch: 399186
-	Sample	Sample	Spike	MS	MS				%Rec.
Analyte	Result	Qualifier	Added	Result	Qualifier	Unit	D	%Rec	Limits
Perfluorohexanoic acid (PFHxA)	ND		2.07	2.35		ug/Kg	<u> </u>	114	71 - 131
Perfluoroheptanoic acid (PFHpA)	ND		2.07	2.32		ug/Kg	₩	112	71 - 131
Perfluorooctanoic acid (PFOA)	ND		2.07	2.14		ug/Kg	₩	103	72 - 132
Perfluorononanoic acid (PFNA)	ND		2.07	2.30		ug/Kg	₽	111	73 - 133
Perfluorodecanoic acid (PFDA)	ND		2.07	2.15		ug/Kg	₩	104	72 - 132
Perfluoroundecanoic acid (PFUnA)	0.13	J	2.07	2.57		ug/Kg	₩	118	66 - 126

25 - 150

25 - 150 25 - 150

25 - 150

25 - 150

Page 20 of 32

Eurofins TestAmerica, Sacramento

Client Sample ID: 20FAI-LM-01

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Job ID: 320-63125-1

Method: 537 (modified) - Fluorinated Alkyl Substances (Continued)

Lab Sample ID: 320-63125-1 MS

Matrix: Solid

Analysis Batch: 399992

Client Sample ID: 20FAI-LM-01

Prep	i ype: I	otal/NA
Prep	Batch:	399186
0/ Daa		

7 many 510 2 at 511 50 50 2	Sample	Sample	Spike	MS	MS				%Rec.
Analyte	Result	Qualifier	Added	Result	Qualifier	Unit	D	%Rec	Limits
Perfluorododecanoic acid (PFDoA)	ND		2.08	2.23		ug/Kg	 \	107	71 - 131
Perfluorotridecanoic acid (PFTriA)	ND		2.07	2.40		ug/Kg	₩	116	71 - 131
Perfluorotetradecanoic acid (PFTeA)	ND		2.07	2.16		ug/Kg	☼	104	67 - 127
Perfluorobutanesulfonic acid (PFBS)	ND		1.83	2.03		ug/Kg	₩	111	69 - 129
Perfluorohexanesulfonic acid (PFHxS)	0.20	J	1.88	2.16		ug/Kg	☼	104	62 - 122
Perfluorooctanesulfonic acid (PFOS)	0.82	F1	1.92	4.00	F1	ug/Kg	☼	166	68 - 141
9-Chlorohexadecafluoro-3-oxan onane-1-sulfonic acid	ND		1.93	2.57		ug/Kg	₩	133	74 - 134
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		2.07	2.31		ug/Kg	₩	112	53 - 158
11-Chloroeicosafluoro-3-oxaund ecane-1-sulfonic acid	ND	F1	1.95	2.70	F1	ug/Kg	₩	138	66 - 136
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		1.95	2.42		ug/Kg	₩	124	79 - 139

	MS	MS	
Isotope Dilution	%Recovery	Qualifier	Limits
13C2 PFHxA	95		25 - 150
13C4 PFHpA	89		25 - 150
13C4 PFOA	90		25 - 150
13C5 PFNA	89		25 - 150
13C2 PFDA	87		25 - 150
13C2 PFUnA	85		25 - 150
13C2 PFDoA	81		25 - 150
13C2 PFTeDA	75		25 - 150
13C3 PFBS	87		25 - 150
1802 PFHxS	90		25 - 150
13C4 PFOS	79		25 - 150
d3-NMeFOSAA	40		25 - 150
d5-NEtFOSAA	36		25 - 150
13C3 HFPO-DA	85		25 - 150

Lab Sample ID: 320-63125-1 MSD

Matrix: Solid

Client Sample ID: 20FAI-LM-01

Prep Type: Total/NA Prep Batch: 399186

Analysis Batch: 399992									Prep Ba	tch: 39	99186
-	Sample	Sample	Spike	MSD	MSD				%Rec.		RPD
Analyte	Result	Qualifier	Added	Result	Qualifier	Unit	D	%Rec	Limits	RPD	Limit
Perfluorohexanoic acid (PFHxA)	ND		2.16	2.28		ug/Kg	₩	106	71 - 131	3	30
Perfluoroheptanoic acid (PFHpA)	ND		2.16	2.40		ug/Kg	☼	111	71 - 131	4	30
Perfluorooctanoic acid (PFOA)	ND		2.17	2.18		ug/Kg	☼	101	72 - 132	2	30
Perfluorononanoic acid (PFNA)	ND		2.17	2.39		ug/Kg		110	73 - 133	4	30
Perfluorodecanoic acid (PFDA)	ND		2.16	2.31		ug/Kg	☼	107	72 - 132	7	30
Perfluoroundecanoic acid (PFUnA)	0.13	J	2.17	2.65		ug/Kg	₽	116	66 - 126	3	30
Perfluorododecanoic acid (PFDoA)	ND		2.18	2.22		ug/Kg	☼	102	71 - 131	0	30

Eurofins TestAmerica, Sacramento

Page 21 of 32

QC Sample Results

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Job ID: 320-63125-1

Method: 537 (modified) - Fluorinated Alkyl Substances (Continued)

Lab Sample ID: 320-63125-1 MSD	Client Sample ID: 20FAI-LM-01
Matrix: Solid	Prep Type: Total/NA
Analysis Batch: 399992	Prep Batch: 399186

7, 0.0 - u.o 00000-	Camala	Commis	Cuilca	MCD	MCD				0/ Doo		חחח
	•	Sample	Spike	MSD	MSD				%Rec.		RPD
Analyte	Result	Qualifier	Added	Result	Qualifier	Unit	D	%Rec	Limits	RPD	Limit
Perfluorotridecanoic acid (PFTriA)	ND		2.16	2.18		ug/Kg	- \$	101	71 - 131	10	30
Perfluorotetradecanoic acid (PFTeA)	ND		2.17	2.18		ug/Kg	≎	101	67 - 127	1	30
Perfluorobutanesulfonic acid (PFBS)	ND		1.91	2.00		ug/Kg	≎	105	69 - 129	2	30
Perfluorohexanesulfonic acid (PFHxS)	0.20	J	1.97	2.55		ug/Kg	≎	119	62 - 122	16	30
Perfluorooctanesulfonic acid (PFOS)	0.82	F1	2.01	3.07		ug/Kg	₽	112	68 - 141	26	30
9-Chlorohexadecafluoro-3-oxan onane-1-sulfonic acid	ND		2.02	2.34		ug/Kg	₽	116	74 - 134	10	30
Hexafluoropropylene Oxide Dimer Acid (HFPO-DA)	ND		2.16	2.39		ug/Kg	₽	111	53 - 158	3	30
11-Chloroeicosafluoro-3-oxaund ecane-1-sulfonic acid	ND	F1	2.04	2.71		ug/Kg	₽	133	66 - 136	0	30
4,8-Dioxa-3H-perfluorononanoic acid (ADONA)	ND		2.04	2.47		ug/Kg	₽	121	79 - 139	2	30

acid (ADONA)			
	MSD	MSD	
Isotope Dilution	%Recovery	Qualifier	Limits
13C2 PFHxA	99		25 - 150
13C4 PFHpA	95		25 - 150
13C4 PFOA	96		25 - 150
13C5 PFNA	95		25 - 150
13C2 PFDA	95		25 - 150
13C2 PFUnA	87		25 - 150
13C2 PFDoA	88		25 - 150
13C2 PFTeDA	79		25 - 150
13C3 PFBS	91		25 - 150
1802 PFHxS	91		25 - 150
13C4 PFOS	86		25 - 150
d3-NMeFOSAA	90		25 - 150
d5-NEtFOSAA	87		25 - 150
13C3 HFPO-DA	90		25 - 150

QC Association Summary

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Job ID: 320-63125-1

LCMS

Prep Batch: 399186

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
320-63125-1	20FAI-LM-01	Total/NA	Solid	SHAKE	_
320-63125-2	20FAI-LM-02	Total/NA	Solid	SHAKE	
320-63125-3	20FAI-LM-03	Total/NA	Solid	SHAKE	
320-63125-4	20FAI-LM-04	Total/NA	Solid	SHAKE	
320-63125-5	20FAI-LM-05	Total/NA	Solid	SHAKE	
320-63125-6	20FAI-LM-06	Total/NA	Solid	SHAKE	
320-63125-7	20FAI-LM-07	Total/NA	Solid	SHAKE	
320-63125-8	20FAI-LM-08	Total/NA	Solid	SHAKE	
320-63125-9	20FAI-LM-09	Total/NA	Solid	SHAKE	
320-63125-10	20FAI-LM-10	Total/NA	Solid	SHAKE	
320-63125-11	20FAI-LM-88	Total/NA	Solid	SHAKE	
MB 320-399186/1-A	Method Blank	Total/NA	Solid	SHAKE	
LCS 320-399186/2-A	Lab Control Sample	Total/NA	Solid	SHAKE	
320-63125-1 MS	20FAI-LM-01	Total/NA	Solid	SHAKE	
320-63125-1 MSD	20FAI-LM-01	Total/NA	Solid	SHAKE	

Analysis Batch: 399992

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
320-63125-1	20FAI-LM-01	Total/NA	Solid	537 (modified)	399186
320-63125-2	20FAI-LM-02	Total/NA	Solid	537 (modified)	399186
320-63125-3	20FAI-LM-03	Total/NA	Solid	537 (modified)	399186
320-63125-4	20FAI-LM-04	Total/NA	Solid	537 (modified)	399186
320-63125-5	20FAI-LM-05	Total/NA	Solid	537 (modified)	399186
320-63125-6	20FAI-LM-06	Total/NA	Solid	537 (modified)	399186
320-63125-7	20FAI-LM-07	Total/NA	Solid	537 (modified)	399186
320-63125-8	20FAI-LM-08	Total/NA	Solid	537 (modified)	399186
320-63125-9	20FAI-LM-09	Total/NA	Solid	537 (modified)	399186
320-63125-10	20FAI-LM-10	Total/NA	Solid	537 (modified)	399186
320-63125-11	20FAI-LM-88	Total/NA	Solid	537 (modified)	399186
MB 320-399186/1-A	Method Blank	Total/NA	Solid	537 (modified)	399186
LCS 320-399186/2-A	Lab Control Sample	Total/NA	Solid	537 (modified)	399186
320-63125-1 MS	20FAI-LM-01	Total/NA	Solid	537 (modified)	399186
320-63125-1 MSD	20FAI-LM-01	Total/NA	Solid	537 (modified)	399186

General Chemistry

Analysis Batch: 399182

Lab Sample ID	Client Sample ID	Prep Type	Matrix	Method	Prep Batch
320-63125-1	20FAI-LM-01	Total/NA	Solid	D 2216	
320-63125-2	20FAI-LM-02	Total/NA	Solid	D 2216	
320-63125-3	20FAI-LM-03	Total/NA	Solid	D 2216	
320-63125-4	20FAI-LM-04	Total/NA	Solid	D 2216	
320-63125-5	20FAI-LM-05	Total/NA	Solid	D 2216	
320-63125-6	20FAI-LM-06	Total/NA	Solid	D 2216	
320-63125-7	20FAI-LM-07	Total/NA	Solid	D 2216	
320-63125-8	20FAI-LM-08	Total/NA	Solid	D 2216	
320-63125-9	20FAI-LM-09	Total/NA	Solid	D 2216	
320-63125-10	20FAI-LM-10	Total/NA	Solid	D 2216	
320-63125-11	20FAI-LM-88	Total/NA	Solid	D 2216	

Eurofins TestAmerica, Sacramento

Page 23 of 32

Lab Sample ID: 320-63125-1

Lab Sample ID: 320-63125-1

Lab Sample ID: 320-63125-2

Lab Sample ID: 320-63125-3

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-01

Date Collected: 07/23/20 15:26

Matrix: Solid Date Received: 07/28/20 11:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Client Sample ID: 20FAI-I M-01

					_	an campic in the color	
Date Collected: 07/23/20 1	5:26					Matrix: So	lid
Date Received: 07/28/20 1	1:15					Percent Solids: 89	€.3
Batch	Batch	Dil	Initial	Final	Batch	Prepared	

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	SHAKE			5.07 g	10.0 mL	399186	07/28/20 18:39	AZ	TAL SAC
Total/NA	Analysis	537 (modified)		1			399992	07/30/20 20:23	KJP	TAL SAC

Client Sample ID: 20FAI-LM-02

Date Collected: 07/23/20 15:20

Date Received: 07/28/20 11:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Lab Sample ID: 320-63125-2
Matrix: Solid
Percent Solids: 90.8

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	SHAKE			5.43 g	10.0 mL	399186	07/28/20 18:39	AZ	TAL SAC
Total/NA	Analysis	537 (modified)		1			399992	07/30/20 20:52	KJP	TAL SAC

Client Sample ID: 20FAI-LM-03

Date Collected: 07/23/20 15:45

Date Received: 07/28/20 11:15

_										
	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Client Sample ID: 20FAI-LM-03 Lab Sample ID: 320-63125-3

Date Collected: 07/23/20 15:45

Date Received: 0	7/28/20 11	:15						P	ercent So	olias: 93.2
	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	SHAKE			5.15 g	10.0 mL	399186	07/28/20 18:39	AZ	TAL SAC

Analysis 537 (modified) Client Sample ID: 20FAI-LM-04 Lab Sample ID: 320-63125-4

1

Date Collected: 07/23/20 15:54

Total/NA

Date Received: 07/28/20 11:15

_										
	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Eurofins TestAmerica, Sacramento

399992 07/30/20 21:01 KJP

Page 24 of 32

8/3/2020

Matrix: Solid

Matrix: Solid

Matrix: Solid

TAL SAC

Matrix: Solid

10

Matrix: Solid

Matrix: Solid

Matrix: Solid

Matrix: Solid

Lab Sample ID: 320-63125-4

Lab Sample ID: 320-63125-5

Lab Sample ID: 320-63125-5

Lab Sample ID: 320-63125-6

Lab Sample ID: 320-63125-7

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-04

Date Collected: 07/23/20 15:54

Date Received: 07/28/20 11:15 Percent Solids: 94.1 Batch Batch Dil Initial Batch Final **Prepared**

Method Number **Prep Type** Type Run **Factor** Amount Amount or Analyzed Analyst Lab 399186 Total/NA Prep SHAKE 5.38 g 10.0 mL 07/28/20 18:39 $\overline{\mathsf{AZ}}$ TAL SAC 07/30/20 21:10 KJP Total/NA Analysis 537 (modified) 399992 TAL SAC 1

Client Sample ID: 20FAI-LM-05

Date Collected: 07/23/20 16:22

Matrix: Solid Date Received: 07/28/20 11:15

Batch Batch Dil Initial Final **Batch** Prepared **Prep Type** Type Method Run **Factor** Amount Amount Number or Analyzed Analyst Lab Total/NA Analysis D 2216 399182 07/28/20 18:15 JCB TAL SAC

Client Sample ID: 20FAI-LM-05

Date Collected: 07/23/20 16:22

Date Received: 07/28/20 11:15 Percent Solids: 69.2 Dil Initial Batch Batch Batch Final **Prepared Prep Type** Type Method Run Factor **Amount** Amount Number or Analyzed Analyst Lab Total/NA Prep SHAKE 399186 07/28/20 18:39 $\overline{\mathsf{AZ}}$ TAL SAC 5.16 g 10.0 mL

399992 07/30/20 21:39 KJP Total/NA 537 (modified) TAL SAC Analysis 1 Lab Sample ID: 320-63125-6

Client Sample ID: 20FAI-LM-06

Date Collected: 07/23/20 16:30

Date Received: 07/28/20 11:15

Batch Batch Dil Initial Final Batch **Prepared** Method **Factor Amount** Amount Number or Analyzed **Prep Type** Type Run Analyst Lab Total/NA Analysis D 2216 399182 07/28/20 18:15 JCB TAL SAC

Client Sample ID: 20FAI-LM-06

Date Collected: 07/23/20 16:30 Matrix: Solid Date Received: 07/28/20 11:15 Percent Solids: 91.0

Dil Batch Batch Initial Final **Batch Prepared Prep Type** Method Factor Amount Number or Analyzed Type Run Amount **Analyst** Lab Total/NA SHAKE TAL SAC Prep 5.11 g 10.0 mL 399186 07/28/20 18:39 ΑZ Total/NA Analysis 399992 07/30/20 21:48 KJP TAL SAC 537 (modified) 1

Client Sample ID: 20FAI-LM-07

Date Collected: 07/23/20 16:36

Date Received: 07/28/20 11:15

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Eurofins TestAmerica, Sacramento

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-07

Lab Sample ID: 320-63125-7 Date Collected: 07/23/20 16:36

Matrix: Solid

Date Received: 07/28/20 11:15 Percent Solids: 91.0

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Туре	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	SHAKE			5.38 g	10.0 mL	399186	07/28/20 18:39	AZ	TAL SAC
Total/NA	Analysis	537 (modified)		1			399992	07/30/20 21:57	KJP	TAL SAC

Lab Sample ID: 320-63125-8 Client Sample ID: 20FAI-LM-08

Date Collected: 07/24/20 12:34 Matrix: Solid

Date Received: 07/28/20 11:15

_	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Client Sample ID: 20FAI-LM-08 Lab Sample ID: 320-63125-8

Date Collected: 07/24/20 12:34 **Matrix: Solid** Date Received: 07/28/20 11:15 Percent Solids: 92.5

Prep Type	Batch Type	Batch Method	Run	Dil Factor	Initial Amount	Final Amount	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Prep	SHAKE			5.33 g	10.0 mL	399186	07/28/20 18:39		TAL SAC
Total/NA	Analysis	537 (modified)		1			399992	07/30/20 22:07	KJP	TAL SAC

Client Sample ID: 20FAI-LM-09 Lab Sample ID: 320-63125-9

Date Collected: 07/24/20 12:45 Matrix: Solid

Date Received: 07/28/20 11:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Client Sample ID: 20FAI-LM-09 Lab Sample ID: 320-63125-9

Date Collected: 07/24/20 12:45 Matrix: Solid Date Received: 07/28/20 11:15 Percent Solids: 91.8

_	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	SHAKE			5.47 g	10.0 mL	399186	07/28/20 18:39	AZ	TAL SAC
Total/NA	Analysis	537 (modified)		1			399992	07/30/20 22:16	KJP	TAL SAC

Client Sample ID: 20FAI-LM-10 Lab Sample ID: 320-63125-10

Date Collected: 07/24/20 12:32 Date Received: 07/28/20 11:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared			
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab	
Total/NA	Analysis	D 2216					399182	07/28/20 18:15	JCB	TAL SAC	

Matrix: Solid

Lab Chronicle

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Client Sample ID: 20FAI-LM-10

Date Collected: 07/24/20 12:32

Date Received: 07/28/20 11:15

Lab Sample ID: 320-63125-10 **Matrix: Solid** Percent Solids: 76.7

Batch Batch Dil Initial Final Batch Prepared Method **Factor** Number **Prep Type** Type Run Amount **Amount** or Analyzed Analyst Lab Total/NA 399186 Prep SHAKE 5.45 g 10.0 mL 07/28/20 18:39 AZ TAL SAC Total/NA 07/30/20 22:26 KJP TAL SAC Analysis 537 (modified) 399992 1

Client Sample ID: 20FAI-LM-88

Date Collected: 07/24/20 12:24

Date Received: 07/28/20 11:15

_	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Analysis	D 2216		1			399182	07/28/20 18:15	JCB	TAL SAC

Client Sample ID: 20FAI-LM-88

Date Collected: 07/24/20 12:24

Date Received: 07/28/20 11:15

	Batch	Batch		Dil	Initial	Final	Batch	Prepared		
Prep Type	Type	Method	Run	Factor	Amount	Amount	Number	or Analyzed	Analyst	Lab
Total/NA	Prep	SHAKE			5.39 g	10.0 mL	399186	07/28/20 18:39	AZ	TAL SAC
Total/NA	Analysis	537 (modified)		1			399992	07/30/20 22:35	KJP	TAL SAC

Laboratory References:

TAL SAC = Eurofins TestAmerica, Sacramento, 880 Riverside Parkway, West Sacramento, CA 95605, TEL (916)373-5600

Job ID: 320-63125-1

Matrix: Solid

Matrix: Solid

Percent Solids: 94.4

Lab Sample ID: 320-63125-11

Lab Sample ID: 320-63125-11

Accreditation/Certification Summary

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Job ID: 320-63125-1

Laboratory: Eurofins TestAmerica, Sacramento

All accreditations/certifications held by this laboratory are listed. Not all accreditations/certifications are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Alaska (UST)	State	17-020	01-20-21
ANAB	Dept. of Defense ELAP	L2468	01-20-21
ANAB	Dept. of Energy	L2468.01	01-20-21
ANAB	ISO/IEC 17025	L2468	01-20-21
Arizona	State	AZ0708	08-11-20
Arkansas DEQ	State	19-042-0	06-17-21
California	State	2897	01-31-22
Colorado	State	CA0004	08-31-20
Connecticut	State	PH-0691	06-30-21
Florida	NELAP	E87570	07-01-21
Georgia	State	4040	01-30-21
Hawaii	State	<cert no.=""></cert>	01-29-21
Illinois	NELAP	200060	03-17-21
Kansas	NELAP	E-10375	10-31-20
Louisiana	NELAP	01944	06-30-21
Maine	State	2018009	04-14-22
Michigan	State	9947	01-31-22
Nevada	State	CA000442020-1	07-31-20
New Hampshire	NELAP	2997	04-18-21
New Jersey	NELAP	CA005	06-30-21
New York	NELAP	11666	04-01-21
Oregon	NELAP	4040	01-29-21
Pennsylvania	NELAP	68-01272	03-31-21
Texas	NELAP	T104704399-19-13	06-01-21
US Fish & Wildlife	US Federal Programs	58448	07-31-20
USDA	US Federal Programs	P330-18-00239	07-31-21
Utah	NELAP	CA000442019-01	02-28-21
Vermont	State	VT-4040	04-16-21
Virginia	NELAP	460278	03-14-21
Washington	State	C581	05-05-21
West Virginia (DW)	State	9930C	12-31-20
Wyoming	State Program	8TMS-L	01-28-19 *

A

5

Q

4.6

11

12

14

1

^{*} Accreditation/Certification renewal pending - accreditation/certification considered valid.

Method Summary

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Method	Method Description	Protocol	Laboratory
537 (modified)	Fluorinated Alkyl Substances	EPA	TAL SAC
D 2216	Percent Moisture	ASTM	TAL SAC
SHAKE	Shake Extraction with Ultrasonic Bath Extraction	SW846	TAL SAC

Protocol References:

ASTM = ASTM International

EPA = US Environmental Protection Agency

SW846 = "Test Methods For Evaluating Solid Waste, Physical/Chemical Methods", Third Edition, November 1986 And Its Updates.

Laboratory References:

TAL SAC = Eurofins TestAmerica, Sacramento, 880 Riverside Parkway, West Sacramento, CA 95605, TEL (916)373-5600

Job ID: 320-63125-1

Sample Summary

Client: Shannon & Wilson, Inc

Project/Site: Fairbanks International Airport

Lab Sample ID	Client Sample ID	Matrix	Collected	Received
320-63125-1	20FAI-LM-01	Solid	07/23/20 15:26	07/28/20 11:15
320-63125-2	20FAI-LM-02	Solid	07/23/20 15:20	07/28/20 11:15
320-63125-3	20FAI-LM-03	Solid	07/23/20 15:45	07/28/20 11:15
320-63125-4	20FAI-LM-04	Solid	07/23/20 15:54	07/28/20 11:15
320-63125-5	20FAI-LM-05	Solid	07/23/20 16:22	07/28/20 11:15
320-63125-6	20FAI-LM-06	Solid	07/23/20 16:30	07/28/20 11:15
320-63125-7	20FAI-LM-07	Solid	07/23/20 16:36	07/28/20 11:15
320-63125-8	20FAI-LM-08	Solid	07/24/20 12:34	07/28/20 11:15
320-63125-9	20FAI-LM-09	Solid	07/24/20 12:45	07/28/20 11:15
320-63125-10	20FAI-LM-10	Solid	07/24/20 12:32	07/28/20 11:15
320-63125-11	20FAI-LM-88	Solid	07/24/20 12:24	07/28/20 11:15

Job ID: 320-63125-1

3

4

5

O

8

9

10

12

13

14

15

Address:

merica

	ò	5	3
	Ē	ξ	3
	5	Ē	ì
	-	Ē	4
	ř	Ę	Š
	u	4	1-
ī			
n			
_			
-			

The second secon	Regu	Regulatory Program:	- 4	MO	NPDES	RCRA Other:			TAL-821	-82
Client Contact	Project M	Project Manager: Marcu		Nade!	Sit	Site Contact:	Date:		COC No:	
Company Name: Shannon & Wilson, Inc.	Tel/Email: MDA	MON	-		. COM La	Lab Contact:	Carrier:		of 1 cocs	
Address: 3355 Hill Road		40	Turnaround Time	Time		500			Sampler: Am J	
	CALEN	CALENDAR DAYS	WOR	WORKING DAYS		अस् अर	1		For Lab Use Only:	
	TA	TAT if different fro	from Below	Sda	7	m			Walk-in Client:	
Pax:		2	2 weeks		(N)	W (Lab Sampling:	
Site: Fairbanks International Argade		7 7	2 days		Y) əldu	LES dsw/			Job / SDG No.:	
			Sample		neS be) St				
Sample Identification	Sample	Sample Time	(C=Comp, G=Grab)	Matrix	Cont.	Perfor			Sample Specific Notes:	
SOFAI-LM-01	7/23/20	7/23/20 1526	5	S	-	×				
20FAI- LM-02	7/23/20 152D	1520	9	50	1	X				
20FAI - LM-03	7/23/20 1545	(545)	5	8	_	X				
30 FAI - LM - 04	7/23/20 1554	1554	S	So	_	×				
20FA1- LM-05	7/23/20 1622	1622	S	50	_	×				
20FAI - LIM - OL	7/23/20 163C	1630	9	S	-	×				
30FAI - LM - 07	गहमा वरहाम	1631	5	50	-	×				
20FAI - LM - 08	+14/20 (334	1334	0	05	1	X				-
JOFAI - LM - 09	24420 1345	1245	S	95	_	7				- 1
30FAI - LM1-10	7/24/20 (332	(332	5	8	_	7		320 623226		1
30FAI - LM-88	CCI 02/142/E	bee!	5	28	_	×		02700720	Section of Custody	- 1
Presentation Head: 4= I/s 2= HC! 3= H2CA: 4=HNO3: F=N=OH: 6= Other	-HOCNEY	S= Other			1					
Possible Hazard Identification: Are any samples from a listed EPA Hazardous Waste? Pleas Comments Section if the lab is to dispose of the sample.	Please List any EPA Wasi		te Codes for the sample in the	he sampl	e in the	Sample Disposal (A fee may be assessed if samples are retained longer than 1 month)	nay be assesse	d if samples are retaine	d longer than 1 month)	1
Non-Hazard Flammable Skin Irritant	Poison B	æ	Unknown	nw		Return to Client	Disposal by Lab	ab Archive for	Months	
Special Instructions/QC Requirements & Comments:									,	
Custody Seals Intact: X Yes No	Custody Seal No.:		130980	10	136981	ooler Temp.	(C): Ops,q: 3)	6 Corr'd: 4.0%	Therm ID No.: Wk - 7	П
Relinquished by: (MMMM)	Company:		Uilson	Date/Time: 458	e: 450	Received by:	M	Company:	Date/Time: 28-721, 20 11	13
Relinquished by:	Company:			Date/Time:	:01	Received by:		Company:		
Relinquished by:	Company:			Date/Time:	ie:	Received in Laboratory by:		Company:	Date/Time:	
										1

Client: Shannon & Wilson, Inc

Job Number: 320-63125-1

Login Number: 63125 List Source: Eurofins TestAmerica, Sacramento

List Number: 1

Creator: Nelson, Kym D

Answer	Comment
True	
True	1030980, 1030981
N/A	
True	
True	gel packs
True	
N/A	
True	
True	
True	
True	
N/A	
	True True N/A True True True True True True True True

Eurofins TestAmerica, Sacramento

Laboratory Data Review Checklist

Completed By:	
Dana Fjare	
Title:	
Environmental Scientist	
Date:	
8/11/20	
Consultant Firm:	
Shannon & Wilson, Inc.	
Laboratory Name:	
Eurofins TestAmerica, Sacra	amento
Laboratory Report Number:	
320-63125-1	
Laboratory Report Date:	
8/3/20	
CS Site Name:	
N/A	
ADEC File Number:	
N/A	
Hazard Identification Number:	
N/A	

3	20-63125-1
Labo	oratory Report Date:
8	2/3/20
CS S	ite Name:
N	J/A
N	Note: Any N/A or No box checked must have an explanation in the comments box.
1. <u>I</u>	<u>Laboratory</u>
	 a. Did an ADEC CS approved laboratory receive and <u>perform</u> all of the submitted sample analyses? Yes⊠ No□ N/A□ Comments:
	TestAmerica/Eurofins Laboratories West Sacramento, CA is CS certified for the analysis of perfluorooctanesulfonic acid (PFOS) and perfluorooctanoic acid (PFOA) by method 537.
	b. If the samples were transferred to another "network" laboratory or sub-contracted to an alternate laboratory, was the laboratory performing the analyses ADEC CS approved?
	$Yes \square No \square N/A \boxtimes Comments:$
	Analysis was performed by Eurofins TestAmerica laboratory in Sacramento, CA.
2. <u>C</u>	Chain of Custody (CoC)
	a. CoC information completed, signed, and dated (including released/received by)?
	$Yes \boxtimes No \square N/A \square$ Comments:
	b. Correct analyses requested?
	$Yes \boxtimes No \square N/A \square$ Comments:
3. <u>I</u>	Laboratory Sample Receipt Documentation
	a. Sample/cooler temperature documented and within range at receipt (0° to 6° C)?
	Yes \boxtimes No \square N/A \square Comments:
	b. Sample preservation acceptable – acidified waters, Methanol preserved VOC soil (GRO, BTEX, Volatile Chlorinated Solvents, etc.)?
	Yes \square No \square N/A \boxtimes Comments:
	No preservation, other than chilling, is required for PFAS analysis.

320-63125-1
Laboratory Report Date:
8/3/20
CS Site Name:
N/A
 c. Sample condition documented – broken, leaking (Methanol), zero headspace (VOC vials)? Yes⊠ No□ N/A□ Comments:
The laboratory report noted the samples were received in good condition.
d. If there were any discrepancies, were they documented? For example, incorrect sample containers/preservation, sample temperature outside of acceptable range, insufficient or missing samples, etc.?
$Yes \square No \square N/A \boxtimes Comments:$
The laboratory report did not note any sample handling discrepancies.
e. Data quality or usability affected?
Comments:
Data quality and usability were not affected; see above.
4. <u>Case Narrative</u>
a. Present and understandable?
Yes \boxtimes No \square N/A \square Comments:

320-63125-1
Laboratory Report Date:
8/3/20
CS Site Name:
N/A
b. Discrepancies, errors, or QC failures identified by the lab? Yes⊠ No□ N/A□ Comments: The matrix spike (MS) recovery in preparation batch 320-399186 and analytical batch 320-399992
was outside control limits for the analytes perfluorooctanesulfonic acid (PFOS) and 11-chloroeicosafluoro-3-oxaundecane-1-sulfonic acid. Sample matrix interference and/or non-homogeneity are suspected because the associated laboratory control sample (LCS) recovery was within acceptable limits. See Section 6.c.iii.
The result for the analyte perfluorohexanesulfonic acid (PFHxS) was manually integrated in sample 20FAI-LM-05. The qualitative identification of the analyte has some degree of uncertainty and the result was flagged 'I' by the laboratory.
The laboratory applied an 'I' qualifier to the perfluorohexanesulfonic acid (PFHxS) result for sample 20FAI-LM-05 to indicate the transition mass ratio was outside established ratio limits.
The samples 20FAI-LM-01, 20FAI-LM-02, 20FAI-LM-03, 20FAI-LM-04, 20FAI-LM-05, MS 320-63125-A-1, and MSD 320-63125-A-1 were slightly yellow after final volume.
c. Were all corrective actions documented?
Yes \square No \square N/A \boxtimes Comments: The laboratory did not specify any corrective actions.
d. What is the effect on data quality/usability according to the case narrative?
Comments:
The laboratory did not specify an effect on data quality or usability. However, we have flagged the PFHxS results for sample 20FAI-LM-05 as estimated ("J-flagged") due to the I flag reported by the laboratory.
5. <u>Samples Results</u>
a. Correct analyses performed/reported as requested on COC?
$Yes \boxtimes No \square N/A \square$ Comments:

320	0-63125-1
Labora	atory Report Date:
8/3	3/20
CS Sit	e Name:
N/	A
	b. All applicable holding times met?
ı	Yes⊠ No□ N/A□ Comments:
	c. All soils reported on a dry weight basis?
ſ	$Yes \boxtimes No \square N/A \square$ Comments:
	d. Are the reported LOQs less than the Cleanup Level or the minimum required detection level for the project?
ſ	$Yes \boxtimes No \square N/A \square$ Comments:
	e. Data quality or usability affected?
	Data quality and usability were not affected; see above.
6. <u>QC</u>	<u>C Samples</u>
	a. Method Blank
	i. One method blank reported per matrix, analysis and 20 samples?
	Yes⊠ No□ N/A□ Comments:
	ii. All method blank results less than limit of quantitation (LOQ) or project specified objectives?
ſ	$Yes \boxtimes No \square N/A \square$ Comments:
	iii. If above LOQ or project specified objectives, what samples are affected? Comments:
	N/A: project analytes were not detected in the method blank

320-63125-1	
Laboratory Report Date:	
8/3/20	
CS Site Name:	
N/A	
iv. Do the affected sample	e(s) have data flags? If so, are the data flags clearly defined?
Yes□ No□ N/A⊠	Comments:
Project analytes were not detec	eted in the method blank.
v. Data quality or usabili	ty affected? Comments:
Data quality and usability are r	
b. Laboratory Control Sample	e/Duplicate (LCS/LCSD)
i. Organics – One LCS/I	LCSD reported per matrix, analysis and 20 samples? (LCS/LCSD ods, LCS required per SW846)
Yes□ No⊠ N/A□	Comments:
An LCS was reported for soil a	analysis.
ii. Metals/Inorganics – or samples?	ne LCS and one sample duplicate reported per matrix, analysis and 20
$Yes \square No \square N/A \boxtimes$	Comments:
Metals/Inorganic analyses were	e not requested with this work order.
project specified object	t recoveries (%R) reported and within method or laboratory limits and trives, if applicable? (AK Petroleum methods: AK101 60%-120%, K103 60%-120%; all other analyses see the laboratory QC pages)
Yes⊠ No□ N/A□	Comments:
limits and project spec	e percent differences (RPD) reported and less than method or laboratory effectives, if applicable? RPD reported from LCS/LCSD, and or ate. (AK Petroleum methods 20%; all other analyses see the laboratory
Yes□ No□ N/A⊠	Comments:
N/A; see above.	
v. If %R or RPD is outside	de of acceptable limits, what samples are affected? Comments:
N/A; LCS accuracy was within	

320-63125-1
Laboratory Report Date:
8/3/20
CS Site Name:
N/A
vi. Do the affected sample(s) have data flags? If so, are the data flags clearly defined?
Yes \square No \square N/A \boxtimes Comments:
N/A; LCS accuracy was within laboratory control limits.
vii. Data quality or usability affected? (Use comment box to explain.) Comments:
Data quality and usability were not affected; see above.
 c. Matrix Spike/Matrix Spike Duplicate (MS/MSD) Note: Leave blank if not required for project i. Organics – One MS/MSD reported per matrix, analysis and 20 samples? Yes□ No⊠ N/A□ Comments:
An MS/MSD was reported for soil analysis.
ii. Metals/Inorganics – one MS and one MSD reported per matrix, analysis and 20 samples?Yes□ No□ N/A⊠ Comments:
Metals/inorganics analysis was not requested with this work order.
 iii. Accuracy – All percent recoveries (%R) reported and within method or laboratory limits and project specified objectives, if applicable? Yes□ No⊠ N/A□ Comments:
The matrix spike (MS) recovery for preparation batch 320-399186 and analytical batch 320-399992 was outside control limits for the analytes PFOS and 11-chloroeicosafluoro-3-oxaundecane-1-sulfonic acid.
 iv. Precision – All relative percent differences (RPD) reported and less than method or laboratory limits and project specified objectives, if applicable? RPD reported from MS/MSD, and or sample/sample duplicate. Yes⊠ No□ N/A□ Comments:
TOUS THE COMMONS.
v. If %R or RPD is outside of acceptable limits, what samples are affected? Comments:

The original sample for the MS is project sample 20FAI-LM-01.

320-63125-1
Laboratory Report Date:
8/3/20
CS Site Name:
N/A
vi. Do the affected sample(s) have data flags? If so, are the data flags clearly defined?
Yes \boxtimes No \square N/A \square Comments:
The analyte 11-chloroeicosafluoro-3-oxaundecane-1-sulfonic acid was not detected in <i>20FAI-LM</i> -01; therefore, the result does not require qualification for the high MS recovery.
The detected result for PFOS in 20FAI-LM-01 is considered to be affected by the high MS recovery for that analyte. The PFOS result is flagged 'JH' to identify the estimated result, biased high.
vii. Data quality or usability affected? (Use comment box to explain.) Comments:
Yes; see above.
d. Surrogates – Organics Only or Isotope Dilution Analytes (IDA) – Isotope Dilution Methods Only
 i. Are surrogate/IDA recoveries reported for organic analyses – field, QC and laboratory samples?
Yes \boxtimes No \square N/A \square Comments:
ii. Accuracy – All percent recoveries (%R) reported and within method or laboratory limits and project specified objectives, if applicable? (AK Petroleum methods 50-150 %R for field samples and 60-120 %R for QC samples; all other analyses see the laboratory report pages)
Yes⊠ No□ N/A□ Comments:
iii. Do the sample results with failed surrogate/IDA recoveries have data flags? If so, are the data flags clearly defined?
Yes \square No \square N/A \boxtimes Comments:
IDA recovery was within laboratory control limits.
iv. Data quality or usability affected? Comments:
Data quality and usability are not affected; see above.

320-63125-1
Laboratory Report Date:
8/3/20
CS Site Name:
N/A
e. Trip Blanksi. One trip blank reported per matrix, analysis and for each cooler containing volatile samples?
(If not, enter explanation below.)
Yes□ No□ N/A⊠ Comments: Volatile analyses were not requested, so a trip blank was not required.
ii. Is the cooler used to transport the trip blank and VOA samples clearly indicated on the COC? (If not, a comment explaining why must be entered below)
$Yes \square No \square N/A \boxtimes Comments:$
A trip blank was not submitted with this work order.
iii. All results less than LOQ and project specified objectives?
Yes□ No□ N/A⊠ Comments:
A trip blank was not submitted with this work order.
iv. If above LOQ or project specified objectives, what samples are affected? Comments:
N/A; a trip blank was not submitted with this work order.
v. Data quality or usability affected? Comments:
Data quality and usability are not affected; see above.
f. Field Duplicate i. One field duplicate submitted per matrix, analysis and 10 project samples?
Yes⊠ No□ N/A□ Comments:
ii. Submitted blind to lab?
Yes \boxtimes No \square N/A \square Comments: Field duplicate sample pairs $20FAI$ - LM - 08 and $20FAI$ - LM - 88 were submitted with this work order.

320-63125-1
Laboratory Report Date:
8/3/20
CS Site Name:
N/A
iii. Precision – All relative percent differences (RPD) less than specified project objectives? (Recommended: 30% water, 50% soil)
Yes \boxtimes No \square N/A \square Comments:
The RPD values were within the project objective of 50% for soil for the detected analyte PFHxS. Other analytes were not detected in the duplicate pair, so an RPD could not be calculated.
iv. Data quality or usability affected? (Use the comment box to explain why or why not.) Comments:
Data quality and/or usability were not affected. See above.
g. Decontamination or Equipment Blank (If not applicable, a comment stating why must be entered below)?
Yes□ No□ N/A⊠ Comments:
Reusable equipment was not used for this project, so an equipment blank was not submitted with this work order.
i. All results less than LOQ and project specified objectives?
Yes \square No \square N/A \boxtimes Comments:
N/A; an equipment blank was not submitted with this work order.
ii. If above LOQ or project specified objectives, what samples are affected? Comments:
N/A; an equipment blank was not submitted with this work order.
iii. Data quality or usability affected? Comments:
Data quality and usability were not affected; see above.

	320-63125-1				
La	boratory Report Date:				
	8/3/20				
CS Site Name:					
	N/A				
7.	Other Data Flags/Qualifiers (ACOE, AFCEE, Lab Specific, etc.)				
	a. Defined and appropriate?				
	Yes \square No \square N/A \boxtimes Comments:				

The PFHxS result for sample *20FAI-LM-05* is considered estimated and flagged 'J' because the transition mass ratio did not meet laboratory acceptance criteria. The laboratory analyst used professional judgement to identify the analyte but there is some degree of uncertainty in this determination.

Important Information About Your Geotechnical/Environmental Report

CONSULTING SERVICES ARE PERFORMED FOR SPECIFIC PURPOSES AND FOR SPECIFIC CLIENTS.

Consultants prepare reports to meet the specific needs of specific individuals. A report prepared for a civil engineer may not be adequate for a construction contractor or even another civil engineer. Unless indicated otherwise, your consultant prepared your report expressly for you and expressly for the purposes you indicated. No one other than you should apply this report for its intended purpose without first conferring with the consultant. No party should apply this report for any purpose other than that originally contemplated without first conferring with the consultant.

THE CONSULTANT'S REPORT IS BASED ON PROJECT-SPECIFIC FACTORS.

A geotechnical/environmental report is based on a subsurface exploration plan designed to consider a unique set of project-specific factors. Depending on the project, these may include the general nature of the structure and property involved; its size and configuration; its historical use and practice; the location of the structure on the site and its orientation; other improvements such as access roads, parking lots, and underground utilities; and the additional risk created by scope-of-service limitations imposed by the client. To help avoid costly problems, ask the consultant to evaluate how any factors that change subsequent to the date of the report may affect the recommendations. Unless your consultant indicates otherwise, your report should not be used (1) when the nature of the proposed project is changed (for example, if an office building will be erected instead of a parking garage, or if a refrigerated warehouse will be built instead of an unrefrigerated one, or chemicals are discovered on or near the site); (2) when the size, elevation, or configuration of the proposed project is altered; (3) when the location or orientation of the proposed project is modified; (4) when there is a change of ownership; or (5) for application to an adjacent site. Consultants cannot accept responsibility for problems that may occur if they are not consulted after factors that were considered in the development of the report have changed.

SUBSURFACE CONDITIONS CAN CHANGE.

Subsurface conditions may be affected as a result of natural processes or human activity. Because a geotechnical/environmental report is based on conditions that existed at the time of subsurface exploration, construction decisions should not be based on a report whose adequacy may have been affected by time. Ask the consultant to advise if additional tests are desirable before construction starts; for example, groundwater conditions commonly vary seasonally.

Construction operations at or adjacent to the site and natural events such as floods, earthquakes, or groundwater fluctuations may also affect subsurface conditions and, thus, the continuing adequacy of a geotechnical/environmental report. The consultant should be kept apprised of any such events and should be consulted to determine if additional tests are necessary.

MOST RECOMMENDATIONS ARE PROFESSIONAL JUDGMENTS.

Site exploration and testing identifies actual surface and subsurface conditions only at those points where samples are taken. The data were extrapolated by your consultant, who then applied judgment to render an opinion about overall subsurface conditions. The actual interface between materials may be far more gradual or abrupt than your report indicates. Actual conditions in areas not sampled may differ from those predicted in your report. While nothing can be done to prevent such situations, you and your consultant can work together to help reduce their impacts. Retaining

your consultant to observe subsurface construction operations can be particularly beneficial in this respect.

A REPORT'S CONCLUSIONS ARE PRELIMINARY.

The conclusions contained in your consultant's report are preliminary, because they must be based on the assumption that conditions revealed through selective exploratory sampling are indicative of actual conditions throughout a site. Actual subsurface conditions can be discerned only during earthwork; therefore, you should retain your consultant to observe actual conditions and to provide conclusions. Only the consultant who prepared the report is fully familiar with the background information needed to determine whether or not the report's recommendations based on those conclusions are valid and whether or not the contractor is abiding by applicable recommendations. The consultant who developed your report cannot assume responsibility or liability for the adequacy of the report's recommendations if another party is retained to observe construction.

THE CONSULTANT'S REPORT IS SUBJECT TO MISINTERPRETATION.

Costly problems can occur when other design professionals develop their plans based on misinterpretation of a geotechnical/environmental report. To help avoid these problems, the consultant should be retained to work with other project design professionals to explain relevant geotechnical, geological, hydrogeological, and environmental findings, and to review the adequacy of their plans and specifications relative to these issues.

BORING LOGS AND/OR MONITORING WELL DATA SHOULD NOT BE SEPARATED FROM THE REPORT.

Final boring logs developed by the consultant are based upon interpretation of field logs (assembled by site personnel), field test results, and laboratory and/or office evaluation of field samples and data. Only final boring logs and data are customarily included in geotechnical/environmental reports. These final logs should not, under any circumstances, be redrawn for inclusion in architectural or other design drawings, because drafters may commit errors or omissions in the transfer process.

To reduce the likelihood of boring log or monitoring well misinterpretation, contractors should be given ready access to the complete geotechnical engineering/environmental report prepared or authorized for their use. If access is provided only to the report prepared for you, you should advise contractors of the report's limitations, assuming that a contractor was not one of the specific persons for whom the report was prepared, and that developing construction cost estimates was not one of the specific purposes for which it was prepared. While a contractor may gain important knowledge from a report prepared for another party, the contractor should discuss the report with your consultant and perform the additional or alternative work believed necessary to obtain the data specifically appropriate for construction cost estimating purposes. Some clients hold the mistaken impression that simply disclaiming responsibility for the accuracy of subsurface information always insulates them from attendant liability. Providing the best available information to contractors helps prevent costly construction problems and the adversarial attitudes that aggravate them to a disproportionate scale.

READ RESPONSIBILITY CLAUSES CLOSELY.

Because geotechnical/environmental engineering is based extensively on judgment and opinion, it is far less exact than other design disciplines. This situation has resulted in wholly unwarranted claims

being lodged against consultants. To help prevent this problem, consultants have developed a number of clauses for use in their contracts, reports, and other documents. These responsibility clauses are not exculpatory clauses designed to transfer the consultant's liabilities to other parties; rather, they are definitive clauses that identify where the consultant's responsibilities begin and end. Their use helps all parties involved recognize their individual responsibilities and take appropriate action. Some of these definitive clauses are likely to appear in your report, and you are encouraged to read them closely. Your consultant will be pleased to give full and frank answers to your questions.

The preceding paragraphs are based on information provided by the ASFE/Association of Engineering Firms Practicing in the Geosciences, Silver Spring, Maryland